

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

LONPAC INSURANCE BHD Ref: CS3/LPC20009042/Gtf3e2 300 BEACH ROAD #17-04/07 THE CONCOURSE Date: 03-09-2020

SINGAPORE 199555


			Code: LPC2				
1. Policy Particulars :- (THIRD PARTY CLAIM)							
	Insured Veh.	GBE 4967J	Veh. Inspected	SLJ 1417E			
	Policy No.		Coverage (\$)	0.00			
	Claim No.	20/20/20/VC05/023580	Excess (\$)	0.00			
	Assign From	KENNY LIM	Assign Date	26/08/2020			
2.	. Vehicle Particulars & Condition						
	Make & Model	HONDA SHUTTLE 1.5G	c.c	1496			
	Engine No.	HIDDEN	Year of Reg.	2016			
	Chassis No.	GK81007587	Colour	BLUE			
	Odometer	80502 KM	Steering	IN ORDER			
	Brakes	IN ORDER	Modification	SPORTS RIM			
	General	GOOD					
3. Conditions of Tyres							
		Size	Make	Balance			
	R/H Front Tyre	195/60 R15	FIRESTONE	6 mm			
	L/H Front Tyre	195/60 R15	FIRESTONE	6 mm			
	R/H Rear Tyre	195/60 R15	FIRESTONE	6 mm			

4. Description of Damages

195/60 R15

L/H Rear Tyre

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT & REAR PORTION.



6 mm

Page No.:1 of 1

5.	General Information					
	Accident Date	24/08/2020	Inspect Date / Time	27/08/2020 (11:53 AM)		
	Survey held at	CHIP SOON AUTO SUPPLY CO.				
		BLK 9002 #01-74 TAMPINES STREET 93 TAMPINES INDUSTRIAL PARK A SINGAPORE 528836				

FIRESTONE

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
- THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

Report Ref No. CS3/LPC20009042/Gtf3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

Automotive Assessor

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.