

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
INDIA INTERNATIONAL INSURANCE PL Ref : CS3/III20004541/Eyf3e2-1					
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date: 30-09-2020 Code: III2			
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 8711T	Veh. Inspected	FBA 1854S	
	Policy No.	MCOM0015	Coverage (\$)	0.00	
	Claim No.	MCT20030384	Excess (\$)	0.00	
	Assign From	CARINE KEK	Assign Date	26/08/2020	
2. Vehicle Particulars & Condition					
	Make & Model	HONDA CB400	c.c	399	
	Engine No.	HIDDEN	Year of Reg.	2006	
	Chassis No.	NC391102296	Colour	BLACK	
	Odometer	130516	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	120/60 R17	METZELER	4 mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre	160/60 R17	METZELER	4 mm	
	L/H Rear Tyre			mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	22/03/2020	Inspection Date	26/03/2020	
	Survey held at	JD MOTORSPORTS PTE LTD			
		25 KAKI BUKIT ROAD 4 #06-38 SYNERGY @ KB SINGAPORE 417800			
5a.	Remarks				
		A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. 3)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair				
	ESTIMATED NORI	MAL PERIOD FOR REPAIR:	4 Working Days		