

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

26/08/2020

Blk 1 Kaki Bukit Ave 6
01-43
Singapore 417883

TP A16
kheachan.

Accident date: 25/08/2020

Estimated repair cost for vehicle no: SJQ8249P TOYOTA VIOS E 1.5 A '09

CHASSIS: MR053HY9305113202

S/n	Qty	Items	U/price	Amount	
1	1	Rear Boot Lid <i>distorted</i>		\$590.10	✓
2	2	Rear Boot Lid Hinge <i>best</i>	\$123.05	\$246.10	✓
3	1	Rear Boot Lid Emblem Logo <i>new</i>		\$42.50	✓
4	1	Rear Boot Lid Vios Logo <i>new</i>		\$43.55	✓
5	1	Rear Boot Lid Centre Moulding <i>could</i>		\$172.85	✓
6	1	Rear Boot Lid Number Plate <i>could</i>		\$50.00	✓
7	2	Rear Boot Lid Number Plate Lamp <i>new</i>	\$83.50	\$167.00	x
8	1	Rear Boot Lid Inner Lock <i>damaged</i>		\$182.25	✓
9	1	Rear Boot Lid Inner Rubber <i>fit</i>		\$161.40	✓
10	2	Rear Tail Lamp <i>could</i>	\$281.45	\$562.90	✓
11	4	Rear Tail Lamp Clip <i>new</i>	\$8.00	\$32.00	✓
12	2	Rear Tail Lamp Lower Bracket <i>could</i>	\$121.25	<u>\$242.50</u>	90. ✓
13	1	Rear Bumper <i>distorted</i>		\$391.40	✓
14	8	Rear Bumper Clip <i>new</i>	\$6.50	\$52.00	30
15	2	Rear Bumper Side Retainer <i>new</i>	\$121.25	\$242.50	✓
16	1	Rear Bumper Reverse Sensor (Special Nett) <i>damaged</i>		\$350.00	200 (50)
17	2	Rear Bumper Side Reflector <i>could</i>	\$182.25	\$364.50	✓
18	2	Rear Fender <i>LH Buckled</i>	\$981.75	\$1,963.50	84.75
19	2	Rear Fender Inner Trim Board <i>3 new</i>	\$314.40	\$628.80	+
20	16	Rear Fender Inner Trim Board Clip <i>3 new</i>	\$6.50	\$104.00	+
21	2	Rear Fender Mudflap <i>torn</i>	\$58.20	\$116.40	✓
22	1	Rear Fender Air Duct <i>could</i>		\$110.80	✓
23	1	Rear End Panel <i>distorted</i>		\$781.50	✓
24	1	Rear End Panel Top Garnish <i>could</i>		\$286.50	✓
25	2	Rear End Panel Bracket <i>best</i>	\$125.60	\$251.20	✓
26	1	Rear Spare Tyre Panel <i>Regis</i>		\$681.75	+
27	1	Rear Spare Tyre Panel Top Cover <i>torn</i>		\$289.95	✓

28	2	Rear Spare Tyre Panel Top Sponge	Debond	\$240.10	\$480.20	✓
29	1	Rear Spare Tyre Panel & End Panel Sealant	Neu		\$450.00	+
30	1	Rear Exhaust			\$781.45	+
31	2	Rear Exhaust Mounting	2	\$28.50	\$57.00	+
32	1	Rear Center Exhaust	1		\$787.20	+
33	1	Rear Windscreen Moulding	Neu		\$132.10	✓
34	1	Rear Exhaust	2		\$736.00	+
35	2	Rear Exhaust Mounting	2	\$64.00	\$128.00	+
36	1	Rear Center Exhaust	1		\$1,840.00	+

37 1 Rear Bumper Lower Spoiler Distorted 800 400(SN)
 663245 S.N. 600
 497433
 Subtotal :- \$14,499.90

Labour charges

To remove & refit cushion	\$280.00	80
To remove & refit reverse sensor	\$100.00	50
To remove & refit reverse camera	\$180.00	+
To remove & refit rear & centre exhaust	\$380.00	80
To check wiring	\$100.00	30
Towing fee	\$100.00	+
Tuff kote	\$150.00	60
Panel Beating	\$1,600.00	1200
Spray painting	\$1,600.00	1300
	Subtotal :-	\$4,490.00
	Total:-	\$18,989.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

total: 837433

4/s: 6.7K

6.7K