



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: MS FIRST CAPITAL INSURANCE LIMITED 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877	Document No.	: SQT20002700	Page	1
Registration No	: SLK2027K	Date	: 26. Aug 2020		
Chassis No	: MRHFC5650GT000702	Customer No.	: WZF002		
Model	: CIVIC 1.6 VTI YM2016	Svc Advisor	: ANIKKA LAI SWEE KAM		
Owner's Name	: GOH CHIN CHAI	Engine No	: R16B21600952		
Ins Policy No.	:	Date Time	: 26. Aug 2020 10:57:25 AM		
Date of Accident	: 26/8/2020	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: GOH CHIN CHAI OWNER INSURER: TOKIO MARINE ACC DATE: 26/08/2020 SURVEYED BY: DATE: REF NO: TP INSURER: FIRST CAPITAL TP VEH: SHC1456B						
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:						
68500-TEA-N00ZZ	LID COMP TRUNK / PD	1	531.20	25	398.40	27.89	426.29
68610-TEA-T10ZZ	HINGE COMPR.TRUNK / BT	1	48.90	25	36.67	2.57	39.24
68660-TEA-T10ZZ	HINGE COMPL.TRUNK / PT	1	48.90	25	36.67	2.57	39.24
74865-TEA-T01	WEATHERSTRIPTRUNK LID / CR4	1	70.00	25	52.50	3.68	56.18
74851-TEA-003	LOCK ASSYTRUNK / Jam	1	81.20	25	60.90	4.26	65.16
74862-TEA-003	STRIKERTRUNK LID / 2X Svc	1	7.80	25	5.85	0.41	6.26
74890-TEA-T11ZB	GARNISH ASSYRR.LICENSE / CRA	1	109.90	25	82.42	5.77	88.19
75701-TBA-A10	EMBLEM,H-MARK / NEC	1	13.30	25	9.97	0.70	10.67
90301-ST0-003	NUTPUSH 3MM / NEC	2	2.10	25	3.15	0.22	3.37
34100-TEA-T11	LIGHT ASSYLICENSE / MIS.	1	68.70	25	51.52	3.61	55.13
84620-TEA-Z11ZA	LINING ASSYTRUNK LID / CR4	1	36.00	25	27.00	1.89	28.89
75722-TBA-A00	EMBLEM SETRR. / NEC	1	12.90	25	9.67	0.68	10.35
75725-TEA-T01	EMBLEMRR. / NEC	1	12.00	25	9.00	0.63	9.63
39530-TBA-A01	CAMERA ASSYRR.VIEW / ? X Svc	1	344.70	25	258.52	18.10	276.62
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER / CR4	1	617.20	25	462.90	32.40	495.30
71593-TEA-T01	SPACERR.RR.BUMPER SIDE / NEC	1	11.50	25	8.62	0.60	9.22
71598-TEA-T01	SPACERL.RR.BUMPER SIDE / NEC	1	11.50	25	8.62	0.60	9.22

Printed on 27/8/2020 12:16:51 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
Registration No : SLK2027K
Chassis No : MRHFC5650GT000702
Model : CIVIC 1.6 VTI YM2016
Owner's Name : GOH CHIN CHAI
Ins Policy No. :
Date of Accident : 26/8/2020

Document No. : SQT20002700
Date : 26. Aug 2020
Customer No. : WZF002
Svc Advisor : ANIKKA LAI SWEE KAM
Engine No : R16B21600952
Date | Time : 26. Aug 2020 10:57:25 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
91505-TM8-003	CLIP,BUMPER <i>NEC</i>	22	2.30	25	37.95	2.66	40.61
71505-TBA-A00	BRACKETR.RR.BUMPER SIDE <i>BR</i>	1	2.50	25	1.87	0.13	2.00
71555-TBA-A00	BRACKETL.RR.BUMPER SIDE <i>BR</i>	1	2.50	25	1.87	0.13	2.00
33505-TEA-T01	REFLECTOR ASSYR.RR. <i>AS</i>	1	7.90	25	5.92	0.41	6.33
33555-TEA-T01	REFLECTOR ASSYL.RR. <i>AS</i>	1	7.90	25	5.92	0.41	6.33
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER <i>SCR</i>	1	39.80	25	29.85	2.09	31.94
71503-TEA-T00	GARNISH,R.RR.BUMPER SIDE <i>SCR</i>	1	8.50	25	6.37	0.45	6.82
71508-TEA-T00	GARNISH,L.RR.BUMPER SIDE <i>SCR</i>	1	8.50	25	6.37	0.45	6.82
71504-TBA-A00	COVERR.FINISHER <i>X</i>	1	12.00	25	9.00	0.63	9.63
71509-TBA-A00	COVERL.FINISHER <i>X</i>	1	12.00	25	9.00	0.63	9.63
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER <i>BT</i>	1	180.00	25	135.00	9.45	144.45
65550-TEA-T00ZZ	PAN COMPSPARE TIRE <i>CRU</i>	1	236.70	25	177.52	12.43	189.95
66100-TEC-307ZZ	PANEL SETRR. <i>pb</i>	1	265.70	25	199.27	13.95	213.22
84640-TEA-Z01ZA	LINING ASSYRR.PANEL <i>CRU</i>	1	50.30	25	37.72	2.64	40.36
84521-TEA-Q01ZA	LID ASSYSPARE TIRE <i>CRU</i>	1	65.70	25	49.27	3.45	52.72
84542-TET-H00	BOX COMPTOOL <i>X</i>	1	41.50	25	31.12	2.18	33.30
34271-S5A-A01	LAMP UNIT <i>X</i>	1	90.50	25	67.87	4.75	72.62
04636-TEA-T00ZZ	PANEL SETR.RR.OUTSIDE <i>Fender CRU</i>	1	777.50	25	583.12	40.82	623.94
04646-TEA-T00ZZ	PANEL SETL.RR.OUTSIDE <i>CRU</i>	1	777.50	25	583.12	40.82	623.94
74483-TEA-T00	PACKINGFUEL ADAPTER <i>X</i>	1	3.50	25	2.62	0.18	2.80
63910-TEA-T00ZZ	LID COMPFUEL FILLER <i>X</i>	1	116.60	25	87.45	6.12	93.57
75450-TEA-T02	OUTLET ASSY,RR.AIR <i>def.</i>	1	8.80	25	6.60	0.46	7.06
66154-TBA-A00ZZ	STIFFENERL.RR.PANEL SIDE <i>DD</i>	1	29.20	25	21.90	1.53	23.43
66501-TEA-T00ZZ	STIFFENERRR.SHELF FR. <i>CRU</i>	1	46.30	25	34.72	2.43	37.15
66500-TET-H00ZZ	SHELF COMPRR.PARCEL <i>DD</i>	1	267.10	25	200.32	14.02	214.34
65660-TEA-T00ZZ	FRAME COMP,L.RR.FLOOR <i>?</i>	1	703.10	25	527.32	36.91	564.23
64701-TEA-T00ZZ	PANELL.RR.INSIDE <i>?</i>	1	231.50	25	173.62	12.15	185.77
64710-TEA-315ZZ	STIFFENER COMP.,L.RR.SHOCK ABSORBER <i>?</i>	1	142.00	25	106.50	7.46	113.96
64730-TEC-U00ZZ	WHEELHOUSE COMPL.RR <i>?</i>	1	280.00	25	210.00	14.70	224.70

Printed on 27/8/2020 12:16:51 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
 36 ROBINSON ROAD
 #16-01 CITY HOUSE
 SINGAPORE 068877

Registration No : SLK2027K

Chassis No : MRHFC5650GT000702

Model : CIVIC 1.6 VTI YM2016

Owner's Name : GOH CHIN CHAI

Ins Policy No. :

Date of Accident : 26/8/2020

Document No. : SQT20002700 Page 3

Date : 26. Aug 2020

Customer No. : WZF002

Svc Advisor : ANIKKA LAI SWEE KAM

Engine No : R16B21600952

Date | Time : 26. Aug 2020 10:57:25 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
33500-TEA-T01	TAILLIGHT ASSYR. ✓ CRA	1	285.50	25	214.12	14.99	229.11
33550-TEA-T01	TAILLIGHT ASSYL. ✓ CRA	1	307.40	25	230.55	16.14	246.69
34150-TEX-Y01	LIGHT ASSYR.LID ✓ SCR	1	133.60	25	100.20	7.01	107.21
34155-TEX-Y01	LIGHT ASSYL.LID ✓ CRA	1	133.60	25	100.20	7.01	107.21
38387-TZ5-A01	ANTENNA ASSYL.F. ✓ CRA	1	60.80	25	45.60	3.19	48.79
74940-SZW-003	BUZZER ASSYSMART ? ✓ CRA	1	62.90	25	47.17	3.30	50.47
91534-SWA-003	CLIPCOUPLER . ? ✓ NEC	1	5.20	25	3.90	0.27	4.17
73227-TEA-003	RUBBER CWINDSHIELD DAM	1	18.80	25	14.10	0.99	15.09
73525-SYY-000	RUBBERRR QTR W/SHIELD	3	9.90	25	22.27	1.56	23.83
91501-S70-003	FASTENER BW/SHIELD	2	5.30	25	7.95	0.56	8.51
91536-SS0-J01	FASTENER AW/SHIELD	2	3.80	25	5.70	0.40	6.10
91568-TF0-003	CLIP,WINDSHIELD UPPER } ✓ NEC.	2	3.20	25	4.80	0.34	5.14
73125-SR3-000	RUBBER, W/SHIELD	1	12.90	25	9.67	0.68	10.35
73126-SR3-000	RUBBER, W/SHIELD	1	14.70	25	11.02	0.77	11.79
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
73550-TEA-T01	GLASS ASSYL.QUARTER WINDSHIEL ✓ NEC	1	149.20	25	111.90	7.83	119.73
73500-TEA-T01	GLASS ASSYR.QUARTER WINDSHIEL ✓ NEC	1	149.20	25	111.90	7.83	119.73
Sum Item					6032.61	422.29	6,454.90

BO-R-COOL-RRQ	SUPPLY & INSTALL SOLAR FILM ON REAR QTR GLASS.	1 ✓ NEC	250.00	80	250.00	17.50	267.50
BO-R-COOL-RRQ	SUPPLY & INSTALL SOLAR FILM ON REAR QTR GLASS.	1 ✓ NEC	250.00	80	250.00	17.50	267.50
Sum Ext. Service					500.00	35.00	535.00

BOSUN	SUNDRIES	1 ✓ NEC	100.00	50	100.00	7.00	107.00
BG02R	REPLACE RR. WINDSCREEN.(N)	1 ✓ NEC	650.00		650.00	45.50	695.50
BG51R	REPLACE RR. L QTR GLASS.(N)	1 ✓ NEC	250.00		250.00	17.50	267.50
BG52R	REPLACE RR. R QTR GLASS.(N)	1 ✓ NEC	250.00		250.00	17.50	267.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1 ✓ NEC	150.00	120	150.00	10.50	160.50
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1 ✓ NEC	150.00	120	150.00	10.50	160.50

Printed on 27/8/2020 12:16:51 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

1dy 650

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATIONGST Reg No. WZF002
Company Reg No. S80FC1380G

Customer	: MS FIRST CAPITAL INSURANCE LIMITED	Document No.	: SOT20002700	Page	4
	36 ROBINSON ROAD	Date	: 26. Aug 2020		
	#16-01 CITY HOUSE	Customer No.	: WZF002		
	SINGAPORE 068877	Svc Advisor	: ANIKKA LAI SWEE KAM		
Registration No	: SLK2027K	Engine No	: R16B21600952		
Chassis No	: MRHFC5650GT000702	Date Time	: 26. Aug 2020 10:57:25 AM		
Model	: CIVIC 1.6 VTI YM2016	Surveyor Name	:		
Owner's Name	: GOH CHIN CHAI	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 26/8/2020				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	800.00	85%	800.00	56.00	856.00
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	450.00	35%	450.00	31.50	481.50
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	450.00	35%	450.00	31.50	481.50
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	500.00	45%	500.00	35.00	535.00
BKTRR	REMOVE & TRANSFER ITEMS TO NEW TRUNK LID	1	500.00	325%	500.00	35.00	535.00
BOJSE	BODY JOINT SEALANT. end panel	1	100.00	80%	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT. floor panel	1	100.00	80%	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT. fender	1	100.00	80%	100.00	7.00	107.00
BKRP02B	CUT & RENEW RR FLOOR PANEL. FENDERS & DAMAGE PARTS	1	7500.00	6,500%	7500.00	525.00	8025.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	4000.00	3,900%	4000.00	280.00	4280.00
BKOT00A	PLACE VEHICLE TO BENCH FOR CHASSIS FRAME ALIGNMENT	1	1200.00	1,000%	1200.00	84.00	1284.00
BO-TOW	TOWING SERVICES (MBBS)	1	180.00	80%	180.00	12.60	192.60
Sum Labor					17430.00	1,220.10	18,650.10

Survey By

Date & Time

Excess

Status

Signature

Total Amount 23,962.61 1,677.39 25,640.00

Total (Inclusive of GST) 25,640.00

Repair dly. - 15 dly
P/P.

before pain photo

Sunpin@1kcauto.com

Sun Pin (Lkk)
27/08/2020

TP without prejudice

Resurvey
Sun Pin (Lkk.)
28/08/2020

Printed on 27/8/2020 12:16:51 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd., it will be refunded.