



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
Registration No : SLK2027K
Chassis No : MRHFC5650GT000702
Model : CIVIC 1.6 VTI YM2016
Owner's Name : GOH CHIN CHAI
Ins Policy No. :
Date of Accident : 26/8/2020

Document No. : SQT20002700 **Page** 1
Date : 26. Aug 2020
Customer No. : WZF002
Svc Advisor : ANIKKA LAI SWEE KAM
Engine No : R16B21600952
Date | Time : 26. Aug 2020 10:57:25 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: GOH CHIN CHAI OWNER INSURER: TOKIO MARINE ACC DATE: 26/08/2020 SURVEYED BY: DATE: REF NO: TP INSURER: FIRST CAPITAL TP VEH: SHC1456B						
68500-TEA-N00ZZ	LID COMP TRUNK	1	531.20	25	398.40	27.89	426.29
68610-TEA-T10ZZ	HINGE COMPR.TRUNK	1	48.90	25	36.67	2.57	39.24
68660-TEA-T10ZZ	HINGE COMPL.TRUNK	1	48.90	25	36.67	2.57	39.24
74865-TEA-T01	WEATHERSTRIPTRUNK LID	1	70.00	25	52.50	3.68	56.18
74851-TEA-003	LOCK ASSYTRUNK	1	81.20	25	60.90	4.26	65.16
74862-TEA-003	STRIKERTRUNK LID	1	7.80	25	5.85	0.41	6.26
74890-TEA-T11ZB	GARNISH ASSYRR.LICENSE	1	109.90	25	82.42	5.77	88.19
75701-TBA-A10	EMBLEM,H-MARK	1	13.30	25	9.97	0.70	10.67
90301-ST0-003	NUTPUSH 3MM	2	2.10	25	3.15	0.22	3.37
34100-TEA-T11	LIGHT ASSYLICENSE	1	68.70	25	51.52	3.61	55.13
84620-TEA-Z11ZA	LINING ASSYTRUNK LID	1	36.00	25	27.00	1.89	28.89
75722-TBA-A00	EMBLEM SETRR.	1	12.90	25	9.67	0.68	10.35
75725-TEA-T01	EMBLEMRR.	1	12.00	25	9.00	0.63	9.63
39530-TBA-A01	CAMERA ASSYRR.VIEW	1	344.70	25	258.52	18.10	276.62
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	1	617.20	25	462.90	32.40	495.30
71593-TEA-T01	SPACERR.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22

Printed on 26/8/2020 12:49:41 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
Registration No : SLK2027K
Chassis No : MRHFC5650GT000702
Model : CIVIC 1.6 VTI YM2016
Owner's Name : GOH CHIN CHAI
Ins Policy No. :
Date of Accident : 26/8/2020

Document No. : SQT20002700 **Page** 2
Date : 26. Aug 2020
Customer No. : WZF002
Svc Advisor : ANIKKA LAI SWEE KAM
Engine No : R16B21600952
Date | Time : 26. Aug 2020 10:57:25 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
71598-TEA-T01	SPACERL.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIP,BUMPER	22	2.30	25	37.95	2.66	40.61
71505-TBA-A00	BRACKETR.RR.BUMPER SIDE	1	2.50	25	1.87	0.13	2.00
71555-TBA-A00	BRACKETL.RR.BUMPER SIDE	1	2.50	25	1.87	0.13	2.00
33505-TEA-T01	REFLECTOR ASSYR.RR.	1	7.90	25	5.92	0.41	6.33
33555-TEA-T01	REFLECTOR ASSYL.RR.	1	7.90	25	5.92	0.41	6.33
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER	1	39.80	25	29.85	2.09	31.94
71503-TEA-T00	GARNISH,R.RR.BUMPER SIDE	1	8.50	25	6.37	0.45	6.82
71508-TEA-T00	GARNISH,L.RR.BUMPER SIDE	1	8.50	25	6.37	0.45	6.82
71504-TBA-A00	COVERR.FINISHER	1	12.00	25	9.00	0.63	9.63
71509-TBA-A00	COVERL.FINISHER	1	12.00	25	9.00	0.63	9.63
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER	1	180.00	25	135.00	9.45	144.45
65550-TEA-T00ZZ	PAN COMPSPARE TIRE	1	236.70	25	177.52	12.43	189.95
66100-TEC-307ZZ	PANEL SETRR.	1	265.70	25	199.27	13.95	213.22
84640-TEA-Z01ZA	LINING ASSYRR.PANEL	1	50.30	25	37.72	2.64	40.36
84521-TEA-Q01ZA	LID ASSYSPARE TIRE	1	65.70	25	49.27	3.45	52.72
84542-TET-H00	BOX COMPTOOL	1	41.50	25	31.12	2.18	33.30
34271-S5A-A01	LAMP UNIT	1	90.50	25	67.87	4.75	72.62
04636-TEA-T00ZZ	PANEL SETR.RR.OUTSIDE	1	777.50	25	583.12	40.82	623.94
04646-TEA-T00ZZ	PANEL SETL.RR.OUTSIDE	1	777.50	25	583.12	40.82	623.94
74483-TEA-T00	PACKINGFUEL ADAPTER	1	3.50	25	2.62	0.18	2.80
63910-TEA-T00ZZ	LID COMPFUEL FILLER	1	116.60	25	87.45	6.12	93.57
75450-TEA-T02	OUTLET ASSY,RR.AIR	1	8.80	25	6.60	0.46	7.06
66154-TBA-A00ZZ	STIFFENERL.RR.PANEL SIDE	1	29.20	25	21.90	1.53	23.43
66501-TEA-T00ZZ	STIFFENERRR.SHELF FR.	1	46.30	25	34.72	2.43	37.15
66500-TET-H00ZZ	SHELF COMPRR.PARCEL	1	267.10	25	200.32	14.02	214.34
65660-TEA-T00ZZ	FRAME COMP,L.RR.FLOOR	1	703.10	25	527.32	36.91	564.23
64701-TEA-T00ZZ	PANELL.RR.INSIDE	1	231.50	25	173.62	12.15	185.77
64710-TEA-315ZZ	STIFFENER COMP.,L.RR.SHOCK ABSORBER	1	142.00	25	106.50	7.46	113.96

Printed on 26/8/2020 12:49:41 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
Registration No : SLK2027K
Chassis No : MRHFC5650GT000702
Model : CIVIC 1.6 VTI YM2016
Owner's Name : GOH CHIN CHAI
Ins Policy No. :
Date of Accident : 26/8/2020

Document No. : SQT20002700 **Page** 3
Date : 26. Aug 2020
Customer No. : WZF002
Svc Advisor : ANIKKA LAI SWEE KAM
Engine No : R16B21600952
Date | Time : 26. Aug 2020 10:57:25 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
64730-TEC-U00ZZ	WHEELHOUSE COMPL.RR	1	280.00	25	210.00	14.70	224.70
33500-TEA-T01	TAILLIGHT ASSYR.	1	285.50	25	214.12	14.99	229.11
33550-TEA-T01	TAILLIGHT ASSYL.	1	307.40	25	230.55	16.14	246.69
34150-TEX-Y01	LIGHT ASSYR.LID	1	133.60	25	100.20	7.01	107.21
34155-TEX-Y01	LIGHT ASSYL.LID	1	133.60	25	100.20	7.01	107.21
38387-TZ5-A01	ANTENNA ASSYL.F.	1	60.80	25	45.60	3.19	48.79
74940-SZW-003	BUZZER ASSYSMART	1	62.90	25	47.17	3.30	50.47
91534-SWA-003	CLIPCOUPLER	1	5.20	25	3.90	0.27	4.17
73227-TEA-003	RUBBER CWINDSHIELD DAM	1	18.80	25	14.10	0.99	15.09
73525-SYY-000	RUBBERRR QTR W/SHIELD	3	9.90	25	22.27	1.56	23.83
91501-S70-003	FASTENER BW/SHIELD	2	5.30	25	7.95	0.56	8.51
91536-SS0-J01	FASTENER AW/SHIELD	2	3.80	25	5.70	0.40	6.10
91568-TF0-003	CLIP,WINDSHIELD UPPER	2	3.20	25	4.80	0.34	5.14
73125-SR3-000	RUBBER, W/SHIELD	1	12.90	25	9.67	0.68	10.35
73126-SR3-000	RUBBER, W/SHIELD	1	14.70	25	11.02	0.77	11.79
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
73550-TEA-T01	GLASS ASSYL.QUARTER WINDSHIEL	1	149.20	25	111.90	7.83	119.73
73500-TEA-T01	GLASS ASSYR.QUARTER WINDSHIEL	1	149.20	25	111.90	7.83	119.73

Sum Item **6032.61** **422.29** **6,454.90**

BO-R-COOL-RRQ SUPPLY & INSTALL SOLAR FILM ON REAR QTR GLASS. 1 250.00 250.00 17.50 267.50
BO-R-COOL-RRQ SUPPLY & INSTALL SOLAR FILM ON REAR QTR GLASS. 1 250.00 250.00 17.50 267.50

Sum Ext. Service **500.00** **35.00** **535.00**

BOSUN SUNDRIES 1 100.00 100.00 7.00 107.00
BG02R REPLACE RR. WINDSCREEN.(N) 1 650.00 650.00 45.50 695.50
BG51R REPLACE RR. L QTR GLASS.(N) 1 250.00 250.00 17.50 267.50
BG52R REPLACE RR. R QTR GLASS.(N) 1 250.00 250.00 17.50 267.50

Printed on 26/8/2020 12:49:41 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
Registration No : SLK2027K
Chassis No : MRHFC5650GT000702
Model : CIVIC 1.6 VTI YM2016
Owner's Name : GOH CHIN CHAI
Ins Policy No. :
Date of Accident : 26/8/2020

Document No. : SQT20002700 **Page** 4
Date : 26. Aug 2020
Customer No. : WZF002
Svc Advisor : ANIKKA LAI SWEE KAM
Engine No : R16B21600952
Date | Time : 26. Aug 2020 10:57:25 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	150.00		150.00	10.50	160.50
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	150.00		150.00	10.50	160.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	800.00		800.00	56.00	856.00
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	450.00		450.00	31.50	481.50
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	450.00		450.00	31.50	481.50
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	500.00		500.00	35.00	535.00
BKTRR	REMOVE & TRANSFER ITEMS TO NEW TRUNK LID	1	500.00		500.00	35.00	535.00
BOJSE	BODY JOINT SEALANT.	1	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT.	1	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT.	1	100.00		100.00	7.00	107.00
BKRP02B	CUT & RENEW RR FLOOR PANEL. FENDERS & DAMAGE PARTS	1	7500.00		7500.00	525.00	8025.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	4000.00		4000.00	280.00	4280.00
BKOT00A	PLACE VEHICLE TO BENCH FOR CHASSIS FRAME ALIGNMENT	1	1200.00		1200.00	84.00	1284.00
Sum Labor					17250.00	1,207.50	18,457.50

Survey By

Date & Time

Excess

Status

Signature

Total Amount 23,782.61 1,664.79 25,447.40

Total (Inclusive of GST) 25,447.40

Printed on 26/8/2020 12:49:41 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.