

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/TP/0593/2020/GW

24-Aug-20

Glory Tan

1 OF 1

SFW 3104 Y

Q7 2.0 TFSI QU

Quantity	Description	Unit Price	Amount
Parts			
1	Adapter cable loom crash sensor for airbag <i>snapped</i>	\$ 51.00	✓
2	Front bumper guide section RHS <i>cracked</i>	\$ 44.00	✓
3	Radiator air guide RHS <i>cracked</i>	\$ 28.00	✓
4	Temperature sensor bracket <i>new</i>	\$ 5.00	✓
5	Headlight mounting RHS <i>cracked</i>	\$ 117.00	✓
6	Engine mounting LHS ?	\$ 370.00	?
Labours			
1	To carry out first measurement test on car-o-liner.	s/n \$ 800.00	<i>work</i> ?
2	To remove and reinstall engine assy with gearbox assy to facilitate renewal of engine mounting.	s/n \$ 2,800.00	?
3	To carry out repairing of front chassis frame lhs on car-liner.	\$ 2,700.00	?
4	To setup the car on car-o-liner.	s/n \$ 2,400.00	?
TOTAL		\$ 9,315.00	

For Premium Automobiles Pte Ltd

Adrian L
1/s 31/08/20
HLS

Authorized Signature