

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMM 8993]

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 280.00 /	
2	To remove and transfer lhs headlight control unit and power module.	S/N \$ 350.00 ✓ 250 /	
3	To dismantle and renew front bumper and lhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 1,050.00 500 /	
4	To respray front bumper.	\$ 900.00 550 /	
5	To carry out diagnostic check.	S/N \$ 192.00 / /	
TOTAL LABOUR CHARGES		: \$ 2,772.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMM 8993 J

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>de</i>	\$	1,987.00 589.60
2	FRONT BUMPER FIXING PARTS <i>? XSVL</i>	\$	185.00
3	FRONT BUMPER GUIDE SECTION - LH <i>? XSVL</i>	\$	38.00
4	FRONT BUMPER GRILLE - CENTRE <i>XNN</i>	\$	159.00
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>XNN</i>	\$	530.00
6	FRONT BUMPER CLOSING ELEMENT - LH <i>XNN</i>	\$	293.00
7	FRONT BUMPER COVER TRIM - LH <i>XNN</i>	\$	161.00
8	RADIATOR GRILLE <i>cm</i>	\$	1,406.00 124.80
9	RADIATOR GRILLE CLOSING ELEMENT <i>? cm</i>	\$	189.00 50.80
10	AIRCON STICKER <i>XNN</i>	NEC \$	8.00 5.68
11	CAUTION SIGN STICKER <i>XNN</i>	NEC \$	14.00 10.80
12	FRONT BUMPER AIR GUIDE GRILLE - LH <i>XNN</i>	\$	186.00
13	FRONT BUMPER SIDE REINFORCEMENT BEAM <i>? bt</i>	\$	715.00 571.60
14	FRONT BUMPER FOAM FILLER PIECE <i>? cm</i>	\$	187.00 149.60
15	FOAM FILLER PIECE COVER <i>? XSVL</i>	\$	121.00
16	LED HEADLIGHT - LH <i>cm</i>	\$	5,455.00 4364.00
17	LIFT CYLINDER - LH <i>XNN</i>	\$	141.00
18	RADIATOR AIR GUIDE - LH <i>XNN</i>	\$	24.00
19	FRONT NO PLATE <i>me</i>	S/N \$	60.00
20	SUNDRIES <i>? XNN</i>	\$	200.00

TOTAL SPARE PARTS CHARGES

: \$12,059.00

TOTAL LABOUR CHARGES

: \$ 2,772.00

GRAND TOTAL

: \$14,831.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *RASUL - 4p 9000068*
Surveyed Date : *28/08/2020 @ 1020*
Authorised Date :
Excess Cost : *3 days + 1 = 4 days*
Liability : *EXCESS: TBA*
Remarks : *Receipt*
Resurvey before print

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant