

Date : 29.08.20

Vehicle Reg No.	SHA1955M	CTPL
-----------------	----------	------

25.08.20

(b) Labour Charges

Total for Part-By-Part Repair Cost

Total for Lumpsum repair cost after Less:

20%

\$1,050.00

Final Lumpsum Repair cost

\$1,050.00

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Name : LIM KWOK ENG

Tel : 62148316

Fax 65468156

Name : Taufikh

Date : 31/8/20

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305418759
 REGN NO : SHA1955M
 MILEAGE : 0000000000
 MAKE : TOYOTA
 MODEL : PRIUS HYBRID(G4)
 DATE OF REGN : 05.07.2017
 DATE/TIME IN : 25.08.2020 14:35
 ACCIDENT DATE : 25.08.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0001	04-01-0302-2282-G	PRIG4 COVER REAR BUMPER	1 L	458.60 25.00 343.95
0002	04-01-0302-2267-G	PRIVC BUMPER PIECE	10 L	22.00 25.00 16.50
0003	04-01-0302-2287-G	PRIG4 GUARD-REAR BUMPER C	1 L	552.60 25.00 414.45
0004	09-01-9999-0068-A	HYUNDAI REVERSE SENSOR AS	1 N	135.70 10.00 122.13

SUB-TOTAL : 897.03

JOB NATURE

0000 L	PANEL BEATING	350.00
0001 23-502	SPRAYPAINT ON AFFECTED AREA	250.00
0002 20-22	REMOVE/REFIX REVERSE SENSOR	80.00

SUB-TOTAL : 680.00

TOTAL : 1,577.03

MVA NAME & SIGNATURE

DATE :

SURVEYOR NAME & SIGNATURE

DATE :

Tanphir 97495749 Wastley.
 WP 26/8/20 C 12pm
 02 days

1/5. Resey after repair \$1,050/-
 Tanphir C 11/11/2020

AUTHORISED : YES / NO

550

1,324.90
-20%

1,059.92

1,033.20

-25%

774.50