



60 Woodlands Industrial Park E4

Singapore 757705

Tel: 65 6362 3422

Fax: 65 6368 7420

SMRT Vehicle Repair Estimate

Group :	Buses / Taxi	s / Commercial					
Reg. No :	GBD5620H				Ref. No :		
Make/Model :	TFR86JDR				Ref. Date	1	
Chassis No. :	MPATFR86J	FT001309			Mileage :	8	
Name of Driver :					Rental / Re	eplacement Vehicle YES /	NO
DOA:	:						
Vehicle Towed Ba	ack?	YES/ NO				The damages on the vehicle ar	
Date/ Time:						indicated in the following diagra	nm:
Type of Accident	: Skid / Head-	-Rear / Head-On / Si	de Swipe / Othe	rs			1
Special Instruct	tion to ARC,						
Signature:							
Date:	==						
Accident Repair Joi	b Card No:				Date Prepar	red :	
Summary of C	harges				Repair Com	pleted :	
Ì		ARC	Quotation			Adjustment by Sun	/eyor
Total Labour Charg	ges	\$2	500.00			\$0.00	
Total Spray Paintin	ng Charges	\$1	950.00			\$0.00	
Other Charges	-	\$8	300.00			\$0.00	
Total Parts Charge	es _		056.87			\$0.00	
	=	\$14	,306.87			\$0.00	=
PART BY PART / LUMP SUM			Lump Sum Repai	ir (if any)	_		
No	o. of Repair Da	ays [06	Days]		No.	of Repair Days [Days]
	Signature:	Prepared By			Adjusted by:]
QN No. :			Inv	voice No.			
Signed :				Date:			

Labour Charges

Item	Job Scope	ARC Quotation	Adjustment by Surveyor
1	TO REMOVE ALL DAMAGED ITEMS, TO CUT AND WELD REAR END PANEL. TO REFIT NEW ITEMS. TO REALIGN AND PULL REAR END PANEL PORTION.	\$2,500.00	
	Total Labour Charges	\$2,500.00	\$0.00

Spray Painting Charges

Item	Job Scope	ARC Quotation	Adjustment by Surveyor
1	TO RESPRAY PAINT REAR BUMPER	\$300.00	
2	TO RESPRAY PAINT REAR END DOOR	\$300.00	
3	TO RESPRAY PAINT REAR END PANEL	\$250.00	
4	TO RESPRAY PAINT REAR RH FENDER	\$300.00	
5	TO RESPRAY PAINT REAR LH FENDER	\$300.00	
6	TO RESPRAY PAINT REAR CHASSIS LH	\$250.00	
7	TO RESPRAY PAINT REAR CHASSIS RH	\$250.00	
	Total Spray Painting Charges	\$1,950.00	\$0.00

Other Charges

Item	Job Scope	ARC Quotation	Adjustment by Surveyor
1	TO CONDUCT SYSTEM WIRING CHECK.	\$80.00	
2	TO REMOVE AND REINSTALL REAR REVERSE SENSOR.	\$120.00	
3	TO WASH AND VACUUM	\$50,00	
4	TO ALIGN BOTH REAR CHASSIS	\$400.00	
5	TO WASH AND VACUUM	\$50.00	
6	TO REMOVE SUNDRY PARTS	\$100.00	
	Total Other Charges	\$800.00	\$0.00

Adjusted by Surveyor

raits	Charges							Surveyor
Item	Part Code	Parts Description	Qty	List Price (\$)	Discou nt (%)	Final Price (\$)	Replace (/) Repair (R)	Replace (/) Repair (R) Not Given (X)
1		REAR BUMPER	1	\$758.50	15%	\$644.73	REPLACE (/)	
2		REAR BUMPER GARNISH	1	\$342.10	15%	\$290.79	REPLACE (/)	
3		SENSOR REVERSE	1	\$200.00	0%	\$200.00	REPLACE (/)	
4		REAR END DOOR	1	\$1,503.40	15%	\$1,277.89	REPLACE (/)	
5		REAR DECK PANEL LH	1	\$1,102.30	15%	\$936.96	REPLACE (/)	
6		REAR DECK PANEL RH	1	\$1,102.30	15%	\$936.96	REPLACE (/)	
7		"STICKER EM 1"	3	\$400.00	0%	\$400.00	REPLACE (/)	
8		"STICKER 70KM/H"	1	\$20.00	0%	\$20.00	REPLACE (/)	
9		REAR CHASSIS LH	1	\$1,522.30	15%	\$1,293.96	REPLACE (/)	
10		REAR CHASSIS RH	1	\$1,522.30	15%	\$1,293.96	REPLACE (/)	
11		REAR END DOOR HANDLE	1	\$290.40	15%	\$246.84	REPLACE (/)	
12		EMBLEM "ISUZU DMAX"	1	\$190.40	15%	\$161.84	REPLACE (/)	
13		REAR TAIL LAMP LH	1	\$310.20	15%	\$263.67	REPLACE (/)	
14		REAR TAIL LAMP RH	1	\$310.20	15%	\$263.67	REPLACE (/)	
15		REAR NUMBER PLATE	1	\$20.00	0%	\$20.00	REPLACE (/)	
16		REAR BUMPER LOWER GARNISH	1	\$245.60	15%	\$208.76	REPLACE (/)	
17		REAR BUMPER REINFORCEMENT	1	\$702.20	15%	\$596.87	REPLACE (/)	
		Total Parts Ch	arges	\$10,542.20		\$9,056.87	, and the second	

Surveryor Remark: