MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934

NT HP: 98888885

Estimation

Date:

5/10/2020

Vehicle: Make / Model:

GBH3387Z TOYOTA DYNA

TO PUTTY,SPRAY PAINT,POLISH WAX	Chassis No:								
1 REAR SIDE GATE RH	No.	Description		Unit Unit Price		Amount			
2 REAR SIDE GATE LOCK RH		Parts Replacement:							
3 REAR TAILAMP RH X	1	REAR SIDE GATE RH / PP	?	1	\$	1,985.00	\$	1,985.00	
\$ 2,356.00 Less 25% \$ 589.00 Total \$ 1,767.00 S/Nett items: 1 REAR SAFETY BAR >: \$ 1 \$ 800.00 \$ 800.00 2 REAR SIDE SAFETY RAILING RH >	2	REAR SIDE GATE LOCK RH 📈 🤾		1	\$	159.00	\$	159.00	
\$ 2,356.00 Less 25% \$ 589.00 Total \$ 1,767.00 S/Nett items: 1 REAR SAFETY BAR >	3	REAR TAILAMP RH X5V(1	\$	212.00	\$	212.00	
Less 25%									
Total \$ 1,767.00								2,356.00	
S/Nett items: 1					Less 25%		\$	589.00	
1 REAR SAFETY BAR						Total	\$	1,767.00	
1 REAR SAFETY BAR	\vdash	S/Nett items:							
2 REAR SIDE SAFETY RAILING RH	1		(1	\$	800.00	\$	800.00	
Labour to: \$ 1,600.00	\rightarrow	REAR SIDE SAFETY RAILING RH	n	1	\$	800.00	\$	800.00	
Labour to:		/ •							
1 TO PANEL BEAT WELD, CUT, ADJUST AND KNOCK 1 \$ 600.00 \$ 600.00 2 3 00.00 3 TO SPRAY TUFF COAT 1 \$ 300.00 \$ 300.00 4 CHECK AND REFIX WIRING AND BULB 1 \$ 60.00 \$ 60.00 \$ \$ 1,560.00 \$ 1,560.00 \$ 1,560.00							\$	1,600.00	
2 TO PUTTY,SPRAY PAINT,POLISH WAX 1 \$ 600.00 \$ 600.00 3 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	\vdash	Labour to:							
2 TO PUTTY,SPRAY PAINT,POLISH WAX 1 \$ 600.00 \$ 600.00 3 00.00 3 00.00 4 CHECK AND REFIX WIRING AND BULB 1 \$ 60.00 \$ 60.00 \$ \$ 60.00 \$ \$ 1,560.00 \$ 1,560.00 \$ 1,560.00	1	TO PANEL BEAT WELD, CUT, ADJUST AND KNOW	СК	1	\$	600.00		600.00	250
3 TO SPRAY TUFF COAT 1 \$ 300.00 \$ 300.00 \$ 4 CHECK AND REFIX WIRING AND BULB 1 \$ 60.00 \$ 60.00 \$ \$ 1,560.00 \$ Total Amount for Labour \$ 1,560.00	\rightarrow			1	\$	600.00		600.00	300
4 CHECK AND REFIX WIRING AND BULB 1 \$ 60.00 \$ 60.00 \$ \$ 1,560.00 \$ \$ 1,560.00 \$ Total Amount for Labour \$ 1,560.00	\vdash			1	\$	300.00	_	300.00	30
Parts Replacement Amount \$ 3,367.00 Total Amount for Labour \$ 1,560.00	\vdash	CHECK AND REFIX WIRING AND BULB		1	\$	60.00	\$	60.00	\mathbf{k}
Parts Replacement Amount \$ 3,367.00 Total Amount for Labour \$ 1,560.00									
Total Amount for Labour \$ 1,560.00	\vdash						\$	1,560.00]
Total Amount for Labour \$ 1,560.00	\vdash]
Total Amount for Labour \$ 1,560.00	Parts Replacement Amount						\$	3,367.00]
Total Amount \$ 4 927 00	Total Amount for Labour						1,560.00		
Total Amount \$ 4 927 00									
	Total Amount					mount	\$	4,927.00	1

Repair day - 2 day

Altergin physo.

Sun Pro (Licle)

05/10/202e

The with projected

LKK Auto Consultants hence notify the Repairer of the following:

- · To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: