

05/10/2020.



**MY CAR CONSULTANT PTE LTD**  
Reg no.: 2016058787

Reg no.: 201605878Z

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934  
HP: 98888885

## Estimation

Date:

5/10/2020

Vehicle:

GBH3387Z

Make / Model:

TOYOTA DYNA

Chassis No:

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	REAR SIDE GATE RH	1	\$ 1,985.00	\$ 1,985.00
2	REAR SIDE GATE LOCK RH	1	\$ 159.00	\$ 159.00
3	REAR TAILAMP RH	1	\$ 212.00	\$ 212.00
				\$ 2,356.00
			Less 25%	\$ 589.00
			Total	\$ 1,767.00
S/Nett items:				
1	REAR SAFETY BAR	1	\$ 800.00	\$ 800.00
2	REAR SIDE SAFETY RAILING RH	1	\$ 800.00	\$ 800.00
				\$ 1,600.00
Labour to:				
1	TO PANEL BEAT WELD,CUT,ADJUST AND KNOCK	1	\$ 600.00	\$ 600.00
2	TO PUTTY,SPRAY PAINT,POLISH WAX	1	\$ 600.00	\$ 600.00
3	TO SPRAY TUFF COAT	1	\$ 300.00	\$ 300.00
4	CHECK AND REFIX WIRING AND BULB	1	\$ 60.00	\$ 60.00
				\$ 1,560.00
			Parts Replacement Amount	\$ 3,367.00
			Total Amount for Labour	\$ 1,560.00
			Total Amount	\$ 4,927.00

Repair day - 2 day

4/5

Alto para photo.

$$\sin p_n(L/c)$$

05/10/2020

TP with prepos

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: \_\_\_\_\_

Date: