

STM2910Z 2008 Dec
KMITD441B294658732
Hyundai Avante 1591CC

78 Ave
Jia le

CC4/ATA20009078/Ads3

Front Windscreen Pillar LH	Dented	890 ✓
Front Windscreen Pillar Inner Garnish LH	new	98 +
Front Windscreen Pillar Inner Garnish clips LH.	new	20 +
Front Windscreen Moulding	} New	97 ✓
Front Windscreen Sealant		60(SN) ✓
Front Door LH	Distorted	1038 ✓
Front Door Lock LH	Turned	238 ✓
Front Door Weatherstripe LH.	Lt	118 ✓
Front Door Hinge x 02 LH	} All new	39 x 2 = 78 +
Front Door Check LH		48 x
Front Door Outer Handle LH.	could	A4 ✓
Front Door Outer Handle End Piece LH	Missing	20 ✓
Front Door Glass LH	Shattered	198 ✓
Front Door Glass Outer Moulding LH	Dented	49 ✓
Front Door Glass Regulator Gear LH	} Banged	238 ✓
Front Door Glass Regulator Motor LH		212 ✓

SJM2910Z

Front Door Glass Channel LH.	Best	111 ✓
Front Door Inner Trim Board LH	Defnd	586 ✓
Front Door Inner Trim Board Clips LH	NM	30 ✓
Front Door Speaker LH.	NM	180(SN) ✗
Front Door Wing Mirror LH.	Damd	358 ✓
Front Door Black Tape LH.	NM	60(SN) ✓
Centre Pillar LH	Dented	968 ✓
Centre Pillar Garnish LH	Defnd	112 ✓
Centre Pillar Garnish Clips LH.	NM	30 ✓
Rocker Panel LH.	Repis	692 ✗
Rocker Panel Top Garnish (Front) LH.	2	55 ✗
Rocker Panel Top Garnish (Rear) LH.	2	49 ✗
Rear Door LH	Distorted	1054 ✓
Rear Door Lock LH	Damd	298 ✓
Rear Door Weatherstripe LH.	nt	128 ✓

SJM2910Z.

Rees	Door	Hinge	LH x 02	Best	39 x 2 = 78	✓
Rees	Door	Cheek	LH.	Best	48	✓
Rees	Door	Glass	LH.	Lt	195	✓
Rees	Door	Glass	Outer Moulding	LH. ^{xl} m	48	x
Rees	Door	Glass	Regulator Gear	LH. ^{2nd} m	281	✓
Rees	Door	Glass	Regulator Molar	LH. ^{np} m	241	x
Rees	Door	Glass	Channel	LH. Best	114	✓
Rees	Door	Inner Trim Board	LH	^{behind} m	589.	✓
Rees	Door	Inner Trim Board	Clips.	LH.	30	✓
Rees	Door	Spacers	LH.	^{new} m	180(SN)	x
Rees	Door	Black Tape	LH.	^{new} m	60(SN)	✓
Rees	Bumper.			^{De band}	491	✓
Rees	Bumper	Clips.		^{new}	30	✓
Rees	Bumper	Side Holder	x 02	^{np} m	28 x 2 = 56	x
Tail	Lamp	RH.		Lt	282	✓

8JM2910Z.

Rees Wheel Rim RH.	At	600(SN) 400(SN)
Rees Tyre RH	At	280(SN) 200(SN)
Rees Lower Arm. RH.	Best	353 ✓
Rees Knuckle Arm RH	Dangd.	481 ✓
Rees Wheel Hub c/w Bearing, RH	Byd	317 ✓
Rees Shock Absorber RH	Best	286 ✓
Rees Control Arm RH.	Best	261 ✓
Rees Cross member	Alt m	785. X.

10653

S.N: 780

8522.40

STm 29102.

Panel Beating.

~~2000~~ 1400

Spray Painting.

~~1600~~ 1200.

Wiring.

3840

~~100~~ 30.

To underseal

~~250~~ 120.

To remove reverse sensor

~~100~~ 50

To remove upholstery and floor carpet.

~~400~~ 280.

To remove front windscreen.

~~180~~ 120.

To transfer front and rear door fittings.

~~300~~ 160

To remove rear undercarriage.

~~350~~ 220

To perform wheel alignment.

~~150~~ 80

To vacuum interior of glass shards.

~~100~~ 60

Towing Fees. (King Roller).

120. ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 13142.40

2/8: 10.5K.

10 Days.