

PLEASE ARRANGE TO SURVEY VEHICLE AT
NO.8 KAKI BUKIT AVE 4 GATE 2
#03-21
SINGAPORE 415875

LINDA LIAO
STK AUTO (S) PTE LTD

Date : 25/08/2020

To : AIG ASIA PACIFIC INSURANCE PTE LTD

Attn : Motor Claim Department

Owner : PENG YICHENG

DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD

Certificate Number : MT/00654321

Accident Date : 24/08/2020

Vehicle Number : SJM2910Z

Make & Model : HYUNDAI HD AVANTE 1.6 M

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
1	FRONT BUMPER	\$ 350.00	
1	FRONT BUMPER RETAINER RH	\$ 65.00	
1	FRONT BUMPER RETAINER LH	\$ 65.00	
1	LH FRONT FENDER	\$ 450.00	
1	LH FRONT FENDER INNER SHIELD	\$ 150.00	
1	LH FRONT DOOR	\$ 650.00	
1	LH FRONT DOOR MOULDING	\$ 150.00	
1	LH FRONT DOOR INNER HANDLE	\$ 250.00	
1	LH FRONT DOOR OUTER HANDLE	\$ 250.00	
1	LH FRONT DOOR LOCK	\$ 350.00	
1	LH FRONT DOOR CONTROL MODULE	\$ 450.00	
1	LH FRONT DOOR REGULATOR	\$ 380.00	
1	LH FRONT DOOR REGULATOR MOTOR	\$ 680.00	
1	LH FRONT DOOR GLASS	\$ 750.00	
1	LH FRONT WING MIRROR	\$ 680.00	
1	LH FRONT DOOR ROCKER PANEL	\$ 1,500.00	
1	LH FRONT DOOR PILLAR INNER	\$ 850.00	
1	LH FRONT DOOR PILLAR OUTER	\$ 850.00	
1	LH FRONT DOOR INNER GARNISH	\$ 650.00	
1	LH FRONT DOOR INNER MOULDING	\$ 450.00	
1	LH FRONT DOOR OUTER MOULDING	\$ 480.00	
1	LH FRONT DOOR BLADE TAPE	\$ 450.00	
1	FRONT WINDSCREEN PILLAR INNER	\$ 680.00	
1	FRONT WINDSCREEN PILLAR OUTER	\$ 680.00	
1	FRONT WINDSCREEN INNER GARNISH	\$ 480.00	
1	LH REAR DOOR	\$ 650.00	
1	LH REAR DOOR REGULATOR GEAR	\$ 380.00	
1	LH REAR DOOR REGULATOR	\$ 680.00	
1	LH REAR DOOR INNER HANDLE	\$ 250.00	
1	LH REAR DOOR INNER MOULDING	\$ 150.00	
1	LH REAR DOOR INNER TRIM BOARD	\$ 380.00	
1	LH REAR DOOR OUTER MOULDING	\$ 150.00	
1	LH REAR DOOR CONTRL MUDULE	\$ 350.00	
1	LH REAR DOOR HANDLE OUTER	\$ 150.00	
1	LH REAR DOOR LOCK	\$ 150.00	

1	LH REAR DOOR BLACK TAP	\$	200.00
1	REAR BUMPER	\$	350.00
1	REAR BUMPER RETAINER RH	\$	45.00
1	REAR BUMPER RETAINER LH	\$	45.00
1	LH REAR FENDER INNER SHIELD	\$	150.00
1	RH REAR SHOCK ABSORBER	\$	450.00
1	RH REAR SHOCK ABSORBER TOP MOULDING	\$	350.00
1	RH REAR STABILIZER BAR LINK	\$	550.00
1	RH REAR LOWER ARM	\$	350.00
1	RH REAR KNUCKLE ARM	\$	450.00
1	RH REAR KNUCKLE ARM BEARING	\$	450.00
1	REAR DRIVE SHAFT	\$	1,250.00
	Sub Total	\$	20,670.00
	DISCOUNT 20% on Parts	\$	4,134.00
	Total	\$	16,536.00
<u>Special Nett Item</u>			
10	LH FRONT FENDER INNER SHIELD CLIPS	\$	80.00
10	REAR BUMPER CLIPS	\$	80.00
10	FRONT WINDSCREEN INNER GARNISH CLIPS	\$	80.00
1	LH FRONT SPORT RIM	\$	650.00
1	LH FRONT TYRE	\$	450.00
1	RH REAR TYRE	\$	450.00
1	RH REAR SPORT RIM	\$	650.00
10	FRONT BUMPER CLIPS	\$	80.00
1	LH FRONT DOOR GLASS SEALANT	\$	65.00
1	LH REAR FENDER INNER SHIELD CLIPS	\$	65.00
1	LH REAR DOOR GLASS SEALANT	\$	65.00
1	WHOLE CAR SOLAR FILM	\$	1,200.00
		\$	3,915.00
<u>Labour charge</u>			
1	TO STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	\$	3,500.00
1	TO SPRAY PAINT ON ACCIDENT AREAS	\$	1,800.00
1	TO REMOVE AND REFIT RH FRONT DOOR COMPARTMENT	\$	180.00
1	TO REMOVE AND REFIT RH REAR DOOR COMPARTMENT	\$	180.00
1	TO RUST PROOFING	\$	150.00
1	TO CONDUCT WHEEL ALIGNMENT AND TYRE BALANCING	\$	150.00
1	TO REMOVE AND REFIT UNDER CARRIAGE	\$	250.00
1	TO REMOVE AND REFIT FRONT SEATS	\$	100.00
1	TO REMOVE AND REFIT REAR SEATS	\$	150.00
1	TO COMPUTER DAGNOSE TEST	\$	150.00
		\$	6,610.00
		\$	27,061.00

FRONT BUMPER CLIPS
LH FRONT FENDER INNER SHIELD CLIPS
LH REAR FENDER INNER SHIELD CLIPS
REAR BUMPER CLIPS
LH HEADLAMP BRACKET LH

LABOUR CHARGE

TO STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS
TO SPRAY PAINT ON ACCIDENT AREAS
TO REMOVE AND REFIT HEADLAMP WIRING
TO REMOVE AND REFIT FRONT DOOR LH
TO REMOVE AND REFIT REAR DOOR LH
TO RUST PROOFING ACCIDENT AREAS

Sub Total

MARK UP 10% on Parts

Total

Grand Total