



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number 63685502
Estimator Telephone Number 68662623
Accident Reporting Number 68662672


Date Generated : 25/08/2020

User ID : BoonChewTay

Section A - Accident Details


Registration Number	SMB3591B
Case Reference Number	BUS/08/20/1030
Registration Date	4/5/2015
Company Type	SMRT Buses Ltd
Make	ALEXANDER DENNIS
Model	ENVIRO 500
Name of Driver	Li Zhenjia
Type of Accident	Side Swipe
Accident Date and Time	18/8/2020 8:30 PM
Accident Reported Date and Time	18/8/2020 9:45 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB3591B-RIGHT REAR PORTION SMP9603M (TP) INSURED WITH AIG
Prepared Date and Time	25/8/2020 7:29 AM
Chassis Number	SFD76CLR5EMTL3763
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,060.00	\$0.00
Total Spray Cost	\$878.00	\$0.00
Total Spare Part Cost	\$0.00	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$1,938.00	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	25/08/2020 7:39 AM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	





SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number 63685992
Estimator Telephone Number 68662623
Accident Reporting Number 68662672

Date Generated : 25/08/2020

User ID : BoonChewTay

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,060.00	795 530
Total Labour	\$1,060.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$878.00	786.
Total Spray Painting & Panel Beating	\$878.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6011031	BODY RH	20412261/EX	Exterior Panel, Rad Access Door R/H	1.00	\$2,485.08	100.00	\$0.00	Repair	X R
6011242	BODY RH	30106514	PANEL EXTERIOR R/H, F OR ADL DD BUS	1.00	\$408.91	100.00	\$0.00	Repair	X R
6011069	VE	31155514	POD, TAIL LIGHT R/H, FOR ADL ES00 DD BUS	1.00	\$1,703.25	100.00	\$0.00	Repair	X R.
Total					\$4,597.24		\$0.00		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

4/5
After paint photo

Sun Pin (LKK)
25/08/2020
TP without prejudice
Repair day - 2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: