

CC6/AIA20009092/Aka3

FONG MOTORS

1 Kaki Bukit Ave 6 Blk C #01-27/45, AutoBay@ Kaki Bukit Singapore 417883
Tel: 6747 6388, Email: fongmotors@gmail.com
Company Reg No. 068972/00L

CORRECTIVE THERAPY SINGAPORE
BLK 486B TAMPINES AVE 9 #07-07
S521486

TP ALG.
Khanchan.

Estimate

Code: FM01/GBK3799C
Date: 26/8/2020
Vehicle No: GBK3799C
Model: PEUGEOT PARTNER
CHASSIS/ENG#: VR3EFYHZRLJ639629

PARTS

S/N	Particular	Quantity	Unit Price	Amount
1	REAR FENDER RH <i>Distorted.</i>	1	\$1,890.00	<u>\$1,890.00</u> ✓
2	REAR FENDER INNER SHIELD RH <i>Int</i>	1	\$175.00	\$175.00 ✓
3	REAR FENDER INNER SHIELD CLIPS RH <i>New</i>	5	\$10.00	\$50.00 30
4	REAR FENDER INNER SHIELD HOLDER RH <i>new</i>	1	\$145.00	\$145.00 X
5	REAR TAILGATE CABIN RUBBER WEATHER STRIP <i>new</i>	1	\$470.00	\$470.00 X.
6	REAR TAILGATE RH <i>Dented.</i>	1	\$1,950.00	<u>\$1,950.00</u> ✓
7	REAR TAILGATE HINGES U/L RH <i>Bent</i>	2	\$225.00	\$450.00 ✓
8	REAR TAILGATE CHECKER ASSY RH <i>Dend</i>	1	\$250.00	\$250.00 ✓
9	REAR TAILGATE INNER TRIMBOARD RH <i>new</i>	1	\$320.00	\$320.00 X
10	REAR TAILGATE RUBBER WEATHER STRIP RH <i>new</i>	1	\$210.00	\$210.00 X.
11	REAR TAILGATE MECHANISM LOCK U/L RH <i>1 piece dnd</i>	2	\$340.00	\$680.00 340.
12	REAR TAILGATE MECHANISM LOCK STRIKER U/L RH <i>new</i>	2	\$220.00	\$440.00 X.
13	REAR TAILGATE LOGO EMBLEM <i>new</i>	1	\$150.00	\$150.00 ✓
14	REAR TAILLAMP RH <i>cracked.</i>	1	\$380.00	\$380.00 ✓
15	REAR TAILLAMP PANEL RH <i>Dented.</i>	1	\$950.00	<u>\$950.00</u> 600.
16	REAR END PANEL <i>Dented</i>	1	\$680.00	\$680.00 ✓
17	REAR END PANEL CORNER MEMBER RH <i>Ryis</i>	1	\$370.00	\$370.00 P.
18	REAR END PANEL TOP GARNISH RH <i>new</i>	1	\$350.00	\$350.00 X
19	REAR BUMPER (CENTER) <i>Distorted.</i>	1	\$490.00	\$490.00 ✓
20	REAR BUMPER CORNER GARNISH RH <i>Distorted</i>	1	\$420.00	\$420.00 ✓
21	REAR BUMPER SIDE RETAINER L/R <i>RH Dented.</i>	2	\$210.00	\$420.00 210.
22	REAR BUMPER CORNER HOLDER L/R <i>new</i>	2	\$210.00	\$420.00 X
23	REAR BUMPER TOWING COVER <i>Missing</i>	1	\$115.00	\$115.00 ✓
24	REAR BUMPER REINFORCEMENT BEAM <i>Bent.</i>	1	\$380.00	\$380.00 ✓
25	REAR EXHAUST SILENCER BOX <i>new</i>	1	\$1,130.00	\$1,130.00 X
26	REAR EXHAUST SILENCER BOX RUBBER MOUNTING <i>new</i>	1	\$170.00	\$170.00 X.
SUBTOTAL BEFORE DISCOUNT				\$13,455.00
PERCENTAGE DISCOUNT 10%				\$1,345.50
Sub-total 1				<u>\$12,109.50</u>

8460

7614.

1	REAR TAILGATE GLASS SEALANT <i>New</i>	1	\$80.00	\$80.00 50.
2	REAR TAILGATE 70KM/H STICKER <i>New</i>	1	\$15.00	\$15.00 ✓
3	REAR TAILLAMP LIGHT BULB RH <i>New</i>	1	\$12.00	\$12.00 ✓
4	REAR TAILLAMP SIGNAL LIGHT BULB RH <i>New</i>	1	\$9.00	\$9.00 ✓
5	REAR TAILLAMP REVERSE LIGHT BULB RH <i>New</i>	1	\$9.00	\$9.00 ✓
6	REAR BUMPER CLIPS (SET) <i>New</i>	1	\$50.00	\$50.00 30
7	REAR BUMPER REVERSE SENSOR (SET) <i>Replaced</i>	1	\$250.00	\$250.00 200
8	REAR TRUNK PANEL TOP CARDBOARD <i>New</i>	1	\$600.00	\$600.00 X
Sub-total 2				<u>\$1,025.00</u>

295

Labour

1	To remove, reinstall electrical wiring harness, check lighting	1	\$60.00	\$60.00 30
2	To remove & refix reverse sensor assy and retify for proper functioning	1	\$80.00	\$80.00 50
3	To diagnose, replace/or repair to retify rear portion electrical system for proper functioning and where consistent to the accident	1	\$100.00	\$100.00 X.
4	To remove reinstall rear tailgate windscreen(to FR)	1	\$150.00	\$150.00 80.
5	To remove, reinstall roof top upholstery, trim garnish, trim liner carpet(to FR)	1	\$120.00	\$120.00 80.
6	To transfer tailgate mechanism & wiring assy(to FR)	1	\$100.00	\$100.00 80.
7	To respray, painting on the change bodyparts, repair portion and where consistent to the accident	1	\$1,200.00	\$1,200.00 800.
8	To remove & refix exhaust silencer box, realign and where consistent to the accident	1	\$100.00	\$100.00 X.
9	To provide labour, workmanship to change damaged bodyparts, repair, align body structure & damaged and where consistent to the accident	1	\$1,200.00	\$1,200.00 1000.
10	To set on chassis bench, adjust & align rear chassis	1	\$250.00	\$250.00 X
11	To apply anti-rust chemical on repaired & replaced panel and where consistent to the accident	1	\$120.00	\$120.00 100.
Labour Total				\$1,810.00
Parts & Labour Total				<u>\$14,944.50</u>

2220

Adrian Lj
H/S 09 Days.

total 10129

H/S : 8.1K.

8.1K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: