

## FONG MOTORS

1 Kaki Bukit Ave 6 Blk C #01-27/45, AutoBay@ Kaki Bukit Singapore 417883  
Tel: 6747 6388, Email: fongmotors@gmail.com  
Company Reg No. 068972/00L

CORRECTIVE THERAPY SINGAPORE  
BLK 486B TAMPINES AVE 9 #07-07  
S521486

TP ALG.  
Khoochan

### Estimate

Code: FM01/GBK3799C  
Date: 26/8/2020  
Vehicle No: GBK3799C  
Model: PEUGEOT PARTNER  
CHASSIS/ENG#: VR3EFYHZRLJ639629

### PARTS

S/N	Particular	Quantity	Unit Price	Amount
1	REAR FENDER RH Distorted.	1	\$1,890.00	\$1,890.00 ✓
2	REAR FENDER INNER SHIELD RH Int	1	\$175.00	\$175.00 ✓
3	REAR FENDER INNER SHIELD CLIPS RH New	5	\$10.00	<del>\$50.00</del> 30
4	REAR FENDER INNER SHIELD HOLDER RH New	1	\$145.00	\$145.00 X
5	REAR TAILGATE CABIN RUBBER WEATHER STRIP New	1	\$470.00	\$470.00 X
6	REAR TAILGATE RH Dented.	1	\$1,950.00	\$1,950.00 ✓
7	REAR TAILGATE HINGES U/L RH Bent	2	\$225.00	\$450.00 ✓
8	REAR TAILGATE CHECKER ASSY RH Dend	1	\$250.00	\$250.00 ✓
9	REAR TAILGATE INNER TRIMBOARD RH New	1	\$320.00	\$320.00 X
10	REAR TAILGATE RUBBER WEATHER STRIP RH New	1	\$210.00	\$210.00 X
11	REAR TAILGATE MECHANISM LOCKER RH 1 piece dnd	2	\$340.00	<del>\$680.00</del> 340
12	REAR TAILGATE MECHANISM LOCKER U/L RH New	2	\$220.00	\$440.00 X
13	REAR TAILGATE LOGO EMBLEM New	1	\$150.00	\$150.00 ✓
14	REAR TAILLIGHT RH Cracked.	1	\$380.00	\$380.00 ✓
15	REAR TAILLIGHT PANEL RH Dented.	1	\$950.00	<del>\$950.00</del> 600
16	REAR END PANEL Dented	1	\$680.00	\$680.00 ✓
17	REAR END PANEL CORNER MEMBER RH New	1	\$370.00	\$370.00 P.
18	REAR END PANEL TOP GARNISH RH New	1	\$350.00	\$350.00 X
19	REAR BUMPER (CENTER) Distorted.	1	\$490.00	\$490.00 ✓
20	REAR BUMPER CORNER GARNISH RH Distorted	1	\$420.00	\$420.00 ✓
21	REAR BUMPER SIDE RETAINER L/R RH Dend.	2	\$210.00	<del>\$420.00</del> 210
22	REAR BUMPER CORNER HOLDER L/R New	2	\$210.00	\$420.00 X
23	REAR BUMPER TOWING COVER Missing	1	\$115.00	<del>\$115.00</del> ✓
24	REAR BUMPER REINFORCEMENT BEAM Bent.	1	\$380.00	\$380.00 ✓
25	REAR EXHAUST SILENCER BOX New	1	\$1,130.00	\$1,130.00 X
26	REAR EXHAUST SILENCER BOX RUBBER MOUNTING New	1	\$170.00	\$170.00 X
SUBTOTAL BEFORE DISCOUNT				\$13,455.00
PERCENTAGE DISCOUNT 10%				\$1,345.50
Sub-total 1				\$12,109.50

8460

7614

1	REAR TAILGATE GLASS SEALANT <i>new</i>	1	\$80.00	<del>\$80.00</del> 50
2	REAR TAILGATE 70KM/H STICKER <i>new</i>	1	\$15.00	<del>\$15.00</del> ✓
3	REAR TAILLAMP LIGHT BULB RH <i>new</i>	1	\$12.00	<del>\$12.00</del> ✓
4	REAR TAILLAMP SIGNAL LIGHT BULB RH <i>new</i>	1	\$9.00	<del>\$9.00</del> ✓
5	REAR TAILLAMP REVERSE LIGHT BULB RH <i>new</i>	1	\$9.00	<del>\$9.00</del> ✓
6	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$50.00	<del>\$50.00</del> 30
7	REAR BUMPER REVERSE SENSOR (SET) <i>re-tested</i>	1	\$250.00	<del>\$250.00</del> 200
8	REAR TRUNK PANEL TOP CARDBOARD <i>new</i>	1	\$600.00	<del>\$600.00</del> X
			<b>Sub-total 2</b>	<b>\$1,025.00</b>

#### Labour

1	To remove, reinstall electrical wiring harness, check lighting	1	\$60.00	<del>\$60.00</del> 30
2	To remove & refix reverse sensor assy and retify for proper functioning	1	\$80.00	<del>\$80.00</del> 50
3	To diagnose, replace/or repair to retify rear portion electrical system for proper functioning and where consistent to the accident	1	\$100.00	<del>\$100.00</del> X
4	To remove reinstall rear tailgate windscreen(to FR)	1	\$150.00	<del>\$150.00</del> 80
5	To remove, reinstall roof top upholstery, trim garnish, trim liner carpet(to FR)	1	\$120.00	<del>\$120.00</del> 80
6	To transfer tailgate mechanism & wiring assy(to FR)	1	\$100.00	<del>\$100.00</del> 80
7	To respray, painting on the change bodyparts, repair portion and where consistent to the accident	1	\$1,200.00	<del>\$1,200.00</del> 800
8	To remove & refix exhaust silencer box, realign and where consistent to the accident	1	\$100.00	<del>\$100.00</del> X
9	To provide labour, workmanship to change damaged bodyparts, repair, align body work to be damaged and where consistent to the accident	1	\$1,200.00	<del>\$1,200.00</del> 1000
10	To set on chassis bench, adjust & align	1	\$250.00	<del>\$250.00</del> X
11	To apply anti-rust chemical on repaired & replaced panels and where consistent to the accident	1	\$120.00	<del>\$120.00</del> 100

<b>Labour Total</b>	<b>\$1,810.00</b>
<b>Parts &amp; Labour Total</b>	<b>\$14,944.50</b>

2020

Adrian Lj  
1/s 09 Days.

total 10129

1/s 8.1K

8.1K

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: