

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



Survey & Repair
7/09 @ 10am - 12pm

GST REG. NO : M2 - 0020081 - X

25 AUG 2020

ESTIMATE

Estimate No. : b1 55852

Page No. : 1 of 5

Date Estimated : 25/08/2020 *INTHERAN*

Prepared By : *Brandon Chan Eng Meng*

- ESTIMATE REPAIR FOR -

Teo Wee Beng Dennis
33 Jalan Tupai

Singapore 249161

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLE3620Y	WBA2F120X0V758213	19/07/2016	218iA/2	0

DESCRIPTION

VALUE

To replace rear RH fender, attachments and repair rear bumper.

5100 5,950.00

To painting rear RH fender, rear bumper, roof frame and tail panel.

2808 3,114.00

To remove and install rear hat-tray, rear seat, carpet and roof top lining to facilitate repairs.

742 875.00

To replace rear windscreen glass.

676.00

To conduct water leak tests.

75.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

To carry out body cavity preservation.
(For cut panel).

451 531.00

To replace tyre and wheel rim including balancing. (1x).

80 94.00

To check steering geometry and conduct wheel alignment according to BMW specification (1X)

451 531.00

Sundries

? 150.00

Total Labour 1: 12,171.00

DESCRIPTION

QTY

PRIC

VALUE

BLIND PLUG <i>? x 1m</i>	1	1.05	1.05
PLASTIC NUT FOR COARSE THREADED PIN <i>? x 1m</i>	6	0.85	5.10
ALLOY RIM 7.5JX17 STAR SPOKE 379 <i>set</i>	1	921.70	921.70
REAR RH SIDE PANEL <i>set</i>	1	1,333.95	1,333.95
RH REINFORCEMENT PLATE SILL <i>? x 1m</i>	1	54.20	54.20
RH B PILLAR REINFORCEMENT PLATE <i>? x 1m</i>	1	53.75	53.75

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559M GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Page No. : 2 of 5

Estimate No. : b1 55852
Date Estimated : 25/08/2020
Prepared By : Brandon Chan Eng Meng

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLE3620Y	WBA2F120X0V758213	19/07/2016	218iA/2	0

DESCRIPTION	QTY	PRIC	VALUE
RH C PILLAR REINFORCEMENT PLATE <i>new</i>	1	69.70	69.70
PLASTIC NUT <i>new</i>	4	0.85	3.40
BUMP STOP <i>new</i>	10	3.75	37.50
REAR WINDOW <i>new photo? new</i>	1	626.30	626.30
Side window, <i>new photo? new</i>	1	293.05	293.05
RH B COLUMN COVERING <i>new</i>	1	71.40	71.40
SET ADHESIVE PADS FOR ACE 2.0 <i>new new</i>	1	43.65	43.65
CAVITY PROTECTION WAX REMOVER 500ML <i>new new</i>	1	18.45	18.45
BLIND RIVET AVIBVLB <i>new</i>	14 <i>20</i>	0.55	11.00 <i>7.70</i>
SCREW (SF PLUS M5X15) <i>new new</i>	3	0.55	1.65
(DG/SL) BODY ADHESIVE K5B (195ML) <i>new</i>	1	331.80	331.80
PUNCH RIVET N5 <i>new</i>	18 <i>19</i>	0.55	10.45 <i>9.90</i>
(DG) BODYWORK ADHESIVE K5A (50ML) <i>new</i>	1	114.45	114.45
(DG) CLEANER R1 (100ML) <i>new</i>	8 <i>1</i>	26.15	26.15 <i>78.45</i>
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) <i>new</i>	8 <i>2</i>	131.55	263.10 <i>394.65</i>
PUNCH RIVET N4 <i>new</i>	8 <i>20</i>	0.55	11.00 <i>4.95</i>
(DG/SL) ADHESIVE PRIMER VP 206 (30ML) <i>new</i>	1	27.85	27.85
(S/L) SEAM SEAL 300ML <i>new</i>	1	33.80	33.80

Total Parts : 4,538.40

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
Date & Time 07/09/2020 @ 1500 Excess S\$ _____
Surveyor's Name RASUE Sign _____
Surveyor's Tel 90010068 Authorised Yes / No _____
Authorised Date _____ Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____
Surveyor's E-mail _____
No. of Working Days Recommend 10 days + 2 days
= 12 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____



Labour 1	:	12,171.00
Parts	:	4,538.40
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,169.66
Grand Total	:	17,879.06

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 55852**
Date Estimated : **25/08/2020**
Prepared By : **Brandon Chan Eng Meng**

- ESTIMATE REPAIR FOR -

Teo Wee Beng Dennis
33 Jalan Tupai

Singapore 249161

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLE3620Y	WBA2F120X0V7582	19/07/2016	218iA/2	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
(DG) CLEANER R1 (100ML) in estimatex	26.15	1.00	0.00	26.15
# SNAP LOCK COUPLING nec	3.80	1.00	0.00	3.80
# COVER POT cra	76.50	1.00	0.00	76.50
# HOOK AND LOOP FASTENER nec	2.85	3.00	0.00	8.55
# RR RH SIDE WINDOW (BASIS) nec	293.05	1.00	0.00	293.05
# TYPE IDENTIFICATION PLATE (CODED) nec	29.45	1.00	0.00	29.45
# LABEL TIRE PRESSURE nec	24.50	1.00	0.00	24.50
# (DG) CLEANER R1 (100ML) nec	26.15	1.00	0.00	26.15

Total Labour :

Total Parts :

Total Labour & Parts :

488.15

488.15