

GREEN FOREST AUTOMOBILE PTE LTD

8 Kaki Bukit Avenue 4, #05-25 Premier @ Kaki Bukit Singapore 415875

CARRO LEASING PTE LTD
8 KAKI BUKIT AVE 4
05-25 PREMIER @ KB
Singapore 415875

TPALG.
Cecilia.

ZWR800343915

28th AUGUST 2020

Accident date: 27th AUGUST 2020
Estimated repair cost for vehicle no: SML5549J (MAY 2019)

S/n	Qty	Items	U/price	Amount	
				\$1,450.00	1225
1	1	Front door-RH Distorted		\$155.20	X
2	1	Front door handle -RH		\$121.25	X
3	1	Front door top hinge-RH		\$121.25	X
4	1	Front door lower hinge-RH		\$585.20	X
5	1	Front door inner gear-RH		\$755.20	X
6	1	Front door inner motor-RH		\$325.20	X
7	1	Front door inner lock-RH		\$171.80	X
8	1	Front door top moulding-RH		\$955.00	X
9	1	Front door inner trim board -RH		\$182.25	X
10	1	Front door inner rubber		\$851.20	X
11	1	Front door pillar-RH		\$685.20	X
12	1	Front rocker panel skirting Deformed		\$1,885.20	1680
13	1	Rear door-RH Distorted		\$155.20	X
14	1	Rear door handle -RH		\$131.75	X
15	1	Rear door top hinges-RH		\$131.75	X
16	1	Rear door lower hinges-RH		\$388.20	X
17	1	Rear door inner lock-RH		\$1,050.20	628
18	1	Rear door inner trim board-RH		\$688.20	235
19	1	Rear door inner gear-RH		\$822.10	X
20	1	Rear door inner gear motor-RH		\$182.55	X
21	1	Rear door inner sponge-RH		\$181.10	X
22	1	Rear door inner rubber-RH		\$172.25	X
23	1	Rear door top moulding-RH		\$2,150.00	X
24	1	rear R/H fender Repair		\$165.00	X
25	1	Rear fender outer garnish -RH		\$675.00	X
26	1	Rear R/H fender inner trim board		\$1,250.00	X
27	1	rear fender inner panel- RH		\$650.00	450(SW)
28	1	Rear RIM -RH		\$400.00	200(SW)
29	1	Rear tyre -RH		2648	X
30	1	Rear Axle Bent		\$388.20	X
31	1	Rear wheel Hub			X
32	1			\$552.10	X
33	1	Rear shock absorber-RH		\$1,688.00	1025
34	1	Rear Bumper Deformed		\$350.00	X
35	1	Rear Bumper Reverse Sensor		\$230.00	75
36	2	Rear Bumper Side Bracket	\$115.00	\$68.00	X
37	1	Rear Bumper Side Reflector-RH			X
Subtotal :-				\$21,286.75	

961565 S.N: 650

721173

Labour charges

To Remove & refix rear fender glass

\$120.00 X

Gum

\$50.00 X

To remove & refix rear & front RH door

~~\$400.00~~ 160

To remove & re-fix cushion

~~\$120.00~~ 60

To remove & re-fix rear undercarriage

\$280.00 ✓

To check wheel alignment computer

~~\$120.00~~ 80

To Check Wiring System

~~\$60.00~~ 30

Tuff Kote

~~\$120.00~~ 60

Towing charges

\$100.00 X

Panel beating

~~\$1,600.00~~ 800

Spray painting

\$1,600.00 1000

Subtotal :- \$4,570.00

Total :- \$25,856.75

total: 10331.73

L/S: 8.2k.

08 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: