

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK

Claim Type: Third Party

Accident Date: 26/08/2020

TP Veh Reg No: SJN9699H

Estimate No: ES2090646/AMK

Date: 28 Aug 2020

Policy No: 5092780487-03 PREMIUM

Veh Reg No: SLQ9210U

Make/Model: PEUGEOT 508 ALLURE 1.6A

Chassis No: VF38DBH2TGL046388

Engine No: 10JBHX3021619

Reg. Date: 27/07/2017

Estimate Repair Cost to Vehicle No :SLQ9210U

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 REAR BUMPER	1,080.00	1 PC	1,080.00	✓
2 REAR BUMPER REINFORCEMENT	390.00	1 PC	390.00	✓
3 REAR BUMPER ABSORBER (PRICE PENDING)	0.00	1 PC	0.00	✓
4 REAR BUMPER SIDE RETAINER (PRICE PENDING)	0.00	1 SET	0.00	X
5 REAR BUMPER BRACKET (PRICE PENDING)	0.00	2 PC	0.00	✓
6 REAR BUMPER LOWER BUMPER	440.00	1 PC	440.00	✓
7 REAR BUMPER SIDE CHROME MOULDING (PRICE PENDING)	0.00	2 PC	0.00	✓
8 REAR BUMPER NO PLATE LAMP (PRICE PENDING)	0.00	2 PC	0.00	✓
9 REAR BUMPER REVERSE CAMERA (PRICE PENDING)	0.00	1 PC	0.00	✓
10 REAR BUMPER INNER CENTRE PDC SENSOR (PRICE PENDING)	0.00	2 PC	0.00	✓
11 TAILLAMP (PRICE PENDING)	0.00	2 PC	0.00	✓
12 REAR BOOT	1,220.00	1 PC	1,220.00	✓
13 REAR BOOT INNER LOCK	96.00	1 PC	96.00	✓
14 REAR BOOT INNER RUBBER (PRICE PENDING)	0.00	1 PC	0.00	✓
15 REAR BOOT CHROME MOULDING (PRICE PENDING)	0.00	1 PC	0.00	✓
16 REAR BOOT OUTER GARNISH (PRICE PENDING)	0.00	1 PC	0.00	✓
17 REAR BOOT LOGO & EMBLEM 'PEUGEOT'	78.00	1 PC	78.00	✓
18 REAR BOOT STOPPER	33.00	2 PC	66.00	✓
19 REAR END PANEL (PRICE PENDING)	0.00	1 PC	0.00	✓
20 REAR END PANEL INNER TOP GARNISH (PRICE PENDING)	0.00	1 PC	0.00	✓
			3,370.00	
			Less 10%	3,033.00
Special Net				
21 REAR END PANEL SEALANT	40.00	1 PC	40.00	3050
22 REAR NUMBER PLATE	35.00	1 PC	35.00	✓
			75.00	75.00
Labour				
23 REMOVE & REFIX REAR BUMPER, LOWER BUMPER & ATTACHMENTS, PARKING SENSORS, REAR BOOT & ATTACHMENTS, TAILLAMPS; TO CUT, WELD & RENEW REAR END PANEL; KNOCKING & REPAIR REAR SPARE TYRE PANEL & REALIGN THE SAME	900.00	1 LA	900.00	800
24 PUTTY & RESPRAY REAR BUMPER, PARKING SENSORS, REAR BOOT & OUTER GARNISH, REAR END PANEL, REAR SPARE TYRE PANEL, FENDERS & ALL AFFECTED AREAS	900.00	1 LA	900.00	800

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO.201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK
Claim Type: Third Party
Accident Date: 26/08/2020
TP Veh Reg No: SJN9699H

Estimate No: ES2090646/AMK
Date: 28 Aug 2020
Policy No: 5092780487-03 PREMIUM
Veh Reg No: SLQ9210U
Make/Model: PEUGEOT 508 ALLURE
1.6A
Chassis No: VF38DBH2TGL046388
Engine No: 10JBHX3021619
Reg. Date: 27/07/2017

Estimate Repair Cost to Vehicle No :SLQ9210U

Description	U/Price	Quantity	List Price	Amount
25 REMOVE & REFIX PARKING SENSORS,CHECK & RESET SYSTEM	80.00	1 LA	SS 80.00	SS 601
26 REMOVE & REFIX REVERSE CAMERA,CHECK & REALIGN THE SAME	60.00	1 LA	60.00	✓
27 RUSTPROOFING	80.00	1 LA	80.00	601
			2,020.00	2,020.00
			Total	SS 5,128.00
			Add GST @ 7%	358.96
			Total Amount Payable	SS 5,486.96

* SURVEY VEHICLE AT ANG MO KIO WORKSHOP

For Cheng Hoe Motor Pte Ltd

Dorlyn LA

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: