

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 7373 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLL 4264 Z

S/N	Nature of Jobs	Estimated Charges
1	To remove, check and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy. S/N \$	280.00 ✓ \$280.00
2	To remove and transfer lhs headlight control unit and power module. S/N \$	350.00 250 \$250.00
3	To dismantle and reinstall lhs front door panel trim. To remove and reinstall lhs wing mirror assy. S/N \$	350.00 280 \$280.00
4	To remove and renew aircon condenser, additional radiator and radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas. S/N \$	1,200.00 ✓ \$1200.00
5	To dismantle and renew front bumper, lhs front fender, bonnet, and lhs headlight. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed. \$	4,900.00 1500 (Without lock carrier) 2750 (With lock carrier) \$2750
6	To respray front bumper, lhs front fender, bonnet and lhs front door. ✓ \$	4,000.00 2200 \$2200
7	To carry out diagnostic check. S/N \$	192.00 ✓ \$192.00
TOTAL LABOUR CHARGES		: \$ 11,272.00

Yvonne

2446744

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLL 4264 Z

S/N	Parts Description	Damage Parts & Prices		
		S/Nett	Remarks	
1	FRONT BUMPER <i>Distorted</i>	\$ 1,842.00	✓	\$1473-60
2	FRONT BUMPER FIXING PARTS	\$ 185.00	+	
3	FRONT BUMPER GUIDE SECTION - LH <i>new</i>	\$ 38.00	+	
4	FRONT BUMPER GRILLE - CENTRE <i>new</i>	\$ 159.00	+	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	\$ 293.00	+	
6	FRONT BUMPER CLOSING ELEMENT - LH <i>new</i>	\$ 293.00	+	
7	RADIATOR GRILLE <i>crushed</i>	\$ 1,406.00	✓	\$1124-80
8	RADIATOR GRILLE CLOSING ELEMENT <i>crushed</i>	\$ 189.00	✓	\$150-80
9	RADIATOR GRILLE INNER COVER - LH / RH UPPER <i>new 2</i>	TBC	+	
10	FRONT BUMPER AIR GUIDE GRILLE - LH <i>new</i>	\$ 186.00	+	
11	AIRCON STICKER <i>new</i>	NEC \$ 8.00	✓	\$5-68
12	CAUTION SIGN STICKER <i>new</i>	NEC \$ 14.00	✓	\$10-80
13	FRONT BUMPER SIDE REINFORCEMENT BEAM <i>Bent</i>	\$ 715.00	✓	\$571-60
14	FRONT BUMPER FOAM FILLER PIECE <i>crushed</i>	\$ 187.00	✓	\$149-60
15	FRONT BUMPER CARRIER COVER <i>crushed</i>	\$ 121.00	✓	\$96-40
16	FRONT BUMPER CARRIER TOP COVER <i>crushed</i>	\$ 121.00	✓	\$96-40
17	SIGNAL HORN - LH HIGH TONE <i>new</i>	\$ 197.00	+	
18	FRONT FENDER - LH <i>crushed</i>	\$ 841.00	✓	\$672-80
19	FRONT FENDER ATTACHMENT PARTS <i>new</i>	\$ 71.00	+	
20	FRONT FENDER BRACKET - LH <i>new</i>	\$ 27.00	+	
SUB TOTAL SPARE PARTS CHARGES		\$ 6,893.00		

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLL 4264 Z

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
21	FRONT FENDER BRACKET - LH <i>Best</i>	\$ 47.00	✓ \$37-28
22	FRONT FENDER BRACE <i>Not new</i>	\$ 95.00	✗
23	FRONT FENDER CLOSING ELEMENT - LH <i>Not new</i>	\$ 61.00	✗
24	WHEEL HOUSING LINER - LH <i>new</i>	\$ 167.00	+
25	WHEEL HOUSING LINER ATTACHMENT PARTS <i>all in</i>	\$ 57.00	+
26	BONNET <i>Dented</i>	\$ 2,709.00	✓ \$2167-20
27	BONNET ATTACHMENT PARTS <i>Not new</i>	\$ 163.00	✗
28	BONNET LID HINGE - LH / RH <i>Not new</i>	2 \$ 122.00	✗
29	FRONT FENDER TOP INNER COVER - LH <i>new</i>	\$ 41.00	✓ \$32-16
30	PLENUM CHAMBER COVER <i>new cut</i>	\$ 177.00	✓ \$141-60
31	BONNET GAS FILLED STRUT <i>new</i>	\$ 118.00	+
32	BONNET EDGE PROTECTION - FRONT <i>new</i>	\$ 28.00	✓ \$21-84
33	BONNET CATCH HOOK <i>Not new</i>	\$ 89.00	✗
34	BONNET STRIKER - LH / RH <i>Not new</i>	2 \$ 218.00	✗
35	BONNET CATCH HOOK <i>Not new</i>	\$ 63.00	✗
36	BONNET LID LOCK <i>2nd LH</i>	2 \$ 423.00	212.50 \$169
37	BONNET BOWDEN CABLE - CENTRE <i>new Dented</i>	\$ 57.00	✓ \$45-52
38	BONNET SOUND ABSORBER <i>new Not new</i>	\$ 217.00	✗
39	LED HEADLIGHT - LH <i>cracked</i>	\$ 5,455.00	✓ \$4364-0
40	MAIN LIGHT ELECTRONICS POWER MODULE - LH <i>Not new</i>	\$ 749.00	+
SUB TOTAL SPARE PARTS CHARGES		: <u>\$ 11,056.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLL 4264 Z

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
41	LED WITH HEAT SINK - LH <i>Not</i>	\$ 725.00	+
42	LIGHT CONTROL SYSTEM CONTROL UNIT <i>Not</i>	\$ 551.00	+
43	HEADLIGHT HOSE - LH <i>Not</i>	\$ 40.00	+
44	HEADLAMP HOUSING REPAIR KIT <i>Not</i>	\$ 130.00	+
45	LIFT CYLINDER <i>Not</i>	\$ 141.00	+
46	LIFT CYLINDER HOSE <i>Not</i>	\$ 67.00	+
47	WASH WATER RESERVOIR <i>Not</i>	\$ 202.00	+
48	LOCK CARRIER <i>Not</i>	\$ 719.00	+
49	AIRCON CONDENSER <i>Not</i>	\$ 545.00	+
50	REFRIGERANT LINE <i>Not</i>	\$ 476.00	+
51	REFRIGERANT LINE <i>Not</i>	\$ 619.00	+
52	TEMPERATURE SENSOR BRACKET <i>Not</i>	\$ 18.00	+
53	RADIATOR <i>Not</i>	\$ 941.00	+
54	ADDITIONAL RADIATOR <i>Not</i>	\$ 859.00	+
55	READY MIX COOLANT <i>Not</i>	\$ 91.00	+
56	RADIATOR FAN RING <i>Not</i>	\$ 184.00	+
57	RADIATOR AIR GUIDE - LH <i>Not</i>	\$ 24.00	+
58	RADIATOR AIR GUIDE - UPPER CENTRE <i>Not</i>	\$ 12.00	+
59	AIR INTAKE AIR GUIDE <i>Not</i>	\$ 54.00	+
60	AIR INTAKE AIR DUCT COVER <i>Not</i>	\$ 28.00	+
61	AIR INTAKE AIR GUIDE <i>Not</i>	\$ 19.00	+
62	FRONT WINDOW SLOT SEAL WITH TRIM STRIP - LH <i>Not</i>	\$ 266.00	+
63	FRONT NO PLATE <i>Not</i>	\$ 60.00	+
64	SUNDRIES <i>Not</i>	\$ 350.00	+
TOTAL SPARE PARTS CHARGES		: \$25,070.00	
TOTAL LABOUR CHARGES		: \$11,272.00	
GRAND TOTAL		: \$36,342.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Resurveyed
Adrian L
03/09/20

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lj
Surveyed Date : 28/08/20
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, ~~06~~ Days. (Without lock carner)
09 Days (With lock carner)
SS

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

