

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 47098

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0606/2020/NS
Date : 27-Aug-20

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Cai Zhibing
Address : 328 Sembawang Crescent
#15-08
Singapore 750328
Telephone : HP +65 81880201
Type of Claim : Own Damage Claim
Policy No. : 2100502195-03
Vehicle No : **SLL 4264 Z**
Model Code : Audi A3 sportsback 1.0 TFSI
Model / Year : Feb-17
Engine No : CHZ 150584
Chassis No : WAUZZZ8V4Ha050159
Mileage : 74355km
Date In : 27-Aug-20
Estimated By : Johnny Boo / Allan Wu
Accident Date : 27-Aug-20
Place of Accident : Along CTE

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLL 4264 Z

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove, check and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$	280.00 \$	280.00
2	To remove and transfer lhs headlight control unit and power module.	S/N \$	350.00 \$	250.00
3	To dismantle and reinstall lhs front door panel trim. To remove and reinstall lhs wing mirror assy.	S/N \$	350.00 \$	280.00
4	To remove and renew aircon condenser, radiator and additional radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$	1,200.00 \$	1,200.00
5	To dismantle and renew front bumper, lhs front fender, bonnet, and lhs headlight. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$	4,900.00 \$	2,750.00
6	To respray front bumper, lhs front fender, bonnet and lhs front door.	\$	4,000.00 \$	2,200.00
7	Supplementary	\$	350.00 \$	250.00
8	To carry out diagnostic check.	S/N \$	192.00 \$	192.00
TOTAL LABOUR CHARGES		:	\$ 11,622.00 \$	7,402.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLL 4264 Z

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER	\$ 1,842.00	\$ 1,473.60
2	FRONT BUMPER FIXING PARTS	\$ 185.00	
3	FRONT BUMPER GUIDE SECTION - LH	\$ 38.00	
4	FRONT BUMPER GRILLE - CENTRE	\$ 159.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 293.00	
6	FRONT BUMPER CLOSING ELEMENT - LH	\$ 293.00	
7	RADIATOR GRILLE	\$ 1,406.00	\$ 1,124.80
8	RADIATOR GRILLE CLOSING ELEMENT	\$ 189.00	\$ 150.80
9	RADIATOR GRILLE INNER COVER - LH / RH UPPER	2 TBC	
10	FRONT BUMPER AIR GUIDE GRILLE - LH	\$ 186.00	
11	AIRCON STICKER	NEC \$ 8.00	\$ 5.68
12	CAUTION SIGN STICKER	NEC \$ 14.00	\$ 10.80
13	FRONT BUMPER SIDE REINFORCEMENT BEAM	\$ 715.00	\$ 571.60
14	FRONT BUMPER FOAM FILLER PIECE	\$ 187.00	\$ 149.60
15	FRONT BUMPER CARRIER COVER	\$ 121.00	\$ 96.40
16	FRONT BUMPER CARRIER TOP COVER	\$ 121.00	\$ 96.40
17	SIGNAL HORN - LH HIGH TONE	\$ 197.00	
18	FRONT FENDER - LH	\$ 841.00	\$ 672.80
19	FRONT FENDER ATTACHMENT PARTS	\$ 71.00	
20	FRONT FENDER BRACKET - LH	\$ 27.00	
SUB TOTAL SPARE PARTS CHARGES		\$ 6,893.00	\$ 4,352.48

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLL 4264 Z

S/N	Parts Description	c/f	Damage Parts & Prices	
			S/Nett	Remarks
				\$ 4,352.48
21	FRONT FENDER BRACKET - LH		\$ 47.00	\$ 37.28
22	FRONT FENDER BRACE		\$ 95.00	
23	FRONT FENDER CLOSING ELEMENT - LH		\$ 61.00	
24	WHEEL HOUSING LINER - LH		\$ 167.00	
25	WHEEL HOUSING LINER ATTACHMENT PARTS		\$ 57.00	
26	BONNET		\$ 2,709.00	\$ 2,167.20
27	BONNET ATTACHMENT PARTS		\$ 163.00	
28	BONNET LID HINGE - LH / RH	2	\$ 122.00	
29	FRONT FENDER TOP INNER COVER - LH		\$ 41.00	\$ 32.16
30	PLENUM CHAMBER COVER		\$ 177.00	\$ 141.60
31	BONNET GAS FILLED STRUT		\$ 118.00	
32	BONNET EDGE PROTECTION - FRONT		\$ 28.00	\$ 21.84
33	BONNET CATCH HOOK		\$ 89.00	
34	BONNET STRIKER - LH / RH	2	\$ 218.00	
35	BONNET CATCH HOOK		\$ 63.00	
36	BONNET LID LOCK	2	\$ 423.00	\$ 169.20
37	BONNET BOWDEN CABLE - CENTRE		\$ 57.00	\$ 45.52
38	BONNET SOUND ABSORBER		\$ 217.00	
39	LED HEADLIGHT - LH		\$ 5,455.00	\$ 4,364.00
40	MAIN LIGHT ELECTRONICS POWER MODULE - LH		\$ 749.00	
SUB TOTAL SPARE PARTS CHARGES			\$ 11,056.00	\$ 11,331.28

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLL 4264 Z

S/N	Parts Description	c/f	Damage Parts & Prices	
			S/Nett	Remarks
				\$ 11,331.28
41	LED WITH HEAT SINK - LH		\$ 725.00	
42	LIGHT CONTROL SYSTEM CONTROL UNIT		\$ 551.00	
43	HEADLIGHT HOSE - LH		\$ 40.00	
44	HEADLAMP HOUSING REPAIR KIT		\$ 130.00	
45	LIFT CYLINDER		\$ 141.00	
46	LIFT CYLINDER HOSE		\$ 67.00	
47	WASH WATER RESERVOIR		\$ 202.00	\$ 161.20
48	LOCK CARRIER		\$ 719.00	\$ 575.20
49	AIRCON CONDENSER		\$ 545.00	\$ 436.00
50	REFRIGERANT LINE		\$ 476.00	
51	REFRIGERANT LINE		\$ 619.00	
52	TEMPERATURE SENSOR BRACKET		\$ 18.00	
53	RADIATOR		\$ 941.00	
54	ADDITIONAL RADIATOR		\$ 859.00	
55	READY MIX COOLANT		\$ 91.00	\$ 72.32
56	RADIATOR FAN RING		\$ 184.00	
57	RADIATOR AIR GUIDE - LH		\$ 24.00	\$ 19.20
58	RADIATOR AIR GUIDE - UPPER CENTRE		\$ 12.00	
59	AIR INTAKE AIR GUIDE		\$ 54.00	
60	AIR INTAKE AIR DUCT COVER		\$ 28.00	
61	AIR INTAKE AIR GUIDE		\$ 19.00	
62	FRONT WINDOW SLOT SEAL WITH TRIM STRIP - LH		\$ 266.00	
63	FRONT NO PLATE	S/N	\$ 60.00	\$ 60.00
64	SUPPLEMENTARY		\$ 5,495.00	\$ 4,395.44
65	SUNDRIES		\$ 350.00	\$ 14.80
TOTAL SPARE PARTS CHARGES			\$ 30,565.00	\$ 17,065.44
TOTAL LABOUR CHARGES			\$ 11,622.00	\$ 7,402.00
GRAND TOTAL			\$ 42,187.00	\$ 24,467.44

All charges are not inclusive of GST.
Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.
BL-22/10/20

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0606/2020/NS 02-Sep-20 Glory Tan 1 OF 1 SLL 4264 Z Audi A3 sportsback 1.0 TFSI
Quantity	Description	Unit Price	Amount
Parts			
1	Headlight RHS	\$ 5,455.00	\$ 4,364.00
2	Radiator bracket LHS	\$ 40.00	\$ 31.44
TOTAL		\$ 5,495.00	\$ 4,395.44
Labours			
1	To transfer rhs headlight control unit and power module.	s/n \$ 350.00	\$ 250.00
TOTAL		\$ 350.00	\$ 250.00

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant