

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

Lee / Admin

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-08 MIDVIEW CITY
 SINGAPORE 573960

Contact : 66550005-GRAB 83388369

TP Budget Direct
 Veron

ESTIMATE

Repair Code : CLM16395

Date in : 27/08/2020

Vehicle Num. : SLU6408R

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31265243/LEB5965264

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT LH DOOR <i>Dented</i>	1	1080.50	✓ 1,080.50
FRONT LH DOOR FRAME BLACK TAPE STICKER <i>x new</i>	1	33.00	✓ 33.00
FRONT LH DOOR INNER PLASTIC SEAL COVER <i>x new</i>	1	35.50	X 35.50
FRONT LH DOOR LOWER HINGE <i>x new</i>	1	38.50	X 38.50
FRONT LH DOOR LOWER WEATHER STRIP SEAL <i>new</i>	1	28.00	✓ 28.00
FRONT LH DOOR SIDE MIRROR COVER <i>x new</i>	1	80.00	X 80.00
FRONT LH DOOR VERTICAL WEATHER STRIP SEAL <i>cut</i>	1	20.00	✓ 20.00
FRONT LH DOOR WEATHER STRIP SEAL <i>x new</i>	1	71.00	X 71.00
FRONT LH FENDER <i>Repair</i>	1	580.00	X 580.00
FRONT LH FENDER 'HYBRID' EMBLEM <i>new</i>	1	95.00	✓ 95.00
FRONT LH FENDER ARCH GARNISH <i>cut</i>	1	220.00	✓ 220.00
LH SIDE SKIRT GARNISH <i>Debond</i>	1	377.50	✓ 377.50
REAR LH DOOR <i>Dented</i>	1	930.60	✓ 930.60
REAR LH DOOR CENTER WEATHER STRIP SEAL <i>new new</i>	1	36.50	X 36.50
REAR LH DOOR FRAME BLACK TAPE STICKER <i>x new</i>	1	33.00	✓ 33.00
REAR LH DOOR INNER PLASTIC SEAL COVER <i>x new</i>	1	35.50	+ 35.50
REAR LH DOOR LOWER HINGE <i>x new</i>	1	38.50	X 38.50
REAR LH DOOR LOWER WEATHER STRIP SEAL <i>new</i>	1	14.90	✓ 14.90

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-08 MIDVIEW CITY
 SINGAPORE 573960

Contact : 66550005-GRAB 83388369

ESTIMATE

Repair Code : CLM16395

Date in : 27/08/2020

Vehicle Num. : SLU6408R

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31265243/LEB5965264

REAR LH DOOR TRANSPARENT STICKER <i>new</i>	1	35.00	✓	35.00
REAR LH DOOR WEATHER STRIP SEAL <i>new</i>	1	18.50	✓	18.50
REAR LH FENDER ARCH GARNISH <i>new</i>	1	195.00	✓	195.00
REAR LH SPORT RIM <i>new</i>	1	813.00	500(SN)	813.00
REAR LH WHEEL BEARING HUB <i>engd.</i>	1	263.50	✓	263.50
Subtotal before discount				5,073.00
Percentage discount 20%				1,014.60
Sub-total 1				4,058.40
FRONT LH DOOR INNER TRIM BOARD CLIPS - SET <i>new</i>	1	50.00	✗	50.00
FRONT LH FENDER ARCH GARNISH CLIPS - SET <i>new</i>	1	30.00	✓	30.00
FRONT LH FENDER INNER SHIELD CLIPS - SET <i>new</i>	1	50.00	✗	50.00
LH SIDE SKIRT GARNISH CLIPS - SET <i>new</i>	1	50.00	30	50.00
REAR LH DOOR INNER TRIM BOARD CLIPS - SET <i>new</i>	1	50.00	✗	50.00
REAR LH FENDER ARCH GARNISH CLIPS - SET <i>new</i>	1	30.00	✓	30.00
REAR LH TYRE <i>Not new</i>	1	300.00	✗	300.00
Subtotal before discount				560.00
Percentage discount 0%				0.00
Sub-total 2				560.00
Parts-total				4,618.40

*** This is a computer-generated document which requires no signature.***



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

GRAB RENTALS PTE LTD

18 SIN MING LANE #01-08 MIDVIEW CITY

SINGAPORE 573960

Contact : 66550005-GRAB 83388369

ESTIMATE

Repair Code : CLM16395

Date in : 27/08/2020

Vehicle Num. : SLU6408R

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31265243/LEB5965264

LABOUR

To remove, reinstall electrical wiring harness, check lighting. (to FR)

To remove, reinstall rear suspension and undercarriage part. (to FR)

To road test driving, check and resetting wheel alignments system.

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

30 50.00

50 200.00

80 100.00

X 100.00

160 200.00

800 1,300.00

600 900.00

50 100.00

1770

Labour Total

2,950.00

Parts & Labour Total

7,568.40

*** This is a computer-generated document which requires no signature.***

page 3

total: 5005.60

4/s: 4K.

0.5 Days

4k

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: