



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS3/LPC20006818/R1vf3e2-1

300 BEACH ROAD  
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 15-09-2020



Code : LPC2

#### 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                      |                |            |
|--------------|----------------------|----------------|------------|
| Insured Veh. | YN 5581L             | Veh. Inspected | GX 6548M   |
| Policy No.   |                      | Coverage (\$)  | 0.00       |
| Claim No.    | 19/20/20/VC05/023404 | Excess (\$)    | 0.00       |
| Assign From  | ONG LI LI            | Assign Date    | 30/06/2020 |

#### 2. Vehicle Particulars & Condition

|              |                     |              |          |
|--------------|---------------------|--------------|----------|
| Make & Model | TOYOTA LITEACE 2.2M | c.c          | 2184     |
| Engine No.   | HIDDEN              | Year of Reg. | 2004     |
| Chassis No.  | CR425009802         | Colour       | GREY     |
| Odometer     | 375842              | Steering     | IN ORDER |
| Brakes       | IN ORDER            | Modification | NIL      |
| General      | FAIR                |              |          |

#### 3. Conditions of Tyres

|                | Size     | Make   | Balance |
|----------------|----------|--------|---------|
| R/H Front Tyre | 165 R13C | A-PLUS | 5 mm    |
| L/H Front Tyre | 165 R13C | A-PLUS | 5 mm    |
| R/H Rear Tyre  | 165 R13C | A-PLUS | 5 mm    |
| L/H Rear Tyre  | 165 R13C | A-PLUS | 5 mm    |

#### 4. Description of Damages

|                                                                             |
|-----------------------------------------------------------------------------|
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.<br>DAMAGES SEE DETAILS. |
|-----------------------------------------------------------------------------|

#### 5. General Information

|                |                                                                                            |                 |            |
|----------------|--------------------------------------------------------------------------------------------|-----------------|------------|
| Accident Date  | 15/06/2020                                                                                 | Inspection Date | 01/07/2020 |
| Survey held at | MILLION AUTO SERVICE<br>4 PENJURU PLACE<br>#01-12 2.8 PENJURU TECH HUP<br>SINGAPORE 608782 |                 |            |

#### 5a. Remarks

|                                                                                                                                        |
|----------------------------------------------------------------------------------------------------------------------------------------|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|----------------------------------------------------------------------------------------------------------------------------------------|

#### 5b. Estimate Days of Repair

|                                     |                |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 4 Working Days |
|-------------------------------------|----------------|