

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Pauline Tham

Date: 02 Sep 2020

## **Preliminary Advice**

Insured Vehicle No	: SMR9650R	Accident Date	: 27/08/2020
TP Vehicle No	: SKQ6411M	Assignment Date	: 28/08/2020
Make	: MERCEDES-BENZ C180	Est. Duration of Repair	: 5
Date of Inspection	: 28/08/2020		
Inspection At	: JOO HAK KEE AUTO PTE LTD (HQ) BLK 3007 UBI ROAD 1, #01-406 SINGAPORE 408701		

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,207.60
Revised Amount	:S\$	10,114.10
Check Items (Estimated)	:S\$	373.50
Total	:S\$	10,487.60

Lump Sum Repair	:S\$
-----------------	------

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments : survey on wp