



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring
#08-1339 Singapore 470130
Tel: 9450 7920
zoomautowerks@gmail.com

Car Number: SMD4099P

Model : Toyota Noah

Damaged Area: (Rear Right Portion)

Repairer Estimation Cost of Repair :

Supplementary may be included during the cost of repair :

not Authorized
Lulu
31/8/20
d/s \$5000
Take photo after repair.
6 days.

Parts / Material :

1	Rear Bumper	Dis	\$	1,105.20	✓
2	Rear Bumper Side Retainer @ 112.20	015 Bent	\$	224.40	1PC
3	Rear Bumper Bracket @ 95.60	11	\$	191.20	X
4	Rear Bumper Reflector RH	11	\$	486.70	X
5	Rear Bumper Side RH	705 NN	\$	320.40	X
6	Rear Bumper Side RH Clips	11	\$	30.00	X
7	Rear Taillamp RH	11	\$	980.50	X
8	Rear Bumper Bumper Clips (SET)	new	\$	60.00	✓
9	Rear Tailgate	11		Repair	X
10	Rear Tailgate Emblem	11	\$	98.20	X
11	Rear Sliding Door RH	705 Bent		1,299.10	✓
12	Rear Fender RH	50650	\$	1,380.40	✓
13	Rear Fender Inner Shield LH	11	\$	254.30	X
14	Rear Fender Inner Shield Clips (SET)	11	\$	60.00	X
15	Rear Fender Quarter Glass Inner Seal	new 115.00	\$	420.30	✓
16	Rear Fuel Tank Lid	11	\$	265.20	X
17	Rear Suspension RH	11	\$	385.90	X
18	Rear Hub Bearing	Dange	\$	485.60	✓

Parts : \$
Less Parts 25% : \$
Total Parts : \$

4557.50
25%
3418.12

Special Net Items :

Brake Oil	11	\$	75.00	X
Rear Tyre RH	300	\$	380.00	X
Rear Rim RH	705 Bent	\$	850.00	450
Total S/N Parts :		\$	1,305.00	

Labour :

To Remove, Repair & Renew Affected Accident Areas	\$	1,400.00	1000
To Putty, Spray Paint on Affected Accident Areas	\$	1,200.00	800
To Check & Re-Connect all electrical wiring	\$	50.00	20
To Conduct Wheel Alignment	\$	250.00	60
To Renew, Balance & Replace Rear LH Tyre	\$	11 80.00	X
To Conduct Diagnostic & Reset Engine Mangement	\$	450.00	50
To Remove & Install Rear Interior Upholstery	\$	120.00	100
To Remove & Install Head Linning to Facilitate Repairs	\$	11 200.00	X
To Remove & Install Rear RH Quarter Glass	\$	180.00	100

To Remove & Install Rear RH Undercarriage
To Rust Proof Affected Areas

\$ 250.00 / 20
\$ 150.00 60

Total Labour : \$ 4,330.00

TOTAL PARTS : \$
TOTAL SPECIAL NET ITEM : \$
TOTAL LABOUR : \$
TOTAL REPAIR COST : \$

2310

DATE OF SURVEY / INSPECTED :
RECOMMENDED PART BY PART / LUMP SUM :
RECOMMENDED NUMBER OF DAYS :
SURVEY BY / SURVEYOR FIRM :
RE-SURVEY DISMANTLE PARTS / BEFORE PAINT / AFTER PAINT :
FINALISED AMOUNT :

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 4557.50
503
P- 2278.75
S.V- 450.00
L- 2310.00
\$ 5038.75