



China Tarping  
Voh In.  
21/08/20  
Monday

# 辉 阳 汽 车 有 限 公 司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721  
Tel: 64515752 (2 Lines) . Fax: 64514658  
GST & Reg No. 201629438M

28/08/2020

Owner: ACE FLEET MANAGEMENT PTE LTD

Not Authorized  
L1 Lnp @ 8850p  
Recovery After Paint  
6 days

## ESTIMATE TO REPAIR TOYOTA NOAH 1.8X - SMN9429K

|       |   |         |           |           |                  |          |
|-------|---|---------|-----------|-----------|------------------|----------|
| 1pc   | rear tailgate                                       | 1712.85 | Rh        | \$        | 1,712.85         | ✓        |
| 1pc   | rear tailgate "HYBRID" emblem                       |         | na        | \$        | 132.25           | —        |
| 1pc   | rear tailgate windscreen glass                      |         | Shortland | \$        | 1,850.50         | ✓        |
| 1pc   | rear tailgate windscreen moulding                   |         | na        | \$        | 172.80           | ✓        |
| 1pc   | rear tailgate outer chrome                          |         | CM        | \$        | 581.90           | —        |
| 1pc   | rear tailgate "TOYOTA" logo                         |         | na        | \$        | 121.10           | —        |
| 1pc   | rear tailgate inner lock                            | 561.25  | na        | \$        | 581.90           | —        |
| 1pc   | rear tailgate inner rubber                          |         | Dilina    | \$        | 371.85           | —        |
| 1pc   | rear tailgate inner garnish                         |         | mgcm      | \$        | 371.75           | ✓        |
| 2pcs  | rear taillamp @\$781.55                             |         | ols cr    | \$        | 1,563.10         | LT       |
| 2pcs  | rear taillamp lower garnish @\$371.85               |         | ols cm    | \$        | 743.70           | LT       |
| 2pcs  | rear taillamp lower garnish side retainer @\$172.25 |         | ols dir   | \$        | 344.50           | LT       |
| 1pc   | rear bumper   |         | Rh        | \$        | 1,217.45         | ✓        |
| 2pcs  | rear bumper side retainer @\$172.10                 |         | ols dir   | \$        | 344.20           | LT       |
| 1pc   | rear bumper RH side reflector                       |         | Sm        | \$        | 181.90           | X        |
| 10pcs | rear bumper clip @\$5.00                            |         | na        | \$        | 50.00            | —        |
| 1pc   | rear end panel                                      | 610.30  | Rh        | \$        | 781.10           | ✓        |
| 1pc   | rear end panel inner garnish                        | 288.90  | mg dir    | \$        | 378.85           | —        |
| 1pc   | rear end panel outer sensor                         |         | ad        | \$        | 381.50           | ✓        |
| 1pc   | rear floor panel inner trim                         |         | na        | \$        | 581.90           | ✓        |
| 1pc   | rear floor panel top board trim                     | 845.10  | na        | \$        | 1,238.00         | —        |
| 1pc   | rear fender RH inner garnish                        |         | na        | \$        | 731.35           | — 681.00 |
|       |   |         |           | \$        | 14,434.45        |          |
|       | less 25%  |         |           | \$        | 3,608.61         |          |
|       |   |         |           | \$        | 10,825.84        |          |
| 1set  | rear parking sensor                                 |         | Short     | s.nett    | \$ 280.00        | 200sn    |
| 1set  | rear windscreen glass private hire car decal        |         | na        | s.nett    | \$ 20.00         | —        |
|       | sealant   |         | na        | s.nett    | \$ 80.00         | 40sn     |
|       | remove & refit rear windscreen glass                |         |           | \$        | 120.00           | ✓        |
|       | wiring  |         |           | \$        | 180.00           | 2ol      |
|       | tuffkote  |         |           | \$        | 180.00           | 6ol      |
|       | spray painting                                      |         |           | \$        | 1,400.00         | 9ool     |
|       | labour charges                                      |         |           | \$        | 1,400.00         | 7ool     |
|       | <b>Total</b>  |         |           | <b>\$</b> | <b>14,485.84</b> |          |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_

