

# 輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721  
Tel: 64515752 (2 Lines) . Fax: 64514658  
GST & Reg No. 201629438M

*China Taping*  
*veh in.*  
*31/08/20*  
*Monday*

28/08/2020

Owner: ACE FLEET MANAGEMENT PTE LTD

*Not Authorized*  
*11 Days @*  
*Resurvey After Paint*  
*6 days*

**ESTIMATE TO REPAIR TOYOTA NOAH 1.8X - SMN9429K**

1pc	rear tailgate		<i>Rh</i> \$ 1,712.85 ✓
1pc	rear tailgate "HYBRID" emblem		<i>nu</i> \$ 132.25 ✓
1pc	rear tailgate windscreen glass		<i>Shattered</i> \$ 1,850.50 ✓
1pc	rear tailgate windscreen moulding		<i>nu</i> \$ 172.80 ✓
1pc	rear tailgate outer chrome		<i>CM</i> \$ 581.90 ✓
1pc	rear tailgate "TOYOTA" logo		<i>nu</i> \$ 121.10 ✓
1pc	rear tailgate inner lock		<i>nu</i> \$ 581.90 ✓
1pc	rear tailgate inner rubber		<i>Di/ra</i> \$ 371.85 ✓
1pc	rear tailgate inner garnish		\$ 371.75 ?
2pcs	rear taillamp @\$781.55		<i>ols cu</i> \$ 1,563.10 ✓
2pcs	rear taillamp lower garnish @\$371.85		<i>ols cm</i> \$ 743.70 ✓
2pcs	rear taillamp lower garnish side retainer @\$172.25		<i>ols dir</i> \$ 344.50 ✓
1pc	rear bumper		<i>Rh</i> \$ 1,217.45 ✓
2pcs	rear bumper side retainer @\$172.10		<i>ols dir</i> \$ 344.20 ✓
1pc	rear bumper RH side reflector		<i>Sm</i> \$ 181.90 X
10pcs	rear bumper clip @\$5.00		<i>nu</i> \$ 50.00 ✓
1pc	rear end panel		\$ 781.10 ?
1pc	rear end panel inner garnish		<i>mg dir</i> \$ 378.85 ✓
1pc	rear end panel outer sensor		\$ 381.50 ?
1pc	rear floor panel inner trim		<i>re/nu</i> \$ 581.90 ✓
1pc	rear floor panel top board trim		<i>re/nu</i> \$ 1,238.00 ✓
1pc	rear fender RH inner garnish		<i>Rh</i> \$ 731.35 ✓
			<hr/>
			\$ 14,434.45
	less 25%		<hr/> \$ 3,608.61
			<hr/> \$ 10,825.84
1set	rear parking sensor		<i>Shor</i> s.nett \$ 280.00 <i>200sn</i>
1set	rear windscreen glass private hire car decal		<i>nu</i> s.nett \$ 20.00 ✓
	sealant		<i>nu</i> s.nett \$ 80.00 <i>40sn</i>
	remove & refit rear windscreen glass		\$ 120.00 ✓
	wiring		\$ 180.00 <i>20l</i>
	tuffkote		\$ 180.00 <i>60h</i>
	spray painting		\$ 1,400.00 <i>900l</i>
	labour charges		\$ 1,400.00 <i>700l</i>
	<b>Total</b>		<hr/> <b>\$ 14,485.84</b> <hr/>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_

