

21/08/2020

Chua

ESTIMATE QUOTATIONS

VEH REG. No: SKC 5H2A

Hyundai Elantra 1.6 Auto

<u>S/No:</u>	<u>DESCRIPTIONS</u>	<u>QTY</u>	<u>PRICE</u>	
1.	Removal/Pulling/Knocking/Fixing:		X Repair	
	(a) Front R/H Door Assy	1pc	} \$ 320.00	
	(b) Rear R/H Door Assy	1pc		
	(c) Rear R/H Wheel Arch			300
	(d) Front R/H Side Mirror Cover	1pc		650
2.	Paint/Spray Painting Accident Park		\$ 680.00	
3.	Anti-rust (Tuff-Kote) Affected Parts	X NN	\$ 80.00	
4.	Check Wires on Doors/Side Mirror		\$ 50.00 ✓	

REPAIR: \$ 1130.00

1000

4 days

After repair photos

31/08/2020

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

