

Repair Estimate

Date : 28/08/2020

Reference: SJA 819G

Make: Honda
Stream

To Whom It May Concern

Dear Sir,

RE: VEHICLE .: SJA 819G
CHASSIS NO.: RN61038728
ENGINE NO.: R18A1743657TP Chiam.
Veron.Name of insured .: Tan Jee Joan
Date of accident.: 27/08/2020

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

<u>No.</u>	<u>Qty</u>	<u>Part Description</u>	<u>Price (SGD)</u>
1	1	RR DOOR RH <i>Dented</i>	850.00 ✓
2	1	RR DOOR HINGE UPP RH <i>3 new</i>	60.00 +
3	1	RR DOOR HINGE LOW RH	60.00 +
4	1	RR DOOR CHECKER RH - Link Check <i>new</i>	55.00 +
5	1	RR DOOR LOCK RH <i>new</i>	80.00 +
6	1	RR DOOR LOCK CATCHER RH - Striker <i>new</i>	75.00 +
7	1	RR DOOR INNER TRIM RH <i>new</i>	250.00 +
8	1	RR DOOR RUBBER BEADING RH - Body Side <i>new</i>	55.00 +
9	1	RR DOOR WEATHER STRIP RH <i>new</i>	40.00 ✓
10	1	RR DOOR OUTER HANDLE RH <i>Regr</i>	45.00 +
11	1	RR DOOR OUTER HANDLE KNOB RH - Cover <i>3 new</i>	27.00 +
12	1	RR DOOR HANDLE INNER BASE RH - Bracket	33.00 +
13	1	RR DOOR BLACK STICKER RH <i>new</i>	60.00 ✓
14	1	RR DOOR MOULDING RH <i>new</i>	63.00 +
15	1	RR DOOR GLASS RUNCHANNEL RUBBER BEADING WITH QUARTER GLASS RH <i>new</i>	280.00 +
16	1	RR DOOR POWER WINDOW REGULATOR ASSY RH <i>new</i>	320.00 +
17	1	RR FENDER RH <i>Dented</i>	860.00 ✓
18	1	RR BUMPER <i>Regr</i>	680.00 +
19	1	RHR RIM <i>cut</i>	200.00 ✓

Parts Total: 4,093.00
Less 20%: 818.60
Total : 3,274.402010
1608

Labour

<u>No.</u>	<u>Labour Description</u>	<u>Price (SGD)</u>
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	850.00 600
2	Carry out spray painting on accident affected area. (RHR Door, RHR Fender , Rear Bumper)	750.00 600
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	150.00 30
4	To conduct transfer rear door mechanism to new door panel	120.00 80
5	To conduct 4 wheel alignment	150.00 80
6	To remove and refix rear quarter glass	60.00 40
7	Remove and refit Tire from rim	50.00 40
8	Remove and refix seat cushion/upholstery & roof lining to facilitate repairs	250.00 80

1550

Labour Total : 2,380.00**Other**

<u>No.</u>	<u>Other Description</u>	<u>Price (SGD)</u>
1	Door Clip Set	40.00
2	Sealant	50.00

Other Total : 90.00**Total : \$5,744.40****Gst (7%) : \$402.11****GRAND TOTAL: \$6,146.51**

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully

Service Advisor
 Ronnie Tan
 DID: 6844 1985 Fax:6844 5185

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Adrian
 1/8 02/09/20

06 days

total: 3158

1/8 2.5K