



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. M/R 8500111-X

ESTIMATE FOR SMN5920J

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information
WIP No 44620
Reg No/Reg Date SMN5920J / 20/08/2019
Date In/Mileage 31/08/2020 / 13683
Chassis No SWDD2050772R4816718
Engine No 26491530077214
Make/Model MB/MB C 200 AVANTGARDE/AVANTGARDE
Colour/Trim 027 775 Iridium Sil/ 042 201 Leather Bla

Account No	Terms	Date/Time Printed	CSE	Operator	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
WC000668	Credit	31/08/2020/ 17:37	CH	371 / Go Chee Han					
Z REQUEST									
Customer Request									
M-BPNSUN									
POLICY NO/ACC DATE : DMPCSNW00092152000 // 28-8-2020									
DRIVE IN/EXCESS : 29-8-2020 // TBA									
DATE IN/DATE SURVEY:									
BY/AUTHORIZED ON :									
A BPILAB					PANEL BEATING TO REPLACE AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS AND REFINISH.				10560 9600 11520.00
A BPIRES					RESPRAY REAR BUMPER & END PANEL & LH/REAR FENDER & RH/REAR FENDER TRUNK LID				✓ 3000 3600.00
A BPILAB					USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT	0.10			✓ 380.00
A BPILAB					CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT				✓ 120.00
A BPILAB					PLACE VEHICLE ON-TO CELLETTE BENCH & CONDUCT CHASSIS ALIGNMENT. NETT	0.07			✓ 1000.00
A BPILAB					TRANSFER TRUNK LID MECHANICAL & ELETRICAL TO NEW TRUNK LID.NETT				✓ 480.00
A BPILAB					REMOVE & REFIT LUGGAGE COMPARTMENT,TRIM, GARNISH-CARPET FOR NECESSARY REPAIR.NETT				✓ 480.00
A BPILAB					REMOVE & INSTALL INTERIOR SEATS, CARPET, GARNISH UNHOLSTRY ETC FOR NECESSARY REPAIR.				✓ 960 1440.00
A BPILAB					TO DRAIN OUT PETROL & REPLACE FUEL TANK RECESS.NETT				✓ 240.00
A BPILAB					REMOVE CARRIAGE ASSY FROM FRAME, IMPACT.REPLACE AND ASSEMBLE WHEEL BASE & ADJUST TO VEHICLE.				2160.00
									✓ 1420

Confirmed & accepted by

Authorized signatory and company stamp

Go Chee Han
DID : 6771 4336 HP : 9181 7717
Email : cheehan.go@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. NR 8300111 X

ESTIMATE FOR SMN5920J

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information
WIP No 44620
Reg No/Reg Date SMN5920J / 20/08/2019
Date In/Mileage 31/08/2020 / 10683
Chassis No SWBD2050772R4816718
Engine No 26491530077214
Make/Model MB/MB C 200 AVANTGARDE/AVANTGARDE
Colour/Trim 027 775 Iridium Sil/ 042 201 Leather Bla

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	31/08/2020/ 17:37	CH	371 / Go Chee Han

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
A BPILAB TO INSPECT & CONDUCT WHEEL ALIGNMENT.NETT				540.00
A BPILAB REMOVE & REPLACE REAR WINDSCREEN WITH INSTALL . NETT				560.00
S BPNSUB SUPPLY & INSTALL 1 PC REAR WINDSCREEN SOLAR HUPER OPTIK FILM.NETT				300.00
A 54124001 FUSE AND RELAY MODULE IN REAR WELL COMPARTMENT PARTIALLY FOR NECESSARY REPAIRS.NETT				480.00
M REAR BUMPER	1.00	1643.61	00.00	1643.61
M REAR LOWER BLACK TRIM BUMPER	1.00	267.71	00.00	267.71
M REAR BUMPER TRIM STRIP	1.00	293.28	00.00	293.28
M LH/LOWER COVER BUMPER AREA	1.00	101.31	00.00	101.31
M REAR SWITCH MODULE BRACKET	1.00	41.18	00.00	41.18
M ELECTRICAL WIRING HARNESS	1.00	131.09	00.00	131.09
M LH/LOWER BRACKET	1.00	34.46	00.00	34.46
M RH/LOWER BRACKET	1.00	35.15	00.00	35.15
M CTR/BASIC MOUNTING FOR BUMPER	1.00	95.12	00.00	95.12
M LH/BASIC MOUNTING FOR BUMPER	1.00	58.62	00.00	58.62
M RH/BASIC MOUNTING FOR BUMPER	1.00	58.62	00.00	58.62
M LH/TOP BASIC MOUNTING FOR BUMPER	1.00	33.77	00.00	33.77
M RH/TOP BASIC MOUNTING FOR BUMPER	1.00	33.27	00.00	33.27
M RIVET FOR BUMPER	12.00	4.59	00.00	55.08
M EXPANSION RIVET	4.00	5.87	00.00	23.48
M REAR CROSS MEMBER	1.00	674.74	00.00	674.74
M LOAD COMPARTMENT WELL	1.00	562.25	00.00	562.25
M RH/LOWER COVER, REAR-END FLOOR	1.00	159.24	00.00	159.24
M LH/REAR LAMP COMBINATION	1.00	706.03	00.00	706.03
M RH/REAR LAMP COMBINATION	1.00	706.03	00.00	706.03
M LH/TRIM PANEL LOADING SPACE	1.00	50.67	00.00	50.67
M SEAL WASHER	6.00	1.88	00.00	11.28
M LINING LOADING SILL	1.00	135.71	00.00	135.71
M TRUNK LID	1.00	2202.15	00.00	2202.15

Confirmed & accepted by

Repair day - 16 dys.

OP-CTZ

Rev

Authorized signatory and company stamp

Excess - \$500.

Go Chee Han
DID: 6771 4336 HP: 9181 7717
Email: cheehan.go@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

P/P
before paint

Sun Pn (Lk6)
31/08/2020

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. NR-8500111-X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

ESTIMATE FOR SMN5920J

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

CHEONG GOO IN INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information

WIP No 44620
Reg No/Reg Date SMN5920J / 20/08/2019
Date In/Mileage 13683
Chassis No WDD2050772R4846718
Engine No 26491530077214
Make/Model MB/MB C 200 AVANTGARDE/AVANTGARDE
Colour/Trim 027 775 Iridium Sil/ 042 201 Leather Bla

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	31/08/2020/ 17:37	CH	371 / Go Chee Han

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M SEALING FRAME ✓ CR ✓	1.00	202.56	00.00	202.56 ✓
M BOTTOM RETAINER WEDGE ✓ NA ✓	2.00	10.81	00.00	21.62 ✓
M TOP RETAINER WEDGE ✓ Nec ✓	2.00	11.78	00.00	23.56 ✓
M LH/TRUNK LID HINGE LEVER ✓ BT ✓	1.00	254.52	00.00	254.52 ✓
M RH/TRUNK LID HINGE LEVER ✓ OT ✓	1.00	254.52	00.00	254.52 ✓
M TRIM PANEL TRUNK LID ✓ CR ✓	1.00	239.44	00.00	239.44 ✓
M TRUNK LID TRIM STRIP chrome ✓ SCR ✓	1.00	133.01	00.00	133.01 ✓
M SEALING GROMMET ✓ Nec ✓	3.00	2.26	00.00	6.78 ✓
M MERCEDES STAR ✓ Nec ✓	1.00	48.72	00.00	48.72 ✓
M C200 MODEL PLATE ✓ Nec ✓	1.00	91.04	00.00	91.04 ✓
M NUT ✓ Nec ✓	4.00	5.56	00.00	22.24 ✓
M TRUNK LID LOCK ✓ 2 ✓ Jam ✓	1.00	288.88	00.00	288.88 ✓
M TRUNK LID MOTOR MOUNTING CONSOLE ✓ 2 ✓ Xnn ✓	1.00	83.56	00.00	83.56 ✓
M DRIVE UNIT TRUNK LID ✓ 2 ✓ Xnn ✓	1.00	957.91	00.00	957.91 ✓
M REAR WINDOW ✓ Nec ✓	1.00	1034.11	00.00	1034.11 ✓
M ONE-COMPONENT ADHESIVE ✓ Nec ✓	2.00	156.83	00.00	313.66 ✓
M SEALING STRIP ✓ Nec ✓	4.00	2.61	00.00	10.44 ✓
M LH/REAR FENDER ✓ PB ✓	1.00	2273.59	00.00	2273.59 ✓
M RH/REAR FENDER ✓ PB ✓	1.00	2273.59	00.00	2273.59 ✓
M TANK FILLER RECESS ✓ Xnn ✓	1.00	205.79	00.00	205.79 ✓
M BOTH SIDE WALL INSULATION ✓ Nec ✓	2.00	59.75	00.00	119.50 ✓
M ZINC DUST PAINT ✓ Xnn ✓	1.00	256.50	00.00	256.50 ✓
M WHITE SEAM SEALING COMPOUND ✓ Nec ✓	1.00	104.99	00.00	104.99 ✓
M BLIND RIVET 6.4 X 12 ✓ Nec ✓	34.00	1.35	00.00	45.90 ✓
M BLIND RIVET W CSK. HEAD 6.4 X 14.0 ✓ Nec ✓	6.00	1.95	00.00	11.70 ✓
M TS TWO-COMPONENT ADHESIVE ✓ Nec ✓	2.00	776.81	00.00	1553.62 ✓
M REAR END PANEL ✓ DD ✓ photo ✓	1.00	1445.33	00.00	1445.33 ✓
M BLIND RIVET 6.4 X 12.5 ✓ Nec ✓	6.00	2.58	00.00	15.48 ✓

Go Chee Han
DID : 6771 4336 HP : 9181 7717
Email : cheehan.go@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Confirmed & accepted by

Nett 43,706.41
7% GST on 43706.41 3059.45

Authorized signatory and company stamp

Total Payable 46,765.86

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

Finalization

ESTIMATE FOR SMN5920J

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information

WIP No 44620
Reg No/Reg Date SMN5920J / 20/08/2019
Date In/Mileage 02/09/2020 / 13683
Chassis No WDD2050772R4816718
Engine No 26491530077214
Make/Model MB/MB C 200 AVANTGARDE/AVANTGARDE
Colour/Trim 027 775 Iridium Sil/ 042 201 Leather Bla

Account No	Terms	Date/Time Printed	CSE	Operator	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
WC000668	Credit	22/09/2020/ 14:51	CH	371 / Go Chee Han					

M BPNSUN

POLICY NO/ACC DATE : DMPCSNW00092152000 / 28-8-2020

DRIVE IN/EXCESS : 29-8-2020 // \$500

DATE IN/DATE SURVEY: 31-8-2020 // SUN PIN - LKK

BY/AUTHORIZED ON : 1-9-2020 // DENISE TAY - LKK

A BPILAB

PANEL BEATING TO REPLACE AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS AND REFINISH.

10560.00 ✓

A BPIRES

RESPRAY REAR BUMPER & END PANEL & LH/REAR FENDER & RH/REAR FENDER TRUNK LID

3000.00 ✓

A BPILAB

USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT

0.10

380.00 ✓

A BPILAB

CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT

120.00 ✓

A BPILAB

PLACE VEHICLE ON-TO CELLETTE BENCH & CONDUCT CHASSIS ALIGNMENT. NETT

0.07

1000.00 ✓

A BPILAB

TRANSFER TRUNK LID MECHANICAL & ELECTRICAL TO NEW TRUNK LID.NETT

480.00 ✓

A BPILAB

REMOVE & REFIT LUGGAGE COMPARTMENT, TRIM, GARNISH-CARPET FOR NECESSARY REPAIR.NETT

480.00 ✓

A BPILAB

REMOVE & INSTALL INTERIOR SEATS, CARPET, GARNISH UNHOLSTRY ETC FOR NECESSARY REPAIR.

960.00 ✓

A BPILAB

TO DRAIN OUT PETROL & REPLACE FUEL TANK RECESS.NETT

240.00 ✓

A BPILAB

REMOVE CARRIAGE ASSY FROM FRAME, IMPACT.REPLACE AND ASSEMBLE WHEEL BASE & ADJUST TO VEHICLE.

1920.00 ✓

A BPILAB

TO INSPECT & CONDUCT WHEEL ALIGNMENT.NETT

540.00 ✓

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383



Mercedes-Benz

Finalization

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SMN5920J

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information

WIP No 44620
Reg No/Reg Date SMN5920J / 20/08/2019
Date In/Mileage 02/09/2020/ 13683
Chassis No WDD2050772R4816718
Engine No 26491530077214
Make/Model MB/MB C 200 AVANTGARDE/AVANTGARDE
Colour/Trim 027 775 Iridium Sil/ 042 201 Leather Bla

Account No	Terms	Date/Time Printed	CSE	Operator	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
WC000668	Credit	22/09/2020/ 14:51	CH	371 / Go Chee Han					
A BPILAB					REMOVE & REPLACE REAR WINDSCREEN WITH INSTALL. NETT			0.07	560.00
S BPNSUB					SUPPLY & INSTALL 1 PC REAR WINDSCREEN SOLAR HUPER OPTIK FILM.NETT				300.00
A 54124001					FUSE AND RELAY MODULE IN REAR WELL COMPARTMENT PARTIALLY FOR NECESSARY REPAIRS.NETT				480.00
X BPNEXC					INSURANCE EXCESS				-500.00
X					REAR BUMPER /CRU	1.00	1643.61	00.00	1643.61
X					REAR LOWER BLACK TRIM BUMPER /SCR	1.00	267.71	00.00	267.71
X					REAR BUMPER TRIM STRIP /SCR	1.00	293.28	00.00	293.28
X					LH/LOWER BRACKET /CRA	1.00	34.46	00.00	34.46
X					CTR/BASIC MOUNTING FOR BUMPER /Nec	1.00	95.12	00.00	95.12
X					LH/BASIC MOUNTING FOR BUMPER /Nec	1.00	58.62	00.00	58.62
X					LH/TOP BASIC MOUNTING FOR BUMPER /Nec	1.00	33.77	00.00	33.77
X					RH/TOP BASIC MOUNTING FOR BUMPER /Nec	1.00	33.27	00.00	33.27
X					RIVET FOR BUMPER /Nec	12.00	4.59	00.00	55.08
X					EXPANSION RIVET /Nec	4.00	5.87	00.00	23.48
X					LH/REAR LAMP COMBINATION /CRU	1.00	706.03	00.00	706.03
X					TRIM, LOAD COMPARTMENT /Nec (A)	1.00	50.67	00.00	50.67
X					LINING LOADING SILL /CRU	1.00	135.71	00.00	135.71
X					TRUNK LID /CRU	1.00	2202.15	00.00	2202.15
X					SEALING FRAME /CRU	1.00	202.56	00.00	202.56
X					TOP RETAINER WEDGE /Nec	2.00	11.78	00.00	23.56
X					LH/TRUNK LID HINGE LEVER /BT	1.00	254.52	00.00	254.52
X					RH/TRUNK LID HINGE LEVER /BT	1.00	254.52	00.00	254.52
X					TRIM PANEL TRUNK LID /CRU	1.00	239.44	00.00	239.44
X					SEALING GROMMET /Nec	3.00	2.26	00.00	6.78
X					MERCEDES STAR /Nec	1.00	48.72	00.00	48.72
X					C200 MODEL PLATE /Nec	1.00	91.04	00.00	91.04
X					NUT /Nec	4.00	5.56	00.00	22.24
X					TRUNK LID LOCK /Jam	1.00	288.88	00.00	288.88

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Finalization

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SMN5920J

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information

WIP No 44620
Reg No/Reg Date SMN5920J / 20/08/2019
Date In/Mileage 02/09/2020 / 13683
Chassis No WDD2050772R4816718
Engine No 26491530077214
Make/Model MB/MB C 200 AVANTGARDE/AVANTGARDE
Colour/Trim 027 775 Iridium Sil/ 042 201 Leather Bla

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	22/09/2020/ 14:51	CH	371 / Go Chee Han

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X REAR WINDOW / NEC	1.00	1034.11	00.00	1034.11
X ONE-COMPONENT ADHESIVE / NEC	2.00	156.83	00.00	313.66
X LH/REAR FENDER / PD	1.00	2273.59	00.00	2273.59
X RH/REAR FENDER / PD	1.00	2273.59	00.00	2273.59
X BOTH SIDE WALL INSULATION / NEC	1.00	59.75	00.00	59.75
X WHITE SEAM SEALING COMPOUND / NEC	2.00	104.99	00.00	209.98
X BLIND RIVET 6.4 X 12 / NEC	34.00	1.35	00.00	45.90
X BLIND RIVET W CSK. HEAD 6.4 X 14.0 / NEC	6.00	1.95	00.00	11.70
X TS TWO-COMPONENT ADHESIVE / NEC	2.00	776.81	00.00	1553.62
X REAR END PANEL / PD	1.00	1445.33	00.00	1445.33
X BLIND RIVET 6.4 X 12.5 / NEC	6.00	2.58	00.00	15.48
X SIDE WALL INSULATION / NEC (CA)	1.00	59.75	00.00	59.75
X [STR] TWO-COMPONENT ADHESIVE / NEC (A)	2.00	102.00	00.00	204.00
X TRUNK LID TRIM STRIP / CRU (A)	1.00	133.01	00.00	133.01
X LH/LINING WHEEL INSTALLATION / CRU (A)	1.00	278.96	00.00	278.96
X TRUNK LID POWER CLOSING BRACKET / RT (A)	1.00	467.44	00.00	467.44
X RH/CIRCUMFERENTIAL GASKET / NEC (A)	1.00	57.42	00.00	57.42
X LH/CIRCUMFERENTIAL GASKET / NEC (A)	1.00	57.42	00.00	57.42
X C-PILLAR STRUT, INNER LEFT / PD (A)	1.00	395.57	00.00	395.57
X ELASTOMER BEARING / NEC (A)	2.00	2.92	00.00	5.84
X LOAD COMPARTMENT WELL / PD	1.00	562.25	00.00	562.25

P = 18,523.59

L = 21,020

39,543.59

P/P

16 days @ \$39,543.09

Confirmed & accepted by

Nett 39,043.59
7% GST on 39043.59 2733.05

Authorized signatory and company stamp

Total Payable 41,776.64

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383



Mercedes-Benz

SUPPLEMENTARY

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SMN5920J

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information

WIP No 44620
Reg No/Reg Date SMN5920J / 20/08/2019
Date In/Mileage 02/09/2020 / 13683
Chassis No WDD2050772R4816718
Engine No 26491530077214
Make/Model MB/MB C 200 AVANTGARDE/AVANTGARDE
Colour/Trim 027 775 Iridium Sil/ 042 201 Leather Bla

Account No	Terms	Date/Time Printed	CSE	Operator			
WC000668	Credit	22/09/2020/ 14:50	CH	371 / Go Chee Han			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount

M BPNSUN

POLICY NO/ACC DATE : DMPGNNW00092152000 / 28-8-2020
DRIVE IN/EXCESS : 29-8-2020 // \$600
DATE IN/DATE SURVEY: 31-8-2020 // SUN PIN - LKK
BY/AUTHORIZED ON : 1-9-2020 // DENISE TAY - LKK
X [STR] TWO-COMPONENT ADHESIVE - NEC
X LH/LINING WHEEL INSTALLATION - CRU
X TRUNK LID POWER CLOSING BRACKET - BT
X RH/CIRCUMFERENTIAL GASKET - NPL
X LH/CIRCUMFERENTIAL GASKET - NPL
X C-PILLAR STRUT, INNER LEFT - PD
X ELASTOMER BEARING - NPL

2.00	102.00	00.00	204.00
1.00	278.96	00.00	278.96
1.00	467.44	00.00	467.44
1.00	57.42	00.00	57.42
1.00	57.42	00.00	57.42
1.00	395.57	00.00	395.57
2.00	2.92	00.00	5.84

ESTIMATE

Confirmed & accepted by

Nett	1,466.65
7% GST on	102.67
Total Payable	1,569.32

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg