



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SMN5920J

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information
WIP No 44620
Reg No/Reg Date SMN5920J / 20/08/2019
Date In/Mileage 13683
Chassis No WDD2050772R4816718
Engine No 26491530077214
Make/Model MB/MB C 200 AVANTGARDE/AVANTGARDE
Colour/Trim 027 775 Iridium Sil/ 042 201 Leather Bla

Account No	Terms	Date/Time Printed	CSE	Operator				
WC000668	Credit	31/08/2020/ 17:37	CH	371 / Go Chee Han				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
Z REQUEST								
Customer Request								
M-BPNSUN								
POLICY NO/ACC DATE : DMPCSNW00092152000 // 28-8-2020								
DRIVE IN/EXCESS : 29-8-2020 // TBA								
DATE IN/DATE SURVEY:								
BY/AUTHORIZED ON :								
A BPILAB								9600
PANEL BEATING TO REPLACE AFFECTED AREAS, REMOVE AND REPLACE WITH NEW								11520.00
BODY PANELS AND REFINISH.								3000
A BPIRES								3600.00
RESPRAY REAR BUMPER & END PANEL & LH/REAR FENDER & RH/REAR FENDER								
TRUNK LID								
A BPILAB							0.10	380.00
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO								
IDENTIFICATION STANDARD. NETT								120.00
A BPILAB								
CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT							0.07	1000.00
A BPILAB								480.00
PLACE VEHICLE ON-TO CELLETTE BENCH & CONDUCT CHASSIS ALIGNMENT. NETT								480.00
A BPILAB								
TRANSFER TRUNK LID MECHANICAL & ELETRICAL TO NEW TRUNK LID.NETT								960
A BPILAB								1440.00
REMOVE & REFIT LUGGAGE COMPARTMENT,TRIM, GARNISH-								
CARPET FOR NECESSARY REPAIR.NETT								240.00
A BPILAB								
REMOVE & INSTALL INTERIOR SEATS, CARPET, GARNISH UNHOLSTRY ETC								
FOR NECESSARY REPAIR.								
A BPILAB								
TO DRAIN OUT PETROL & REPLACE FUEL TANK RECESS.NETT								2160.00
A BPILAB								1920
REMOVE CARRIAGE ASSY FROM FRAME, IMPACT.REPLACE AND ASSEMBLE								
WHEEL BASE & ADJUST TO VEHICLE.								

Confirmed & accepted by

Authorized signatory and company stamp

Go Chee Han

DID : 6771 4336 HP : 9181 7717

Email : cheehan.go@cyclecarriage.com.sg

Cycle & Carriage Industries Pte Ltd

Customer Service Centre - Pandan Loop

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR 8500111 X

ESTIMATE FOR SMN5920J

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information
WIP No 44620
Reg No/Reg Date SMN5920J / 20/08/2019
Date In/Mileage 18680
Chassis No WDB2080772R4816718
Engine No 26491530077214
Make/Model MB/MB C 200 AVANTGARDE/AVANTGARDE
Colour/Trim 027 775 Iridium Sil/ 042 201 Leather Bla

Account No	Terms	Date/Time Printed	CSE	Operator	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
WC000668	Credit	31/08/2020/ 17:37	CH	371 / Go Chee Han					
A BPILAB					TO INSPECT & CONDUCT WHEEL ALIGNMENT				540.00
A BPILAB					REMOVE & REPLACE REAR WINDSCREEN WITH INSTALL . NETT				560.00
S BPNSUB					SUPPLY & INSTALL 1 PC REAR WINDSCREEN SOLAR HUPER OPTIK FILM.NETT				300.00
A 54124001					FUSE AND RELAY MODULE IN REAR WELL COMPARTMENT PARTIALLY FOR NECESSARY REPAIRS.NETT				480.00
M					REAR BUMPER / CR4	1.00	1643.61	00.00	1643.61
M					REAR LOWER BLACK TRIM BUMPER / SCR.	1.00	267.71	00.00	267.71
M					REAR BUMPER TRIM STRIP ?	1.00	293.28	00.00	293.28
M					LH/LOWER COVER BUMPER AREA ?	1.00	101.31	00.00	101.31
M					REAR SWITCH MODULE BRACKET ?	1.00	41.18	00.00	41.18
M					ELECTRICAL WIRING HARNESS ?	1.00	131.09	00.00	131.09
M					LH/LOWER BRACKET / CR4	1.00	34.46	00.00	34.46
M					RH/LOWER BRACKET ?	1.00	35.15	00.00	35.15
M					CTR/BASIC MOUNTING FOR BUMPER ?	1.00	95.12	00.00	95.12
M					LH/BASIC MOUNTING FOR BUMPER ?	1.00	58.62	00.00	58.62
M					RH/BASIC MOUNTING FOR BUMPER ?	1.00	58.62	00.00	58.62
M					LH/TOP BASIC MOUNTING FOR BUMPER ?	1.00	33.77	00.00	33.77
M					RH/TOP BASIC MOUNTING FOR BUMPER ?	1.00	33.27	00.00	33.27
M					RIVET FOR BUMPER / Nec	12.00	4.59	00.00	55.08
M					EXPANSION RIVET / Nec	4.00	5.87	00.00	23.48
M					REAR CROSS MEMBER ?	1.00	674.74	00.00	674.74
M					LOAD COMPARTMENT WELL / Nec	1.00	562.25	00.00	562.25
M					RH/LOWER COVER, REAR-END FLOOR X	1.00	159.24	00.00	159.24
M					LH/REAR LAMP COMBINATION / CR4	1.00	706.03	00.00	706.03
M					RH/REAR LAMP COMBINATION X	1.00	706.03	00.00	706.03
M					LH/TRIM PANEL LOADING SPACE / CR4	1.00	50.67	00.00	50.67
M					SEAL WASHER clip / Nec	6.00	1.88	00.00	11.28
M					LINING LOADING SILL / CR4	1.00	135.71	00.00	135.71
M					TRUNK LID / CR4	1.00	2202.15	00.00	2202.15

Confirmed & accepted by

Repair day - 16 days.

OP-ETZ

Rev

Excess - \$500.

Authorized signatory and company stamp

Go Chee Han
DID : 6771 4336 HP : 9181 7717
Email : cheehan.go@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

P/P
before paint

Sun Pin (LH6)
31/08/2020

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

ESTIMATE FOR SMN5920J

- All modifications are allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

CYCLE & CARRIAGE INDUSTRIES (S) PTE LTD
 L10 Signature:
ADAN: MOTOR CLAIM DEPARTMENT
 3 ANSON ROAD #16-00
 SPRINGLEAF TOWER
 SINGAPORE 079909
 62222366

Cycle & Carriage
 Industries Pte Limited
 Authorised Dealer
 Company No. 196400367W
 GST Reg No. MR-8500111-X

Vehicle & Document Information

WIP No **44620**
 Reg No/Reg Date **SMN5920J / 20/08/2019**
 Date In/Mileage **13683**
 Chassis No **WDD2050772R4816718**
 Engine No **26491530077214**
 Make/Model **MB/MB C 200 AVANTGARDE/AVANTGARDE**
 Colour/Trim **027 775 Iridium Sil/ 042 201 Leather Bla**

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	31/08/2020/ 17:37	CH	371 / Go Chee Han

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M SEALING FRAME <i>CR4</i>	1.00	202.56	00.00	202.56
M BOTTOM RETAINER WEDGE <i>Nec</i>	2.00	10.81	00.00	21.62
M TOP RETAINER WEDGE <i>Nec</i>	2.00	11.78	00.00	23.56
M LH/TRUNK LID HINGE LEVER <i>BT</i>	1.00	254.52	00.00	254.52
M RH/TRUNK LID HINGE LEVER <i>BT</i>	1.00	254.52	00.00	254.52
M TRIM PANEL TRUNK LID <i>CR4</i>	1.00	239.44	00.00	239.44
M TRUNK LID TRIM STRIP <i>chrome - SCR</i>	1.00	133.01	00.00	133.01
M SEALING GROMMET <i>Nec</i>	3.00	2.26	00.00	6.78
M MERCEDES STAR <i>Nec</i>	1.00	48.72	00.00	48.72
M C200 MODEL PLATE <i>Nec</i>	1.00	91.04	00.00	91.04
M NUT <i>Nec</i>	4.00	5.56	00.00	22.24
M TRUNK LID LOCK <i>?</i>	1.00	288.88	00.00	288.88
M TRUNK LID MOTOR MOUNTING CONSOLE <i>?</i>	1.00	83.56	00.00	83.56
M DRIVE UNIT TRUNK LID <i>?</i>	1.00	957.91	00.00	957.91
M REAR WINDOW <i>Nec</i>	1.00	1034.11	00.00	1034.11
M ONE-COMPONENT ADHESIVE <i>Nec</i>	2.00	156.83	00.00	313.66
M SEALING STRIP <i>Nec</i>	4.00	2.61	00.00	10.44
M LH/REAR FENDER <i>pb</i>	1.00	2273.59	00.00	2273.59
M RH/REAR FENDER <i>pb</i>	1.00	2273.59	00.00	2273.59
M TANK FILLER RECESS <i>X</i>	1.00	205.79	00.00	205.79
M BOTH SIDE WALL INSULATION <i>Nec</i>	2.00	59.75	00.00	119.50
M ZINC DUST PAINT <i>Nec</i>	1.00	256.50	00.00	256.50
M WHITE SEAM SEALING COMPOUND <i>Nec</i>	1.00	104.99	00.00	104.99
M BLIND RIVET 6.4 X 12 <i>Nec</i>	34.00	1.35	00.00	45.90
M BLIND RIVET W CSK. HEAD 6.4 X 14.0 <i>Nec</i>	6.00	1.95	00.00	11.70
M TS TWO-COMPONENT ADHESIVE <i>Nec</i>	2.00	776.81	00.00	1553.62
M REAR END PANEL <i>pb</i>	1.00	1445.33	00.00	1445.33
M BLIND RIVET 6.4 X 12.5 <i>Nec</i>	6.00	2.58	00.00	15.48

Go Chee Han

DID : 6771 4336 HP : 9181 7717

Email : cheehan.go@cyclecarriage.com.sg

Cycle & Carriage Industries Pte Ltd

Customer Service Centre - Pandan Loop

Confirmed & accepted by

Nett 43,706.41
7% GST on 43706.41 3059.45

Authorized signatory and company stamp

Total Payable 46,765.86

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
 188 Pandan Loop
 Singapore 128378
 Tel: 6777 8388
 Fax: 6779 5383
 www.mercedes-benz.com.sg