

HONDA

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Kah Motor Co. Sdn. Bhd.

Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer : GOH GUO-HUA
464 EAST COAST ROAD
SINGAPORE 429037
Registration No : SMD1081J
Chassis No : JHMRU1830JX200113
Model : HRV LX-SIN CVT YM 2018
Owner's Name : GOH GUO-HUA
Ins Policy No. :
Date of Accident : 28/8/2020

Document No. : SQT20002743
Date : 29. Aug 2020
Customer No. : *****425E
Svc Advisor :
Engine No : L15B5670113
Date | Time : 29. Aug 2020 12:01:22 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 3

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER	1	19.30	25	18.33	14.47	15.48
76711-T6A-003	CAPPIVOT	1	5.00	25	4.75	3.75	4.01
91501-S70-003	FASTENER BW/SHIELD	4	5.30	25	20.14	15.90	17.01
91502-S70-003	FASTENER B	2	5.30	25	10.07	7.95	8.51
91536-SS0-J01	FASTENER AW/SHIELD	2	3.80	25	7.22	5.70	6.10
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00			120.00	128.40
73211-T7A-N71	GLASS SETRR.WINDSHIELD	1	739.80	25	702.81	554.85	593.69
Sum Item					4492.26	314.50	4,806.76
BO-VK-ASTRO-RWS	SUPPLY & INSTALL SOLAR FILM ON REAR WINDSCREENS	1	300.00			300.00	321.00
Sum Ext. Service					300.00	21.00	321.00

Survey By

Date & Time

Excess

Status

Signature

Total Amount 24,482.26 1,713.80 26,196.06

Total (Inclusive of GST) 26,196.06

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 29/8/2020 12:12:30 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

HONDA

QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer : GOH GUO-HUA
464 EAST COAST ROAD
SINGAPORE 429037
Registration No : SMD1081J
Chassis No : JHMRU1830JX200113
Model : HRV LX-SIN CVT YM 2018
Owner's Name : GOH GUO-HUA
Ins Policy No :
Date of Accident : 28/8/2020

Document No. : SQT20002743
Date : 29. Aug 2020
Customer No. : *****425E
Svc Advisor :
Engine No : L15B5670113
Date | Time : 29. Aug 2020 12:01:22 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Date of Accident	: 28/8/2020						0% GST	Amount
Item	Description	Qty	Unit Price	Disc %	Amount	Amount	incl GST	
BOSUN	REMOVE AND VACUUM SHATTERED GLASSES	1	650.00	32.5	650.00	45.50	695.50	
BMU30R	REMOVE & REPLACE EXHAUST SYSTEM.(N)	1	650.00	X 11	650.00	45.50	695.50	
BOSUN	REMOVE AND RE-INSTALL TAILGATE SPOILER	1	380.00	28.0	380.00	26.60	406.60	
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	520.00	X 11	520.00	36.40	556.40	
Sum Labor					19690.00	1,378.30	21,068.30	
RS-TMP3040L	VPC 4PCS REAR SENSORS ? x su	1	320.00		320.00	22.40	342.40	
33502-T7A-J01	LAMP UNITR. ? gce	1	482.40	25	391.4	361.80	25.33	387.13
33552-T7A-J01	LAMP UNITL. ca	1	482.40	25	391.4	361.80	25.33	387.13
34150-T7A-J01	LIGHT ASSY,R.LID ca	1	276.90	25	263.05	207.67	14.54	222.21
34155-T7A-J01	LIGHT ASSYL.LID ca	1	276.90	25	263.05	207.67	14.54	222.21
68100-T7A-J20ZZ	TAIL GATE COMP st	1	877.90	25	834	658.42	46.09	704.51
74440-T7A-003	WEATHERSTRIPTAILGATE at	1	101.30	25	96.23	75.97	5.32	81.29
74800-T7A-J02	LOCK ASSYTAILGATE ? ca	1	86.20	25	159.03	64.65	4.53	69.18
84431-T7A-J01ZA	LINING ASSYTAILGATE de	1	139.60	25	132.62	104.70	7.33	112.03
75722-T7W-A01	EMBLEMRR. ne	1	14.60	25	13.67	10.95	0.77	11.72
33505-T7A-J01	REFLECTOR ASSYR.RR. ? x su	1	170.80	X 25	128.10	8.97	137.07	
33555-T7A-J01	REFLECTOR ASSYL.RR. ? x su	1	170.80	X 25	128.10	8.97	137.07	
04717-T7A-000ZZ	FACER.RR.BUMPER CORNER ? x su	1	96.50	X 25	72.37	5.07	77.44	
04718-T7A-000ZZ	FACEL.RR.BUMPER CORNER de	1	96.50	25	91.67	72.37	5.07	77.44
71593-T7A-000	SPACER,R.RR.BUMPER SIDE ne	1	17.30	25	16.43	12.97	0.91	13.88
71598-T7A-000	SPACER,L.RR.BUMPER SIDE ne	1	17.30	25	16.43	12.97	0.91	13.88
91505-TM8-003	CLIP,BUMPER ne	8	2.30	25	17.48	13.80	0.97	14.77
66100-T7A-300ZZ	PANEL COMPRR. st	1	382.70	25	363.56	287.02	20.09	307.11
84640-T7A-J01ZA	LINING ASSYRR.PANEL de	1	45.00	25	42.75	33.75	2.36	36.11
04655-T7A-310ZZ	PANEL SET,RR.FLOOR repair	1	693.00	25	519.75	36.38	556.13	
72841-SH3-315	OILSHEET X 11	3	41.70	X 25	93.82	6.57	100.39	
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER ne	1	19.30	25	18.33	14.47	1.01	15.48
73226-SZW-000	DAMPERSTD 5X5 ne	1	8.70	25	4.75	6.52	0.46	6.98

Printed on 29/8/2020 12:12:30 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATIONGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : GOH GUO-HUA
464 EAST COAST ROAD
SINGAPORE 429037
Registration No : SMD1081J
Chassis No : JHMRU1830JX200113
Model : HRV LX-SIN CVT YM 2018
Owner's Name : GOH GUO-HUA
Ins Policy No :
Date of Accident : 28/8/2020

Document No. : SQT20002743
Date : 29. Aug 2020
Customer No. : *****425E
Svc Advisor :
Engine No : L15B5670113
Date | Time : 29. Aug 2020 12:01:22 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:						
	OWNER INSURER:						
	ACC DATE:						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:						
	TP VEH:						
BOSUN	SUNDRIES	1	100.00 50		100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00 150		180.00	12.60	192.60
BOJSE	BODY JOINT SEALANT REAR END PANEL	1	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT REAR FLOOR PANEL	1	100.00 X		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT TAILGATE	1	100.00		100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00 150		180.00	12.60	192.60
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	650.00 X		650.00	45.50	695.50
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	650.00		650.00	45.50	695.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	650.00		650.00	45.50	695.50
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	650.00		650.00	45.50	695.50
BODAMKIT	WINDSCREEN DAM KIT.	1	100.00		100.00	7.00	107.00
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN ALIGN	1	8000.00 3250		8000.00	560.00	8560.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3500.00 3120		3500.00	245.00	3745.00
BKOT00R	REMOVE & RENEW RR FLOOR INSULATOR.(N)	1	580.00 X		580.00	40.60	620.60
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	650.00 580		650.00	45.50	695.50
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	650.00 580		650.00	45.50	695.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	650.00 325		650.00	45.50	695.50

Printed on 29/8/2020 12:12:30 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.