

XIN HUA WORKSHOP PTE. LTD.

23 Kaki Bukit Avenue 4, #04-01 (South Wing) Singapore 415933

Tel : 6844-1985 Fax : 6844-5185

Reg : 201838521G

Repair Estimate

Date :29/08/2020

Reference: CHEVROLET

Make: ORLANDO

To Whom It May Concern

Dear Sir,

RE: VEHICLE :SLB7600U

CHASSIS NO.: KL1YA7589GK332845

ENGINE NO.: B14NET153530298

Name of insured : AIDIL BAKHTIAR BIN JOSOH

Date of accident.: 28/08/2020

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	FRT BONNET <i>Dented</i>	\$ 1,958.00
2	1	FRT BONNET INSULATOR <i>Abbr torn</i>	\$ 351.00
3	1	FRT BONNET LOCK <i>Abbr m</i>	\$ 203.00
4	1	FRT BONNET LOCK CABLE <i>Abbr m</i>	\$ 148.00
5	1	FRT BONNET RUBBER SEAL <i>Abbr</i>	\$ 85.00
6	2	FRT BONNET STOPPED <i>Abbr m</i>	\$ 10.00
7	1	FRT BONNET HINGE LH <i>2 m</i>	\$ 151.00
8	1	FRT BONNET HINGE RH <i>1 m</i>	\$ 151.00
9	1	FRT FENDER RH <i>Repair</i>	\$ 1,243.00
10	1	FRT FENDER BRACKET RH <i>Abbr m</i>	\$ 128.00
11	1	FRT FENDER INNERSHIELD RH <i>Abbr m</i>	\$ 268.00
12	1	FRT FENDER TOP GARNISH RH <i>Abbr m</i>	\$ 88.00
13	1	FRT FENDER WHEELARCH GARNISH RH <i>Abbr m</i>	\$ 152.00
14	1	FRT BUMPER <i>Distorted</i>	\$ 1,406.00
15	1	FRT BUMPER TOW COVER <i>Missing</i>	\$ 75.00
16	1	FRT BUMPER LOWER <i>Dented</i>	\$ 516.00
17	1	FRT BUMPER LOWER GARNISH(silver colour) <i>Abbr m</i>	\$ 333.00
18	1	FRT BUMPER SIDE RETAINER LH, SUPPORT <i>Abbr m</i>	\$ 133.00
19	1	FRT BUMPER SIDE RETAINER RH, SUPPORT <i>Abbr m</i>	\$ 133.00
20	1	FRT BUMPER BRACKET LH, GUIDE <i>Abbr m</i>	\$ 111.00
21	1	FRT BUMPER BRACKET RH, GUIDE <i>Abbr m</i>	\$ 111.00
22	1	FRT BUMPER SPONGE <i>Cracked</i>	\$ 263.00
23	1	FRT BUMPER REINFORCEMENT, IMPACT BAR <i>Best</i>	\$ 927.00
24	1	FRT BUMPER LOGO <i>New</i>	\$ 158.00

25	1	FRT BUMPER LOW LIP <i>new</i>	\$ 173.00	+
26	1	FRT BUMPER FOG LAMP COVER RH <i>chld</i>	\$ 113.00	✓
27	1	FRT BUMPER FOG LAMP RH <i>new chld.</i>	\$ 330.00	✓
28	1	FRT NUMBER PLATE GARNISH <i>chld</i>	\$ 95.00	✓
29	1	FRT GRILLE TOP <i>ht</i>	\$ 243.00	✓
30	1	FRT GRILLE TOP COVER <i>chld</i>	\$ 131.00	✓
31	1	FRT GRILLE LOW <i>nt</i>	\$ 311.00	✓
32	1	RH HEADLAMP <i>chld</i>	\$ 983.00	✓
33	1	LH HEADLAMP <i>new</i>	\$ 983.00	+
34	1	FRT SUPORT PANEL TOP CENTRE <i>Pyro</i>	\$ 326.00	+
35	1	FRT HEADLAMP LOW PANEL RH(inner) <i>Pyro</i>	\$ 348.00	+
36	1	FRT HEADLAMP LOW PANEL RH(outer) <i>Pyro</i>	\$ 348.00	✓
37	1	A/C CONDENSER <i>wrapped</i>	\$ 875.00	✓
38	1	A/C CONDENSER TOP AIR GUIDE <i>chld</i>	\$ 150.00	✓
39	1	A/C PIPE (condenser to compressor) <i>2nd</i>	\$ 327.00	+
40	1	A/C PIPE (cooling coil to condenser) <i>fan</i>	\$ 268.00	+
41	1	TURBO INTAKECOOLER <i>wrapped</i>	\$ 653.00	✓
42	1	AIR HOSE(turbo to intakecooler) <i>ht</i>	\$ 567.00	✓
43	1	FRT INTAKE AIR DUCT(to resonator box) <i>chld</i>	\$ 145.00	✓
44	1	FRT INTAKE RESONATOR BOX <i>chld</i>	\$ 145.00	✓
45	1	RADIATOR <i>wrapped chld</i>	\$ 1,143.00	✓
46	1	RADIATOR TOP MOUNTING, INSULATOR <i>new</i>	\$ 28.00	✓
47	1	RADIATOR TOP BRACKET <i>new</i>	\$ 17.00	+
48	1	RADIATOR FAN ASSY <i>new</i>	\$ 816.00	+
49	1	RADIATOR FAN COWLING <i>chld</i>	\$ 395.00	✓

12638

11374.20

Parts Total: \$ 19,015.00
Less 10%: \$ 1,901.50
Total : \$ 17,113.50

Labour

No.	Labour Description	Price (SGD)
<u>1</u>	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 1,200.00
<u>2</u>	Carry out spray painting on affected area, FRT BUMPER, FRT BONNET, FRT FENDER RH, FRT DOOR RH, FRT SUPORT PANEL, FRT FENDER LH	\$ 1,200.00
<u>3</u>	To disconnect front wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 120.00
<u>4</u>	To remove and refit aircon condensor, vacuum, refill and check air con gas system	\$ 200.00
<u>5</u>	To remove and refix radiator and conduct pressure test	\$ 120.00
<u>6</u>	To conduct reset of engine light on	\$ 250.00
<u>7</u>	To refocus headlamp	\$ 80.00

1550

Labour Total : \$ 3,170.00

Others

Other Description

No.			Price (SGD)
<u>1</u>	10	BONNET INSULATOR CLIP <i>new</i>	\$ 40.00 <i>30</i>
<u>2</u>	10	FENDER WHEELARCH CLIP <i>new</i>	\$ 40.00 <i>20</i>
<u>3</u>	10	FENDER INNERSHIELD CLIP <i>new</i>	\$ 40.00 <i>+</i>
<u>4</u>	10	BUMPER CLIP <i>new</i>	\$ 40.00 <i>30</i>
<u>5</u>	1	AUTO TRANSMISSION FLUID <i>new</i>	\$ 80.00 <i>50</i>
<u>6</u>	1	RADIATOR COOLANT <i>new</i>	\$ 80.00 <i>50</i>
<u>7</u>	1	FRT NUMBER PLATE <i>new</i>	\$ 65.00 <i>+</i>

180

Other Total: 385.00

TOTAL: 20,668.50

GRAND TOTAL : 20,668.50

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully

Service Advisor
Kelvin Chew
HP: 8292 5595

Admin Lj
2/s 09/09/20
068yrs

total: 13104.20
L/S: 104K.

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: