

Surveyor : RASUL LKK
 Claim : AIG OD
 DOA : 27.08.2020
 Emailed : 10.11.2020, 5.50pm
 Date Survey : 31.08.2020

VEHICLE NO : SJX 9133 X
 MODEL : MIT OUTLANDER 2.0
 WIP : 56609

Material	:	\$	<u>15,189.02</u>
Labour	:	\$	<u>10,295.00</u>
Sub-Total	:	\$	<u>25,484.02</u>
	:		<u>-</u>
Less Excess	:	\$	<u>-</u>
Total	:	\$	<u>25,484.02</u>
GST 7%	:	\$	<u>1,783.88</u>
Grand Total	:	\$	<u>27,267.90</u>
Finalise By/Date	:	<u>LOI / 10/11/2020</u>	

☒ REVERT BACK WITHIN 7 DAYS,
 OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
 + 0 Days (0) Public Holiday
 TOTAL DAYS REPAIR TOOK = 0

☐ TP claim _____

☐ Claim GIA / LTA fee _____

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others _____

☐ Third Party Report - _____

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 31/08/2020	Cust No/Name	/Tay Hee Huat
	Reg No/Reg Date	SJX9133X / 24/04/2018
	Date In/Mileage	11/09/2020/ 66941
	Chassis/Package	GF7W0401404
	Engine No	4J11XS6664
	Make/Model	MIT/OUTLANDER 2.0 2WD CVT ELEGANCE (991)
	Colour/Trim	D01 COSMIC BLUE / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	10/11/2020/ 17:09	BLC	260 / AiTing	56609
Description of Goods / Services					Qty Unit Price Disc% Amount
E PNT88000 REPLACE REAR DAMAGED PARTS, REPLACE REAR BUMPER, TAILGATE, REAR END PANEL, LH REAR FENDER, REPAIR REAR COMPARTMENT, LH REAR COMB LAMP HOUSING, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME					✓ 2700.00
E PNT88000 REMOVE & INSTALL PARKING SENSOR TO FACILITATE REPAIR					✓ 60.00
E PNT88000 REMOVE & INSTALL TAILGATE GLASS AND CONDUCT WATER LEAK TEST					✓ 240.00
M SUNDRY APPLY SEALANT ON TAILGATE GLASS					✓ 80.00
E PNT88000 REMOVE & INSTALL TAILGATE TRIMS & ALL OTHER ATTACHMENTS TO FACILITATE REPAIR					✓ 120.00
E PNT88000 REMOVE & INSTALL REAR COMPARTMENT TRIMS AND REAR FENDER RIMS TO FACILITATE REPAIR					✓ 120.00
E PNT88000 REMOVE & INSTALL REAR QUARTER GLASS AND CONDUCT WATER LEAK TEST					✓ 120.00
E PNT98000 RESPRAY ON REAR BUMPER, TAILGATE, REAR END PANEL, REAR COMPARTMENT, LH REAR FENDER, LH REAR LAMP HOUSING, AND ALL OTHER AFFECTED AREAS TO THE SAME					✓ 1750.00
M SUNDRY APPLY SEALANT ON ACCIDENT PORTIONS					✓ 80.00
M SUNDRY SUPPLY C&C LOGO					✓ 40.00
E PNT88000 REPLACE FRONT DAMAGED PARTS, REPLACE BONNET, LH FRONT FENDER, FRONT SUPPORT PANEL, FRONT BUMPER, REPAIR RH FRONT FENDER, LH FRONT DOOR, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME					✓ 1800.00
E PNT88000					✓ 100.00

PRO-FORMA INVOICE

Co Reg No : 1977014696

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 31/08/2020	Cust No/Name	/Tay Hee Huat
	Reg No/Reg Date	SJX9133X / 24/04/2018
	Date In/Mileage	11/09/2020/ 66941
	Chassis/Package	GF7W0401404
	Engine No	4J11XS6664
	Make/Model	MIT/OUTLANDER 2.0 2WD CVT ELEGANCE (991)
	Colour/Trim	D01 COSMIC BLUE / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	10/11/2020/ 17:09	BLC	260 / AiTing	56609			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
REMOVE & INSTALL A/COND CONDENSOR & RADIATOR TO FACILITATE REPAIR								✓ 80.00
A 54900099								✓ 30.00
VACUUM & TOP UP A/COND GAS								✓ 120.00
A 54900099								✓ 2100.00
CHECK WIRING & ELECTRICAL SYSTEM								✓ 120.00
A 10028901								✓ 2100.00
CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE								✓ 120.00
E PNT98000								✓ 80.00
RESPRAY ON FRONT BUMPER, BONNET, FRONT SUPPORT PANEL, LH & RH FRONT FENDER, LH FRONT DOOR, AND ALL OTHER AFFECTED AREAS TO THE SAME								✓ 40.00
B WHEELALIGNMENT								✓ 20.00
To Conduct Computerize Full Wheel Alignment								✓ 50.00
E PNT88000								225.00
CLEAN AND VACUUM SHATTERED GLASSES								✓ 220.00
M SUNDRY								
APPLY SEALANT ON FRONT ACCIDENT PORTIONS								
M SUNDRY								
SUNDRIES								
S SPECIALISTJOB								
SUPPLY & REPLACE REAR LICENSE PLATE WITH FRAME								
A 54900099								
REMOVE & INSTALL FUEL TANK TO FACILITATE REPAIR → Supp.								
S SPECIALISTJOB								
SUPPLY ONE SET OF REVERSE SENSOR								
X FACE,RR BUMPER					1.00	✓ 807.00	23.00	621.39
X BRKT,R/BMPR FACE SIDE,LH					2.00	✓ 12.00	23.00	18.48
X EXTENSION,RR BUMPER					1.00	✓ 232.00	23.00	178.64
X MOULDING,RR BUMPER,LH					1.00	✓ 106.00	23.00	81.62
X PANEL ASSY,TAILGATE					1.00	✓ 984.00	23.00	757.68
X STOPPER,WINDSHIELD GLASS					2.00	✓ 3.00	23.00	4.62
X GLASS,TAILGATE WINDOW					1.00	✓ 654.00	23.00	503.58
X DAM,TAILGATE SIDE					2.00	✓ 27.00	23.00	41.58
X FASTENER,WINDSHIELD					4.00	✓ 6.00	23.00	18.48

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /Tay Hee Huat Reg No/Reg Date SJX9133X / 24/04/2018 Date In/Mileage 11/09/2020/ 66941 Chassis/Package GF7W0401404 Engine No 4J11XS6664 Make/Model MIT/OUTLANDER 2.0 2WD CVT ELEGANCE (991) Colour/Trim D01 COSMIC BLUE / BK BLACK
31/08/2020	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	10/11/2020/ 17:09	BLC	260 / AiTing	56609
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
X DAM, TAILGATE, UPR		1.00	✓ 13.00	23.00	10.01
X GARNISH, TAILGATE		1.00	✓ 494.00	23.00	380.38
X W/STRIP, TAILGATE OPENING		1.00	✓ 213.00	23.00	164.01
X HANDLE, TAILGATE LOCK RLSE		1.00	✓ 202.00	23.00	155.54
X PANEL, QTR, OTR LH		1.00	✓ 1291.00	23.00	994.07
X GLASS, QTR WINDOW, LH		1.00	? 713.00	23.00	549.01
X PANEL, RR END		1.00	? 246.00	23.00	189.42
X MARK, OUTLANDER		1.00	✓ 95.00	23.00	73.15
X LAMP ASSY, COMB, RR LH		1.00	✓ 600.00	23.00	462.00
X LAMP ASSY, TAIL, LH		1.00	✓ 506.00	23.00	389.62
X FACE, FR BUMPER		1.00	✓ 859.00	23.00	661.43
X BRACKET, FR BUMPER SIDE, LH		1.00	✓ 18.00	23.00	13.86
X GARNISH, FR BUMPER, LH		1.00	✓ 75.00	23.00	57.75
X GARNISH, FR BUMPER SIDE		1.00	✓ 220.00	23.00	169.40
X GARNISH, FR BUMPER SIDE		1.00	✓ 112.00	23.00	86.24
X GARNISH, FR BUMPER SIDE		1.00	✓ 48.00	23.00	36.96
X GRILLE ASSY, RADIATOR		1.00	✓ 569.00	23.00	438.13
X HOOD		1.00	✓ 975.00	23.00	750.75
X INSULATOR, HOOD		1.00	✓ 133.00	23.00	102.41
X WEATHERSTRIP, HOOD		1.00	✓ 40.00	23.00	30.80
X WEATHERSTRIP, HOOD		1.00	✓ 41.00	23.00	31.57
X FENDER, FR LH		1.00	✓ 688.00	23.00	529.76
X SHIELD, FR WHEELHOUSE, LH		1.00	✓ 164.00	23.00	126.28
X PANEL, HEADLAMP SUPPORT, UPR		1.00	✓ 229.00	23.00	176.33
X HEADLAMP ASSY, LH		1.00	✓ 2125.00	23.00	1636.25
X REINFORCEMENT, FR BUMPER		1.00	? 490.00	23.00	377.30
X REINFORCEMENT, FR BUMPER		1.00	? 134.00	23.00	103.18
X REINF, FR BUMPER SIDE, LH		1.00	? 60.00	23.00	46.20
X COVER, HEADLAMP SUPT PANEL		1.00	? 50.00	23.00	38.50
X MOULDING, FR WHEEL ARCH, LH		1.00	? 168.00	23.00	129.36
X MOULDING, RR WHEEL ARCH, LH		1.00	168.00	23.00	129.36
X PNL, HEADLAMP SUPT, UPR LH		1.00	? 58.00	23.00	44.66
X PANEL, HEADLAMP SUPPORT, LH		1.00	58.00	23.00	44.66

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /Tay Hee Huat Reg No/Reg Date SJX9133X / 24/04/2018 Date In/Mileage 11/09/2020/ 66941 Chassis/Package GF7W0401404 Engine No 4J11XS6664 Make/Model MIT/OUTLANDER 2.0 2WD CVT ELEGANCE (991) Colour/Trim D01 COSMIC BLUE / BK BLACK
31/08/2020	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	10/11/2020/ 17:09	BLC	260 / AiTing	56609

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X REINFORCEMENT,RR BUMPER,LH	1.00	? 79.00	23.00	60.83
X TRIM,TAILGATE	1.00	? 329.00	23.00	253.33
X EXTENSION,QTR PANEL,OTR LH	1.00	? 276.00	23.00	212.52
X EXTN,QTR PANEL,RR LWR LH	1.00	? 78.00	23.00	60.06
X REINF,GATE PILLAR,LH → Supp.	1.00	250.00	23.00	192.50
X BOX,CARGO FLOOR	1.00	? 204.00	23.00	157.08
X TRIM,RR END	1.00	? 113.00	23.00	87.01
X REFLECTOR,TAIL LAMP,LH	1.00	? 100.00	23.00	77.00
X LAMP ASSY,TAIL,RH	1.00	? 506.00	23.00	389.62
X DUCT,RR VENTILATOR	1.00	? 39.00	23.00	30.03
X ARM ASSY,RR WINDOW WIPER	1.00	? 64.00	23.00	49.28
X BLADE ASSY,RR WINDOW WIPER	1.00	? 32.00	23.00	24.64
X HANDLE,TAILGATE PULL	1.00	18.00	23.00	13.86
X GROMMET,TAIL LAMP	1.00	3.00	23.00	2.31
X CLIP,RR BUMPER	10.00	3.00	23.00	23.10
X CLIP,ENG ROOM COVER	15.00	2.00	23.00	23.10
X EXTENSION,FR BUMPER	1.00	? 426.00	23.00	328.02
X LATCH,TAILGATE	1.00	? 383.00	23.00	294.91
X COVER,FR BUMPER	1.00	? 280.00	23.00	215.60
X TRIM,RR SHELF	1.00	? 672.00	23.00	517.44
X TRIM,QTR,UPR RH	1.00	? 333.00	23.00	256.41
X TRIM,QTR,UPR LH	1.00	? 333.00	23.00	256.41
X TRIM ASSY,QTR,LWR LH	1.00	? 402.00	23.00	309.54
Z TEXT				
AIG OD CLAIM				
DOA : 27.08.20				
SURVEYOR RASUL 31.08.20				
POLICY NO : 1800042163-01				
Guarantee Your Warranty, Maintain with Cycle & Carriage!				

Parts	15,189.02	Nett	25,484.02
Labour	9,765.00	7% GST on	1783.88
Standard Menu	0.00		
Specialist Job	270.00	Total Payable	27,267.90
Diagnostics Job	0.00		
Sundry/Others	260.00		
Total(w/o GST)	25,484.02		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.

INSURANCE CO. : **AIG**

Supplementary Parts For Registration No.: **SJX 9133 X**

<u>Materials</u>		<u>Cost (\$)</u>
1	Moulding, RR wheel arch, LH	168.00
2	Pane, Headlamp supoprt, LH	58.00
3	Reinf, gate pillar, LH	250.00
4	Handle, tailgate pull	18.00
5	Grommet, tail lamp	3.00
6	Clip (x10)	30.00
7	Clip (x15)	30.00
Total		557.00
Less 23%		128.11
Total Materials		428.89

<u>Labour</u>		<u>Cost (\$)</u>
1	Remove & install fuel tank to facilitate repair	225.00
Total Labour		225.00
Taxable Amount		653.89
7% GST		45.77
Grand total		<u>699.66</u>

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

LOI AI TING
SENIOR OFFICER - ADMIN
TEL: 6568 4556 / 6568 4501

CAR NO: SJX 4133X

Page. 1

WIP: 5609

(ADDITIONAL PARTS CHANGING)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Extension Front Bumper Scr ✓	? / SUPP			
2	Cover Front Bumper ca ✓	? / SUPP			
3	Reinforcement Front Bumper UPR Lt ✓	? / SUPP			
4	Reinforcement Front Bumper LWR Lt ✓	? / SUPP			
5	Reinforcement Front Bumper Side LH Lt ✓	? / SUPP			
6	Cover Headlamp Support Panel de ✓	? / SUPP			
7	Moulding Front Wheel Arch LH (M20) ✓	? / SUPP			
8	Panel Headlamp Support UPR Lt ✓	? / SUPP			
9	Panel Headlamp Support Side LH Lt ✓	? / SUPP			
10	Clip Cover Headlamp Support Panel 10x ✓	? / SUPP			
11	Clip Front & Rear Bumper 15x ne ✓	? / SUPP		07/09/2020	
12	Reinforcement Rear Bumper LH Lt ✓	? / SUPP			
13	Moulding Rear Wheel Arch LH ne ✓	? / SUPP			
14	Latch Tailgate ca ✓	? / SUPP			
15	Rear Inner Pillar LH Lt ✓	? / SUPP			6314A SSI
16	Ext'n QTR Panel OTR LH Lt ✓	? / SUPP			
17	Ext'n QTR Panel Rear LWR LH Lt ✓	? / SUPP			
18	Glass QTR Window LH ne ✓	? / SUPP			
19	Panel Rear End Lt ✓	? / SUPP			
20	Trim Tailgate de ✓	? / SUPP			

DATE	TAKEN BY

PHOTO BEFORE PAINT

PHOTO AFTER PAINT

PHOTO OF MOUNT TO CELLETTE BENCH

REMOVE AND INSTALL ENGINE

REMOVE AND INSTALL DASHBOARD

REMOVE & INSTALL FUEL TANK

PHOTO UNDERCARRIAGE PARTS

MODEL: carlander

SURVEYOR: Rasm

NO: SJX 9133XPage-2 WIP: 56609

(ADDITIONAL PARTS CHART)

Q	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Trim QTR UPR RH SEA	? / SUPP			
2	Trim Assy QTR LWR LH SEA	? / SUPP			
3	Trim QTR UPR LH SEA	? / SUPP			
4	Trim Rear End SEA	? / SUPP			
5	Box Cargo Floor SEA	? / SUPP			
6	Reflector Tail lamp LH SEA	? / SUPP			
7	Lamp Assy Tail RH SEA	? / SUPP			
8	Bracket Rear Window Wiper X	? / SUPP			
9	Cargo Cover SEA	? / SUPP		07/09/2020	
0	Air Duct Ventilator SEA	? / SUPP			
1	Plug Tail lamp 4x SEA	? / SUPP			
2	Arm Assy Rear Window Wiper SEA	? / SUPP			
3	Blade Assy Rear Window Wiper	? / SUPP			
4	Lift-Gate Pull Handle SEA	? / SUPP			
5	RLT fuel tank \$225	? / SUPP	14.9.2020		
6		? / SUPP			
7		? / SUPP			
8		? / SUPP			
9		? / SUPP			
0		? / SUPP			

DATE	TAKEN BY

PHOTO BEFORE PAINT

PHOTO AFTER PAINT

PHOTO OF MOUNT TO CELLETTE BENCH

REMOVE AND INSTALL ENGINE

REMOVE AND INSTALL DASHBAORD

REMOVE & INSTALL FUEL TANK

PHOTO UNDERCARRIAGE PARTS

MODEL: OutlanderSURVEYOR: Rasul

After using M.U.T. II OCS unit to Read & Clear All DTC.

2020.11.10

All DTCs

Setting	
Item	Information
M.U.T.-3 Version	SEW20011-00
V.C.I. Version	B177
Vehicle Information	DBA-GF7W 2017MY

All DTCs

All DTCs

	System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition		
	MPI/GDI/DIESEL	GAS_0E640000		No DTCs			
	Auto Stop & Go (AS&G)	ASG_25080000		No DTCs			
	AT/CVT/A-MT/TC-SST	CVT_14080300		No DTCs			
	AUTO CRUISE	GAS_0E640000		Non-target System			
	4WS/Electric Power Steering	EPS_45880040		No DTCs			
	ABS/ASC/ASTC/WSS	ASC_4208000F		No DTCs			
	SRS-AIR BAG	ORC_81047302		No DTCs			
	Air Conditioner	AC_80080011		No DTCs			
	ETACS	ETACS_83040801		No DTCs			
	Meter	MTR_84084001		No DTCs			
	Steering Angle Sensor	GS_SAS_47000100		Non-target System			
	AND	AND_8C080002		Non-equipped System or Communication Error			
	AUDIO (Display Audio)	AUDIO_8D080002		Non-equipped System or Communication Error			
	LIN	ETACS_83040801		Non-target System			
	Power Gate	ETG_92080000		Non-equipped System or Communication Error			

All DTCs

	System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name		Malfunction Condition
	KOS/IMMO/Keyless	KOS_8A880020		No DTCs		
	OSS	OSS_9588000B		No DTCs		
	CORNER SENSOR/SONAR	SONAR_9D080000		Non-equipped System or Communication Error		
	ACC/FCM	ACCSFCM_4B080000		Non-equipped System or Communication Error		
	Multi Around Monitor	CAMERA_94080100		Non-equipped System or Communication Error		
	Gateway	GW_C1000000		Non-equipped System or Communication Error		
	FCM/LDW/AHB	ADAS_4B080003		Non-equipped System or Communication Error		
	BSW	BSW_RAD_MASTER_A0080000		Non-equipped System or Communication Error		
	BSW(SUB)	BSW_RAD_SLAVE_A0080000		Non-equipped System or Communication Error		