

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

eg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info				
AIG Asia Pacific Insurance Pte.	Cust No/Name	KCV08372/Tay Hee Huat			
Ltd.	Reg No/Reg Date	SJX9133X / 24/04/201			
MOTOR CLAIM DEPARTMENT	Date In/Mileage	/ 0			
78 SHENTON WAY #08-16	Chassis No	GF7W0401404			
AIG BUILDING SINGAPORE 079120	Engine No	4J11XS6664			
Contact No 64191000	Make/Model	MIT/OUTLANDER 2.0 2WD CVT ELEGANCE			
	Colour/Trim	DO1 COSMIC BLUE / BK BLACK			


Account No	Terms	Date/Time Prin		SE Oper		ENGINEE S	WIP No	- Mar 10	
LAX00000	Credit	31/08/2020/ 1	AND THE RESERVE AND THE PARTY OF THE PARTY O	T0076	/ CocoLu		56609		
	3 00 19	Description of	f Goods / S	ervices	WEST TO SERVE	Qty	Unit Price	Disc%	Amount
REAR COMP E PNT88000 REMOVE & E PNT88000 REMOVE & M SUNDRY APPLY SEAL E PNT88000 REMOVE & I E PNT88000 REMOVE & I E PNT88000 SPRAY PAIN REAR FENDE SUNDRY APPLY SEAL SUNDRY C&C LOGO SUNDRY SUPPLY PARE SUNDRY REAR NUMBER PNT88000 RENEW FRT B FRT FENDER PNT88000	INSTALL I I INSTALL I I I I I I I I I I I I I I I I I I I	TAILGATE, RE REAR LAMP'HOU PARKING SENSOR TAILGATE GLASS TAILGATE GLASS TAILGATE TRIMS REAR COMPARTME REAR QUATAR GL EAR BUMPER, TA EAR LAMP HOUSI ACCIDENT PORI SOR Now WITH FRAME 14	EAR END PA USING LH,? R S SS ENT TRIMS LASS AILGATE, R ING LH,?	ANEL REAR FEND REAR END PANEL 8350 FRT SUPPORT	REAR COMPARTI	te		120,	2100 4050.00 60.00 240.00 80.00 180 308.00 120 160.00 80.00 120 160.00 80.00 120 160.00 100 80.00 100 80.00 80.00 80.00 100 80.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.





CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

eg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info				
AIG Asia Pacific Insurance Pte.	Cust No/Name	KCV08372/Tay Hee Huat			
Ltd.	Reg No/Reg Date	SJX9133X / 24/04/201			
MOTOR CLAIM DEPARTMENT	Date In/Mileage				
78 SHENTON WAY #08-16 AIG BUILDING	Chassis No	GF7W0401404			
SINGAPORE 079120	Engine No	4J11XS6664			
Contact No 64191000	Make/Mode1	MIT/OUTLANDER 2.0 2WD CVT ELEGANCE			
	Colour/Trim	DO1 COSMIC BLUE / BK BLACK			

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No	10000	Contract of the
LAX00000	Credit	0-700/2020/ 10:54	BLC	442 / CocoLu		56609		
A F4000000		Description of Good	ds / Services		Qty	Unit Price	Disc%	Amount
A 54900099	TNG & EI	ECTRICAL SYSTEM		1	-			30.00
A 10028901	KING & EL	ECIKICAL SYSTEM					900	' /
	OUT DIAG	SNOSTIC CHECK USING	HT CCAN DD	O TECT				120.00
USING HI-	SCAN PRO	TEST	III-SCAN PK	0 1521			23.00	/
E PNT98000		/ /					5.14	2100 2100 00
SPRAY PAI	NT FOR F	RT BUMPER, BONNET,	FRT SUPPOR	T PANEL			/	2100 2486.00
FKI FENDE	R LH & R	H, FRT DOOR LH.						
WHEELALIGN							1600	120.00
PNISSON		erize Full Wheel Al	a manufactured to a fine of the contract of th				1 272	
CLEAN AND	VACUUM	SHATTERED GLASSES	一八!	1000	几一		1 30	80.00
SUNDRY		SHATTERED GLASSES (211	110019	77(0)	1	1213=	40.00
APPLY SEAL	LANT FOR	FRT ACCIDENT PORTE	DD) (41	111111101	1110	7	× 1930	40.00
SUNDRY			<u> </u>		0		1 1	20.00
Sundry								1
SUNDRY	OTD LUD	27×10						Xna 402.00
FACE, RR BU	MDED AL	RH?XAA				1255 11.7		*
BRKT.R/BMP	R FACE S	SIDE, RH X SVL			1.00	807.00		621.39
BRKT, R/BMP	R FACE S	SIDE, LHAR			2.00	12.00		18.48 18.48
REINFORCEM	ENT, RR B	UMPER, LH ? 51			1.00		23.00	60.83
REINFORCEM	ENT, RR B	UMPER, RH ? XSV			1.00		23.00	
EXTENSION,	RR BUMPE	R de Yord			1.00	232.00		
MOULDING, RE	R BUMPER	,RH 2 X SUL			1.00	106.00	23.00	81.62
MOULDING, RE					1.00	106.00		100000000000000000000000000000000000000
PANEL ASSY,		GLASS New			1.00	984.00		
GLASS, TAILG					2.00		23.00	100
DAM, TAILGAT					1.00	654.00	23.00	
ASTENER, WI					4.00		23.00	150000000000000000000000000000000000000
DAM, TAILGAT					1.00		23.00	502500108
GARNISH, TAI					1.00	13.00	20.00	10.0

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

eg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info				
AIG Asia Pacific Insurance Pte.	Cust No/Name	KCV08372/Tay Hee Huat			
Ltd.	Reg No/Reg Date				
MOTOR CLAIM DEPARTMENT	Date In/Mileage				
78 SHENTON WAY #08-16 AIG BUILDING	Chassis No	GF7W0401404			
SINGAPORE 079120	Engine No	4J11XS6664			
Contact No 64191000	Make/Model	MIT/OUTLANDER 2.0 2WD CVT ELEGANCE			
	Colour/Trim	DO1 COSMIC BLUE / BK BLACK			

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No	0.3703970	Sales Sa
LAX00000	Credit	31/08/2020/ 10:54	BLC	442 / CocoLu		56609		A PROPERTY OF THE PARTY OF THE
M W/STRIP.1	TATLCATE	Description of Good	s / Services	S	Qty I	Jnit Price	Disc%	Amount
M LATCH, TAI	I GATE	OPENING New/			1.00	213.00		164.01/
		OCK RLSE COM			1.00	383.00		294.91
M PANEL, QTR	OTR IH	OCK RESECTA			1.00	202.00		155.54~
M EXTENSION	OTR PAN	EL, OTR LH ? 64/			1.00	1291.00		994.07/
M EXTN.OTR	PANEL RR	LWR LH ? L+/			1.00	276.00		212.52
M GLASS, OTR	WINDOW	IH 7 Nu			1.00		23.00	60.06
M PANEL RR	FND Z	andin St/			1.00	713.00		549.01
M PANEL RR	FND INP	RH = XVL			1.00	246.00		189.42-
M PANEL RR	FND INR	LH? KSVC			1.00	146.00		112.42
M FLOOR, RR	remir			prod.	1.00	146.00	3-75000000000000000000000000000000000000	112.42
M SHIELD.RR	WHEEL R	RRHXSUL	~ 1		1.00	751.00	E20240900	578.27
1 SHIELD.RR	WHEEL RI	(H 2 KJ4)	271	111/2/21/20	52.29		23.00	16.94
TRIM, TAIL	GATE ?	DEF	\mathcal{D}	ima	1.60		23.00	16.94
TRIM. TAIL	GATE UPR	TH 3 X2 NC			1 (4.66)	329.00		253.33.
TRIM. TATLO	SATE UPR	> 4SVC			1.00		23.00	56.21
TRIM. TAILG	ATE. UPR	RH ? XSVE			1.00		23.00	72.38
MARK, OUTLA	NDER NO	1					23.00	56.21
TRIM, QTR, U					1.00		23.00	73.15
TRIM ASSY,					1.00	333.00		256.41
TRIM, QTR, U					1.00		23.00	309.54
TRIM, RR SHE	ELF de	/			1.00		23.00	256.41
TRIM, RR EN	? de-						23.00	517.44
LID, CARGO F	LOOR BOX	7.XSVC			1.00 (13		23.00	94.71
BOX CARGO F	I DOD 7	0. /			1.00		23.00	227.15
DEEL ECTOD T	ATL LAME	DU 7 X 3VV					23.00	157.08
REFLECTOR T	ATI LAMP	,LHG ? CM			1.00		23.00	77.00
LAMP ASSY C	OMB RR I	H C/O			1.00		23.00	77.00
LAMP ASSY, C	OMP DD D	17 XSVC			1.00		23.00	462.00
LAMP ASSY, L.	TOENCE D	LATE ? XSVL			1.00		23.00	462.00
		COA!			1.00		23.00	26.18
LAMP ASSY, TA					1.00		23.00	389.62
LAMP ASSY, TA	AIL, LH U	7.101			1.00		23.00	389.6
BRACKET, RR W	VINDOW W.	IPER 'XNC			1.00	24.00	23.00	18.4

Confirm & accepted by

Vovernber, 2020 11:37 AM

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Page 3 of 5



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

MITSUBISHI MOTORS

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

eg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info				
AIG Asia Pacific Insurance Pte.	Cust No/Name	KCV08372/Tay Hee Huat			
Ltd.	Reg No/Reg Date	SJX9133X / 24/04/201			
MOTOR CLAIM DEPARTMENT	Date In/Mileage	/ 0			
78 SHENTON WAY #08-16 AIG BUILDING	Chassis No	GF7W0401404			
SINGAPORE 079120	Engine No	4J11XS6664			
Contact No 64191000	Make/Model	MIT/OUTLANDER 2.0 2WD CVT ELEGANCE			
	Colour/Trim	DO1 COSMIC BLUE / BK BLACK			

Account No	Terms	Date/Time Pri	nted	CSE	Operator		WIP No	W. T.	STATE OF THE PARTY
LAX00000	Credit	31/08/2020/		BLC	442 / Cocol	u	56609		
	NORTH THE	Description of	of Good	s / Services	5	Qty	Unit Price	Disc%	Amount
M MOTOR, RR	WINDOW V	IIPER ! KEVE	1			1.00	505.00	23.00	388.85
M ARM ASSY	, RR WINDO	W WIPER 7. SCA	. /			1.00	64.00	23.00	49.28
M BLADE AS	SY,RR WIN	DOW WIPER	uk '			1.00	32.00	23.00	24.64
M ANT, KEYL	ESS OPERA	TION, RR 7 KS	eve			1.00	96.00	23.00	73.92
M BUZZER,KI	EYLESS OF	ERATIO, RR 7 X				1.00	91.00	23.00	70.07
M HAKNESS,	KK BUMPER	. K300				1.00	84.00	23.00	64.68
M FACE, FR						1.00	859 1060.00	23.00	816.20
		SIDE, LH Mer				1.00	18.00	23.00	13.86
		ER 多 SUL				1.00	426.00	23.00	328.02
		, LH 60/	T. D			1.00	75.00	23.00	57.75
		DE, LWR LH 7	100	П		□1.00	6.00	23.00	4.62
		SIDECMIL	- (252	T ITAM	O 5 7.00	220.00	23.00	169.40
		SIDECO	_ (211	im	1.00	112.00	23.00	86.24
GARNISH, F	R BUMPER	SIDE CON				CT (7:19)	9 48.00	23.00	36.96
COVER, FR	ROWLER ?	che 211				1.00	280.00	23.00	215.60
REINFORCE	MENI, FR	BUMPER ? bf /				1.00	490 503.00		387.31
BAR, FR BU	MPER GUA	RD 7 KSVC				1.00	130.00	23.00	100.10
REINFORCE	MENI, FR	BUMPER . bt	SIL.			1.00	134.00	23.00	103.18
REINFURCE	MENI, FR	BMPR SIDE . Y	,			1.00		23.00	16.94
KEINF, FR	BUMPER S	KSVL 211				1.00	60.00	23.00	46.20
COVER, FR	SUMPER - 1	211	/			1.00	25.00	23.00	19.25
COVER, HEAL	LAMP SUP	T PANEL . 6+				1.00	50.00	23.00	38.50
GRILLE ASS	Y, RADIAT	OR CM/7	isuc			1.00	569.00	23.00	438.13
BRACKET, RA	DIATOR G	RILLE, LH . 7	.,			1.00	13.00	23.00	10.01
H0004/						1.00	975.00	23.00	750.75
HINGE, HOOD	,RHX>					1.00	68.00	23.00	52.36
HINGE, HOOD						1.00	68.00	23.00	52.36
INSULATOR,						1.00			102.4
LATCH, HOOD						1.00		23.00	58.52
WEATHERSTR:	IP, HOODM	W				1.00		23.00	30.8
WEATHERSTR	P, HOOD A	-/				1.00		23.00	31.5
FENDER, FR L						1.00		23.00	529.7
INSULATOR, F	R FENDER	IHX SVL				1.00		23.00	50.0


Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repairs work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

coudy, 17 November, 2020 11:37 AM

Mobile: +65 9877 7225





CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

ESTIMATE

Reg No : 197701469G	ESTIMATE	GST Reg No : MR-8500111-X			
Invoice Name & Address	Owner Name & Vehicle Info				
AIG Asia Pacific Insurance Pte.	Cust No/Name	KCV08372/Tay Hee Huat			
Ltd.	Reg No/Reg Date	SJX9133X / 24/04/201			
MOTOR CLAIM DEPARTMENT	Date In/Mileage	/ 0			
78 SHENTON WAY #08-16 AIG BUILDING	Chassis No	GF7W0401404			
SINGAPORE 079120	Engine No	4J11XS6664			
Contact No 64191000	Make/Model	MIT/OUTLANDER 2.0 2WD CVT ELEGANCE			
	Colour/Trim	DO1 COSMIC BLUE / BK BLACK			

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No		
LAX00000	Credit	31/08/2020/ 10:54	BLC	442 / CocoLu		56609		
	73	Description of Goo	ds / Services	PART TO SERVE	Qty U	Jnit Price	Disc%	Amount
M SHIELD, FR M MOULDING.	FR RUMPE	OUSE, LH CALXSVL			1.00	164.00	35.51 (0.010 0.000 0.00	126.28
M MOULDING.	FR WHFFI	ARCH, LH . de/			1.00	116.00	240-273-201-201-201-201-201-201-201-201-201-201	89.32
M PANEL HEA	DI AMP SI	IPPORT, UPR ST			1.00 168	199.00		153.23
M PANEL HEA	DI AMP SU	PPORT, LWR 7 XSVL			1.00	229.00	3245 G WWW.	176.33
A PNI HEADI	AMP SIIPT	IIDD I H			1.00	107.00	\$740 OK 1,000 OK	82.39
GARNISH,F	R DECK ?	XSUL			1.00	173.00	23.00	44.66
COVER, FR	DECK . I H	3.78Nr			1.00		23.00	133.21
HEADLAMP					1.00	2125.00	TO THE PERSON NAMED IN	14.63
LAMP ASSY	.FOG FR	LH 7 KSVL			1.00	348.00		1636.25
HORN THEE	T DDOTEC	TION Y					23.00	267.96
CONDENSER	ASSY.A/	C REFRIGE ? ASUC	O		55.00	857.00	Contract to the late of	70.84 659.89
DUCT, RR VI	ENTILATO	R7cm/	(271	ima	175623		23.00	33.88
RADIATOR A	ASSY ?X	sn	-D) [L]	1111111(0	1.00	1091.00	W20081 - PERSON	840.07
TANK ASSY.	RADIATO	R COND : KSOC	0 01		1.00	103.00	Demission Paragraph.	79.31
SHROUD, COO	LING FAI	12 +SVC			1.00	258.00		198.66
FAN, COOLIN	IG, LH 7	ISVI.			1.00		23.00	60.06
MOTOR, COOL	ING FAN.	LH(120W) 7 X5VL			1.00	479.00	Thursday Child	368.83
DUCT, A/CLN	R INTAKE	xsn "			1.00	187.00	CONTRACTOR CO.	143.99
COVER, AIR	CLEANER	(eve			1.00		23.00	120.12
BODY ASSY,	AIR CLEA	NER X SIL			1.00		23.00	112.42
BRACKET, AI	R CLEANE	RXSUC			1.00		23.00	
		OT BODY X & VC			1.00		23.00	53.90 123.97
750 V.S.S.W		,		Date - 16	90010018	101.00	23.00	123.97
			EYOR NAME:	Chi	Motogo			
		SURV	EYOR SIGNAT	TURE:				
		3011	2.1.6	1000 @ 1200				
		DATE	31/08	nne				
		57.1		> > lays				
		REMA	ARKS:	1			100	
Market Contract	10 10	VIII-		A	1			
firm & accep	oted by	-54 633	Ra	on be form	bodied	1	4	35,611.0
			Line par of			Ne	tt	24 057 1
					7% GST on	34957		2447.0
					Tot	al Payal	le	37,404.
norized sign								

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Exceptional Journeys

INSURANCE CO.: AIG

Supplementary Parts For Registration No.: SJX 9133 X

	<u>Materials</u>		<u>Cost (\$)</u>
1	Moulding, RR wheel arch, LH de/		168.00
2	Pane, Headlamp supoprt, LH bt /		58.00
3	Reinf, gate pillar, LH bt -		250.00
4	Handle, tailgate pull de /		18.00
5	Grommet, tail lamp nec		3.00
6	Clip (x10) nec /		30.00
7	Clip (x15) nec /		30.00
		Takal	EE7.00
		Total	557.00 438.44
		Less 23%	128.11
		Total Materials	428.89
	<u>Labour</u>		<u>Cost (\$)</u>
1	Remove & install fuel tank to facilitate re	epair	225.00 /
		Total Labour	225.00
		Taxable Amount	653.89
		7% GST	45.77
		Grand total	699.66

Thank You.

Yours faithfully CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

LOI AI TING SENIOR OFFICER - ADMIN TEL: 6568 4556 / 6568 4501