



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

g No : 197701469G

Invoice Name & Address

AIG Asia Pacific Insurance Pte.
 Ltd.
 MOTOR CLAIM DEPARTMENT
 78 SHENTON WAY #08-16
 AIG BUILDING
 SINGAPORE 079120
 Contact No 64191000

Owner Name & Vehicle Info

Cust No/Name KCV08372/Tay Hee Huat
 Reg No/Reg Date SJX9133X / 24/04/201
 Date In/Mileage / 0
 Chassis No GF7W0401404
 Engine No 4J11XS6664
 Make/Model MIT/OUTLANDER 2.0 2WD CVT ELEGANCE
 Colour/Trim DOI COSMIC BLUE / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	31/08/2020/ 10:54	BLC	442 / CocoLu	56609

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW REAR BUMPER, TAILGATE, REAR END PANEL REAR FENDER LH REAR COMPARTMENT, REAR LAMP HOUSING LH, ? 0450				2700 4050.00
E PNT88000 REMOVE & INSTALL PARKING SENSOR				60.00
E PNT88000 REMOVE & INSTALL TAILGATE GLASS				240.00
M SUNDRY APPLY SEALANT FOR TAILGATE GLASS				80.00
E PNT88000 REMOVE & INSTALL TAILGATE TRIMS	120.00	160		200.00
E PNT88000 REMOVE & INSTALL REAR COMPARTMENT TRIMS AND REAR FENDER TRIMS	120.00	180		300.00
E PNT88000 REMOVE & INSTALL REAR QUATAR GLASS				120 160.00
E PNT98000 SPRAY PAINT FOR REAR BUMPER, TAILGATE, REAR END PANEL, REAR COMPARTMENT REAR FENDER LH, REAR LAMP HOUSING LH, ? 0350				1750 2400.00
M SUNDRY APPLY SEALANT FOR ACCIDENT PORITON				80.00
M SUNDRY C&C LOGO				40.00
M SUNDRY SUPPLY PARKING SENSOR				220.00
M SUNDRY REAR NUMBER PLATE WITH FRAME 4				50.00
E PNT88000 RENEW FRT BUMPER, BONNET, FRT FENDER LH, FRT SUPPORT PANEL FRT FENDER RH, FRT DOOR LH,				1800 2250.00
E PNT88000 REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR				100.00
A 54900099 TOP UP AIRCON GAS				80.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

E & CARRIAGE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name KCV08372/Tay Hee Huat Reg No/Reg Date SJX9133X / 24/04/201 Date In/Mileage / 0 Chassis No GF7W0401404 Engine No 4J11XS6664 Make/Model MIT/OUTLANDER 2.0 2WD CVT ELEGANCE Colour/Trim D01 COSMIC BLUE / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	31/08/2020/ 10:54	BLC	442 / CocoLu	56609

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00
E PNT98000 SPRAY PAINT FOR FRT BUMPER, BONNET, FRT SUPPORT PANEL FRT FENDER LH & RH, FRT DOOR LH.				2100 2450.00
B WHEELALIGNMENT To Conduct Computerize Full Wheel Alignment				120.00
E PNT88000 CLEAN AND VACUUM SHATTERED GLASSES				80.00
M SUNDRY APPLY SEALANT FOR FRT ACCIDENT PORTION				40.00
M SUNDRY Sundry				20.00
M SUNDRY TRIM ASSY QTR LWR RH ? ✓				X 402.00?
M FACE,RR BUMPER de ✓	1.00	807.00	23.00	621.39
M BRKT,R/BMPR FACE SIDE,RH X	2.00	12.00	23.00	18.48
M BRKT,R/BMPR FACE SIDE,LH ✓	2.00	12.00	23.00	18.48
M REINFORCEMENT,RR BUMPER,LH ✓	1.00	79.00	23.00	60.83
M REINFORCEMENT,RR BUMPER,RH ? X	1.00	79.00	23.00	60.83
M EXTENSION,RR BUMPER de ✓	1.00	232.00	23.00	178.64
M MOULDING,RR BUMPER,RH ✓	1.00	106.00	23.00	81.62
M MOULDING,RR BUMPER,LH de ✓	1.00	106.00	23.00	81.62
M PANEL ASSY,TAILGATE ✓	1.00	984.00	23.00	757.68
M STOPPER,WINDSHIELD GLASS ✓	2.00	3.00	23.00	4.62
M GLASS,TAILGATE WINDOW ✓	1.00	654.00	23.00	503.58
P DAM,TAILGATE SIDE ✓	2.00	27.00	23.00	41.58
M FASTENER,WINDSHIELD ✓	4.00	6.00	23.00	18.48
M DAM,TAILGATE,UPR ✓	1.00	13.00	23.00	10.01
M GARNISH,TAILGATE de ✓	1.00	494.00	23.00	380.38

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

Reg No : 1977014696

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name KCV08372/Tay Hee Huat Reg No/Reg Date SJX9133X / 24/04/201 Date In/Mileage / 0 Chassis No GF7W0401404 Engine No 4J11XS6664 Make/Model MIT/OUTLANDER 2.0 2WD CVT ELEGANCE Colour/Trim D01 COSMIC BLUE / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	31/08/2020/ 10:54	BLC	442 / CocoLu	56609
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M W/STRIP, TAILGATE OPENING	✓	1.00	213.00	23.00	164.01
M LATCH, TAILGATE	✓	1.00	383.00	23.00	294.91
M HANDLE, TAILGATE LOCK RLSE	✓	1.00	202.00	23.00	155.54
M PANEL, QTR, QTR LH	✓	1.00	1291.00	23.00	994.07
M EXTENSION, QTR PANEL, QTR LH	✓	1.00	276.00	23.00	212.52
M EXTN, QTR PANEL, RR LWR LH	✓	1.00	78.00	23.00	60.06
M GLASS, QTR WINDOW, LH	✓	1.00	713.00	23.00	549.01
M PANEL, RR END	✓	1.00	246.00	23.00	189.42
M PANEL, RR END, INR RH	✓	1.00	146.00	23.00	112.42
M PANEL, RR END, INR LH	✓	1.00	146.00	23.00	112.42
M FLOOR, RR	✓	1.00	751.00	23.00	578.27
M SHIELD, RR WHEEL, RR RH	✓	1.00	22.00	23.00	16.94
M SHIELD, RR WHEEL, RR LH	✓	1.00	22.00	23.00	16.94
M TRIM, TAILGATE	✓	1.00	329.00	23.00	253.33
M TRIM, TAILGATE, UPR LH	✓	1.00	73.00	23.00	56.21
M TRIM, TAILGATE, UPR	✓	1.00	94.00	23.00	72.38
M TRIM, TAILGATE, UPR RH	✓	1.00	73.00	23.00	56.21
M MARK, OUTLANDER	✓	1.00	95.00	23.00	73.15
M TRIM, QTR, UPR RH	✓	1.00	333.00	23.00	256.41
M TRIM ASSY, QTR, LWR LH	✓	1.00	402.00	23.00	309.54
M TRIM, QTR, UPR LH	✓	1.00	333.00	23.00	256.41
M TRIM, RR SHELF	✓	1.00	672.00	23.00	517.44
M TRIM, RR END	✓	1.00	113.00	123.00	94.71
M LID, CARGO FLOOR BOX	✓	1.00	295.00	23.00	227.15
M BOX, CARGO FLOOR	✓	1.00	204.00	23.00	157.08
M REFLECTOR, TAIL LAMP, RH	✓	1.00	100.00	23.00	77.00
M REFLECTOR, TAIL LAMP, LH	✓	1.00	100.00	23.00	77.00
M LAMP ASSY, COMB, RR LH	✓	1.00	600.00	23.00	462.00
M LAMP ASSY, COMB, RR RH	✓	1.00	600.00	23.00	462.00
M LAMP ASSY, LICENSE PLATE	✓	1.00	34.00	23.00	26.18
M LAMP ASSY, TAIL, RH	✓	1.00	506.00	23.00	389.62
M LAMP ASSY, TAIL, LH	✓	1.00	506.00	23.00	389.62
M BRACKET, RR WINDOW WIPER	✓	1.00	24.00	23.00	18.48

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

Reg No : 1977014696

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name KCV08372/Tay Hee Huat Reg No/Reg Date SJX9133X / 24/04/201 Date In/Mileage / 0 Chassis No GF7W0401404 Engine No 4J11XS6664 Make/Model MIT/OUTLANDER 2.0 2WD CVT ELEGANCE Colour/Trim D01 COSMIC BLUE / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	31/08/2020/ 10:54	BLC	442 / CocoLu	56609
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M MOTOR,RR WINDOW WIPER ?	✓	1.00	505.00	23.00	388.85
M ARM ASSY,RR WINDOW WIPER ?	✓	1.00	64.00	23.00	49.28
M BLADE ASSY,RR WINDOW WIPER ?	✓	1.00	32.00	23.00	24.64
M ANT,KEYLESS OPERATION,RR ?	✓	1.00	96.00	23.00	73.92
M BUZZER,KEYLESS OPERATIO,RR ?	✓	1.00	91.00	23.00	70.07
M HARNESS,RR BUMPER ?	✓	1.00	84.00	23.00	64.68
M FACE,FR BUMPER ?	✓	1.00	1060.00	23.00	816.20
M BRACKET,FR BUMPER SIDE,LH ?	✓	1.00	18.00	23.00	13.86
M EXTENSION,FR BUMPER ?	✓	1.00	426.00	23.00	328.02
M GARNISH,FR BUMPER,LH ?	✓	1.00	75.00	23.00	57.75
M BRKT,FR BUMPER SIDE,LWR LH ?	✓	1.00	6.00	23.00	4.62
M GARNISH,FR BUMPER SIDE ?	✓	1.00	220.00	23.00	169.40
M GARNISH,FR BUMPER SIDE ?	✓	1.00	112.00	23.00	86.24
M GARNISH,FR BUMPER SIDE ?	✓	1.00	48.00	23.00	36.96
M COVER,FR BUMPER ?	✓	1.00	280.00	23.00	215.60
M REINFORCEMENT,FR BUMPER ?	✓	1.00	503.00	23.00	387.31
M BAR,FR BUMPER GUARD ?	✓	1.00	130.00	23.00	100.10
M REINFORCEMENT,FR BUMPER ?	✓	1.00	134.00	23.00	103.18
M REINFORCEMENT,FR BMPR SIDE ?	✓	1.00	22.00	23.00	16.94
M REINF,FR BUMPER SIDE,LH ?	✓	1.00	60.00	23.00	46.20
M COVER,FR BUMPER ?	✓	1.00	25.00	23.00	19.25
M COVER,HEADLAMP SUPT PANEL ?	✓	1.00	50.00	23.00	38.50
M GRILLE ASSY,RADIATOR ?	✓	1.00	569.00	23.00	438.13
M BRACKET,RADIATOR GRILLE,LH ?	✓	1.00	13.00	23.00	10.01
M HOOD ?	✓	1.00	975.00	23.00	750.75
M HINGE,HOOD,RH ?	✓	1.00	68.00	23.00	52.36
M HINGE,HOOD,LH ?	✓	1.00	68.00	23.00	52.36
M INSULATOR,HOOD ?	✓	1.00	133.00	23.00	102.41
M LATCH,HOOD ?	✓	1.00	76.00	23.00	58.52
M WEATHERSTRIP,HOOD ?	✓	1.00	40.00	23.00	30.80
M WEATHERSTRIP,HOOD ?	✓	1.00	41.00	23.00	31.57
M FENDER,FR LH ?	✓	1.00	688.00	23.00	529.76
M INSULATOR,FR FENDER,LH ?	✓	1.00	65.00	23.00	50.05

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name KCV08372/Tay Hee Huat Reg No/Reg Date SJX9133X / 24/04/201 Date In/Mileage / 0 Chassis No GF7W0401404 Engine No 4J11XS6664 Make/Model MIT/OUTLANDER 2.0 2WD CVT ELEGANCE Colour/Trim D01 COSMIC BLUE / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	31/08/2020/ 10:54	BLC	442 / CocoLu	56609
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M SHIELD,FR WHEELHOUSE,LH		1.00	164.00	23.00	126.28
M MOULDING,FR BUMPER,LH		1.00	116.00	23.00	89.32
M MOULDING,FR WHEEL ARCH,LH		1.00	168.00	19.00	153.23
M PANEL,HEADLAMP SUPPORT,UPR		1.00	229.00	23.00	176.33
M PANEL,HEADLAMP SUPPORT,LWR		1.00	107.00	23.00	82.39
M PNL,HEADLAMP SUPT,UPR LH		1.00	58.00	23.00	44.66
M GARNISH,FR DECK		1.00	173.00	23.00	133.21
M COVER,FR DECK,LH		1.00	19.00	23.00	14.63
M HEADLAMP ASSY,LH		1.00	2125.00	23.00	1636.25
M LAMP ASSY,FOG,FR LH		1.00	348.00	23.00	267.96
M HORN,THEFT PROTECTION		1.00	92.00	23.00	70.84
M CONDENSER ASSY,A/C REFRIGE		1.00	857.00	23.00	659.89
M DUCT,RR VENTILATOR		1.00	3944.00	23.00	33.88
M RADIATOR ASSY		1.00	1091.00	23.00	840.07
M TANK ASSY,RADIATOR COND		1.00	103.00	23.00	79.31
M SHROUD,COOLING FAN		1.00	258.00	23.00	198.66
M FAN,COOLING,LH		1.00	78.00	23.00	60.06
M MOTOR,COOLING FAN,LH(120W)		1.00	479.00	23.00	368.83
M DUCT,A/CLNR INTAKE		1.00	187.00	23.00	143.99
M COVER,AIR CLEANER		1.00	156.00	23.00	120.12
M BODY ASSY,AIR CLEANER		1.00	146.00	23.00	112.42
M BRACKET,AIR CLEANER		1.00	70.00	23.00	53.90
M DUCT,A/CLNR TO THROT BODY		1.00	161.00	23.00	123.97

LKK Auto Consultants hence notify the Repairer of the following:
 • To rectify damaged part(s) during repair
 • To display damaged part(s) during repair
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

SURVEYOR NAME: Rasul - Hp 90010068
 SURVEYOR SIGNATURE: [Signature]
 DATE: 31/08/2020 @ 1200
 REMARKS: 20 days

Confirm & accepted by

Rasul before print

Nett 34,957.16
 7% GST on 34957.16 2447.00
 Total Payable 37,404.16

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

INSURANCE CO. : AIG

Supplementary Parts For Registration No.: SJX 9133 X

<u>Materials</u>		<u>Cost (\$)</u>
1	Moulding, RR wheel arch, LH	168.00 ✓
2	Pane, Headlamp supoprt, LH	58.00 ✓
3	Reinf, gate pillar, LH	250.00 ✓
4	Handle, tailgate pull	18.00 ✓
5	Grommet, tail lamp	3.00 ✓
6	Clip (x10)	30.00 ✓
7	Clip (x15)	30.00 ✓
Total		557.00
Less 23%		128.11
Total Materials		428.89

<u>Labour</u>		<u>Cost (\$)</u>
1	Remove & install fuel tank to facilitate repair	225.00
Total Labour		225.00
Taxable Amount		653.89
7% GST		45.77
Grand total		<u><u>699.66</u></u>

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

LOI AI TING
SENIOR OFFICER - ADMIN
TEL: 6568 4556 / 6568 4501