

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chhia Nyuk Pui

Date: 07 Sep 2020

Preliminary Advice

Insured Vehicle No	: SLR1393Y		
TP Vehicle No	: SMP2320A	Accident Date	: 30/08/2020
Make	: MAZDA CX-5	Assignment Date	: 31/08/2020
Date of Inspection	: 31/08/2020	Est. Duration of Repair	: 4
Inspection At	: ZOOM AUTOWERKS PTE LTD (HQ) 15 KAKI BUKIT ROAD 4, #01-53 SINGAPORE 417808		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,411.87
Revised Amount	:S\$	5,413.92
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,413.92
Lump Sum Repair	:S\$	4,300.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- (x) Lump Sum repair

- () The above survey was conducted on a 'without prejudice' basis.