

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
18 SIN MING LANE #01-08 MIDVIEW CITY
SINGAPORE 573960

Contact : 66550005-GRAB 84815758

ESTIMATE

Repair Code : CLM16404

Date in : 28/08/2020

Vehicle Num. : SLS7187G

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31242352/LEB5942371

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER / DEF	1	762.70	762.70
REAR BUMPER RH REFLECTOR / BR	1	141.10	141.10
REAR BUMPER SIDE COVER L/R CRH / DEF	2	195.00	390.00
REAR BUMPER SIDE RETAINER L/R / 1	2	23.00	46.00
REAR BUMPER UNDER COVER / CRH	1	250.00	250.00
REAR END PANEL x R	1	415.60	415.60
REAR END PANEL BUZZLE SENSOR / BR	1	85.20	85.20
REAR END PANEL INNER TOP GARNISH x	1	98.00	98.00
REAR RH FENDER ARCH GARNISH / BR	1	195.00	195.00
REAR RH TAILLAMP x	1	474.60	474.60
REAR RH TAILLAMP INNER BLACK GASKET x	1	38.50	38.50
REAR TAILGATE / DR	1	953.30	953.30
REAR TAILGATE 'HYBRID' EMBLEM / MC	1	75.80	75.80
REAR TAILGATE 'VEZEL' EMBLEM / MC	1	56.20	56.20
REAR TAILGATE HINGES L/R x	2	50.00	100.00
REAR TAILGATE INNER TRIM BOARD / CRH	1	153.40	153.40
REAR TAILGATE LOCK STRIKER x	1	27.50	27.50
REAR TAILGATE MECHANISM LOCK / BT	1	180.00	180.00

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
18 SIN MING LANE #01-08 MIDVIEW CITY
SINGAPORE 573960

Contact : 66550005-GRAB 84815758

ESTIMATE

Repair Code : CLM16404
Date in : 28/08/2020
Vehicle Num. : SLS7187G
Model : HONDA VEZEL HYBRID 1.5X AUTO
Chassis/Eng# : RU31242352/LEB5942371

REAR TAILGATE RH REFLECTOR X	1	413.20	413.20
REAR TAILGATE RH REFLECTOR INNER BLACK GASKET X	1	38.50	38.50
REAR TAILGATE WEATHER STRIP / CR4	1	96.80	96.80
REAR TAILGATE WINDSCREEN / DR	1	1350.00	1,350.00
REAR TAILGATE WINDSCREEN INNER SIDE GARNISH L/R / CNT	2	56.00	112.00
REAR TAILGATE WINDSCREEN INNER TOP GARNISH / CNT	1	69.00	69.00
REAR TAILGATE WINDSCREEN MOULDING L/R / MC	2	50.00	100.00
REAR TAILGATE WINDSCREEN MOULDING T/L / MC	2	50.00	100.00

Subtotal before discount

Percentage discount 20%

Sub-total 1

REAR BUMPER CLIPS - SET / MC	1	30	80.00	80.00
REAR BUMPER REVERSE SENSOR - SET / Shm	1	300	300.00	300.00
REAR RH FENDER ARCH GARNISH CLIPS - SET / MC	2	20	40.00	80.00
REAR RH TAILLAMP CLIPS - SET X	1		25.00	25.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET / MC	1	20	50.00	50.00
REAR TAILGATE NUMBER PLATE X	1		25.00	25.00
REAR TAILGATE NUMBER PLATE HOLDER X	1		50.00	50.00

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
18 SIN MING LANE #01-08 MIDVIEW CITY
SINGAPORE 573960

Contact : 66550005-GRAB 84815758

ESTIMATE

Repair Code : CLM16404
Date in : 28/08/2020
Vehicle Num. : SLS7187G
Model : HONDA VEZEL HYBRID 1.5X AUTO
Chassis/Eng# : RU31242352/LEB5942371

REAR TAILGATE WINDSCREEN SEALANT ✓ MC	1	69	80.00	80.00
				690.00
				0.00
Subtotal before discount				690.00
Percentage discount 0%				0.00
				690.00
Sub-total 2				6,067.92
Parts-total				

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	39	80.00
To remove, reinstall tailgate windscreen	120	150.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	50	140.00
To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.	700	1,000.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	450	1,000.00
To apply anti-rust chemical on repaired and replaced panel.	30	80.00
To remove, reinstall tailgate mechanism and check for function	30	80.00
		2,530.00
		8,597.92

Steve (LKK) MC ML
83228813

31/8/20, 1.79pm

Labour Total

Parts & Labour Total

*** This is a computer-generated document. Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4 dy
L/S
My AL My