

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 47433

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0617/2020/NS
Date : 31-Aug-20

Vehicle IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

*Hi Adrian,
12 days - ok - Jy - 31 Dec 20*

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Lam Pek Ying
Address : 3 Pasir Ris View
Singapore 518586
Telephone : HP +65 91899940
Type of Claim : Own Damage Claims
Policy No. : 2100468761-04
Vehicle No : **SLC 8775 L**
Model Code : Audi A3 Sedan 1.4 TFSI
Model / Year : May-16
Engine No : CZC 540605
Chassis No : WAUZZZ8V5G1089776
Mileage : 109608KM
Date In : 31/08/2020
Estimated By : Johnny Boo / Allan Wu
Accident Date : 31-Aug-20
Place of Accident : Paya Lebar Road And Ubi Junction

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLC 8775 L

S/N	Nature of Jobs		Estimated Charges		Surveyor's Recommendations
1	To remove, check and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N	\$ 280.00	\$	280.00
2	To remove and transfer lhs headlight control unit and power module.	S/N	\$ 350.00	\$	250.00
3	To remove and renew aircon condenser, additional radiator and radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N	\$ 1,200.00	\$	1,200.00
4	To dismantle and reinstall lhs front door panel trim. To remove and reinstall lhs wing mirror assy.	S/N	\$ 350.00	\$	280.00
5	To dismantle and renew front bumper, bonnet, lhs front fender and lhs headlight. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.		\$ 4,900.00	\$	2,750.00
6	To respray front bumper, bonnet, lhs front fender, lhs front door and lhs upper A-pillar.		\$ 4,700.00	\$	2,200.00
7	To tow back vehicle from accident scene.	S/N	\$ 280.00		
	SUPPLEMENTARY		\$ 1,700.00	\$	600.00
8	To carry out pre-diagnostic check and post-diagnostic check.	S/N	\$ 384.00	\$	384.00
TOTAL LABOUR CHARGES		:	\$ 14,144.00	\$	7,944.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLC 8775 L

S/N	Parts Description	Damage Parts & Prices		
			S/Nett	Remarks
1	FRONT BUMPER	\$	1,987.00	\$ 1,589.60
2	FRONT BUMPER FIXING PARTS	\$	185.00	
3	FRONT BUMPER COVER TRIM - LH	\$	161.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$	161.00	
5	FRONT BUMPER PULL STRAP - LOWER	4 \$	204.00	
6	FRONT BUMPER GUIDE SECTION - LH	\$	38.00	\$ 30.16
7	FRONT BUMPER AIR GUIDE GRILLE - LH	\$	108.00	\$ 86.00
8	RADIATOR GRILLE	\$	683.00	
9	RADIATOR GRILLE COVER	\$	97.00	
10	CAUTION SIGN STICKER	NEC \$	14.00	
11	AIRCON STICKER	NEC \$	8.00	
12	FRONT BUMPER SIDE REINFORCEMENT BEAM	\$	715.00	\$ 571.60
13	FRONT BUMPER FOAM FILLER PIECE	\$	136.00	\$ 108.40
14	FOAM FILLER PIECE COVER	\$	55.00	
15	SIGNAL HORN - LH LOW TONE	\$	197.00	\$ 157.60
16	FRONT FENDER - LH	\$	841.00	\$ 672.80
17	FRONT FENDER ATTACHMENT PARTS	\$	71.00	
18	FRONT FENDER BRACKET - LH	\$	27.00	\$ 21.52
19	FRONT FENDER BRACKET	\$	38.00	\$ 30.40
20	FRONT FENDER BRACE	\$	95.00	\$ 75.68
SUB TOTAL SPARE PARTS CHARGES		:	\$ 5,821.00	\$ 3,343.76

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLC 8775 L

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
			\$ 3,343.76
21	WHEEL HOUSING LINER SEAL - LH UPPER	\$ 34.00	
22	WHEEL HOUSING LINER - LH	\$ 167.00	\$ 133.20
23	WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 88.00	
24	BONNET	\$ 3,134.00	\$ 2,507.20
25	BONNET ATTACHMENT PARTS	\$ 163.00	
26	BONNET LID HINGE - LH / RH	2 \$ 122.00	
27	BONNET CATCH HOOK	\$ 89.00	
28	BONNET STRIKER	\$ 109.00	
29	BONNET EDGE PROTECTION - FRONT	\$ 28.00	\$ 21.84
30	BONNET COVER - LH	2 \$ 41.00	
31	BONNET LID LOCK	\$ 212.00	
32	BONNET SOUND ABSORBER	\$ 217.00	
33	HEADLIGHT - LH	2 \$ 1,969.00	\$ 1,575.20
34	DAY DRIVING LIGHTS POWER MODULE	\$ 540.00	\$ 431.60
35	GAS DISCHARGE LAMP CONTROL UNIT	\$ 1,084.00	\$ 867.20
36	GAS DISCHARGE LAMP	2 \$ 408.00	\$ 326.40
37	HEADLIGHT HOSE - LH	\$ 51.00	
38	HEADLAMP HOUSING REPAIR KIT	\$ 130.00	
39	HEADLAMP HOUSING REPAIR KIT - REAR INNER	\$ 130.00	
40	LIFT CYLINDER - LH	\$ 190.00	\$ 152.00
SUB TOTAL SPARE PARTS CHARGES		\$ 8,906.00	\$ 9,358.40

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLC 8775 L

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
			\$ 9,358.40
41	LIFT CYLINDER HOSE	\$ 175.00	
42	WASH WATER RESERVOIR	\$ 202.00	\$ 161.20
43	LOCK CARRIER	\$ 719.00	\$ 575.20
44	AIRCON CONDENSER	\$ 517.00	
45	TEMPERATURE SENSOR BRACKET	\$ 18.00	
46	READY MIX COOLANT	\$ 91.00	
47	RADIATOR AIR GUIDE - LH	\$ 24.00	
48	WATER DEFLECTOR STRIP - LH	\$ 92.00	\$ 72.32
49	FRONT WINDOW SLOT SEAL - LH	\$ 305.00	
50	WINDOW GUIDE TRIM STRIP - LH	\$ 254.00	
51	FRONT NO PLATE	S/N \$ 60.00	
	SUPPLEMENTARY	\$ 121.00	\$ 96.80
52	SUNDRIES	\$ 350.00	\$ 53.36
TOTAL SPARE PARTS CHARGES		: \$ 17,655.00	\$ 10,317.28
TOTAL LABOUR CHARGES		: \$ 14,144.00	\$ 7,944.00
GRAND TOTAL		: \$ 31,799.00	\$ 18,261.28

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0617/2020/NS 03-Sep-20 Glory Tan 1 OF 1 SLC 8775 L Audi A3 Sedan 1.4 TFSI	
Quantity	Description	Unit Price	Amount	
<u>Parts</u> 1	Windscreen washer pump	\$ 121.00	\$ 96.80	
<u>Labours</u> 1	To repair lhs front fender top support.	\$ 700.00	\$ 250.00	
2	To respray lhs front fender top support.	\$ 1,000.00	\$ 350.00	
TOTAL		\$ 1,821.00	\$696.80	

For Premium Automobiles Pte Ltd

Authorised Signature