

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 47312

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0615/2020/NS
Date	:	31-Aug-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Lee Keng Cheong
Address	:	Blk 239 Hougang Street 22 #03-09 Singapore 530239
Telephone	:	HP +65 96260506
Type of Claim	:	Own Damage Claims
Policy No.	:	2070031096
Vehicle No	:	SMS 5406 B
Model Code	:	Audi A6 Design 2.0 TFSI S
Model / Year	:	28/2/2020
Engine No	:	DLH 065932
Chassis No	:	WAUZZZF25LN018377
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	28-Aug-20
Place of Accident	:	Jalan Buroh

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMS 5406 B

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To dismantle and reinstall lhs front door panel trim. To remove and renew lhs wing mirror assy.	S/N \$ 400.00	✓✓
2	To install solar film on lhs front door mirror glass.	S/N \$ 400.00	✓60
3	To repair lhs front fender. Re-organise crash management components. Reinstall all parts removed.	\$ 800.00	250 ✓
4	To respray lhs front fender, lhs front door, lhs rear door and lhs wing mirror cover.	\$ 3,500.00	1100 ✓
5	To carry out diagnostic check.	S/N \$ 192.00	✓✓
TOTAL LABOUR CHARGES		: \$ 5,292.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMS 5406 B

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	EXTERIOR MIRROR MOUNTING - LH <i>cut</i>	\$ 1,391.00	✓ 1112.80
2	MIRROR CAP - LH <i>new</i>	\$ 303.00	+
3	MIRROR GLASS - LH <i>?</i>	\$ 1,196.00	? X NN
4	B PILLAR TRIM - LH <i>cut</i>	\$ 172.00	✓ 137.60
5	B PILLAR TRIM - LH <i>new</i>	\$ 169.00	+
6	FRONT DOOR WINDOW - LH <i>cut</i>	\$ 324.00	✓ 258.80
7	SUNDRIES <i>?</i>	\$ 200.00	? 2.88 ✓ NEC
TOTAL SPARE PARTS		:	\$ 3,755.00
TOTAL LABOUR CHARGES		:	\$ 5,292.00
GRAND TOTAL		:	\$ 9,047.00

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved


Spare parts are Special Price.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adnan
Surveyed Date : 01/08/20
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorized, 04 days.



Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant