



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

AUTO & GENERAL INSURANCE (S) PL
(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

INV No. AC2007019
INV Date 16/10/2020
Reference CS/AGI20009188/Avf3q2
Code AGI



PROFESSIONAL SERVICE FEE

Vehicle No. SKA 1429E
Insured Veh. SLL 4303U
Claim No. C10007144
Policy No.
Accident Date 29/08/2020
Inspection Date 01/09/2020

Description	Total
Survey Inspection	250.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	250.00
GST (7%)	17.50
Grand Total	267.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI20009188/Avf3q2

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHOPPING CENTRESINGAPORE

239924

Date : 16-10-2020



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLL 4303U	Veh. Inspected	SKA 1429E
Policy No.		Coverage (\$)	0.00
Claim No.	C10007144	Excess (\$)	0.00
Assign From	IVY RATILLA	Assign Date	31/08/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	MR053REE104111145	Colour	BLUE
Odometer	138520	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/55 R16	LEAO	6 mm
L/H Front Tyre	195/55 R16	LEAO	6 mm
R/H Rear Tyre	195/55 R16	LEAO	6 mm
L/H Rear Tyre	195/55 R16	LEAO	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	29/08/2020	Inspection Date	01/09/2020
Survey held at	HUA MENG SPRAY PAINTING WORKSHOP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKA 1429E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BOOTLID	BUCKLED	754.70	754.70
2	REAR BOOTLID HINGES @\$56.40	NOT NECESSARY	112.80	-
1	REAR BOOTLID UPPER LOCK	DAMAGED	105.60	105.60
1	REAR BOOTLID LOWER LOCK	NOT NECESSARY	29.60	-
1	REAR BOOTLID WEATHER STRIP	CUT	205.20	205.20
1	REAR BOOTLID HANDLE	NOT NECESSARY	350.50	-
1	REAR BOOTLID CENTRE EMBLEM	NECESSARY	58.30	58.30
1	REAR BOOTLID 1.6 EMBLEM	NECESSARY	32.50	32.50
1	REAR BOOTLID DUEL EMBLEM	NECESSARY	46.60	46.60
1	REAR BOOTLID VVTI EMBLEM	NECESSARY	46.60	46.60
1	REAR BOOTLID COROLLA EMBLEM	NECESSARY	46.60	46.60
1	REAR BOOTLID ALTIS EMBLEM	NECESSARY	46.60	46.60
2	REAR BOOTLID REFLECTOR @\$161.50	NOT NECESSARY	323.00	-
2	REAR LAMP @\$480.00	O/S CRACKED	960.00	386.00
2	REAR LAMP HOUSING @\$84.10	TO REPAIR SEE LABOUR	168.20	-
2	REAR LAMP LOWER BRACKET @\$88.90	NOT NECESSARY	177.80	-
1	REAR END PANEL	DENTED	668.90	586.00
1	REAR END PANEL TOP GARNISH	DEFORMED	202.70	202.70
1	REAR BUMPER	DEFORMED	486.50	486.50
2	REAR BUMPER SIDE RETAINER @\$70.40	NECESSARY	145.40	145.40
2	REAR BUMPER BRACKET @\$87.10	DENTED	174.20	174.20
2	REAR BUMPER LOWER REFLECTOR @\$37.20	N/S CUT	74.40	37.20
1	SET REAR BUMPER CLIPS	NECESSARY	60.00	30.00
1	REAR BUMPER SPONGE	CRACKED	123.50	123.50
1	REAR SPARE TYRE TOP BOARD	TORN	276.60	276.60
2	REAR FENDER INNER TRIM @\$351.70	NOT NECESSARY	703.40	-
	LESS 25% DISCOUNT		-1,595.05	-947.70
			4,785.15	2,843.10
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	380.00	200.00

Report Ref No. CS/AGI20009188/Avf3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR CAMERA (SN)	NOT NECESSARY	500.00	-
			880.00	200.00
	LABOUR			
	TO SUPPLY REAR END PANEL INNER SEALANT .		200.00	60.00
	REMOVE & REINSTALL BOOTLID INNER GARNISH .		200.00	80.00
	REMOVE & REINSTALL REVERSE SENSOR .		150.00	50.00
	REMOVE & REINSTALL CAMERA.		100.00	50.00
	REMOVE,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT.INCLUSIVE OF THE REPAIR OF REAR LAMP HOUSING.		1,200.00	800.00
	RESPRAY PAINTING.		1,000.00	800.00
	TUFF KOTE.		100.00	60.00
	REMOVE AND REINSTALL UPHOLSTERY .		150.00	80.00
			3,100.00	1,980.00
GRAND TOTAL			8,765.15	5,023.10
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,000.00

Report Ref No. CS/AGI20009188/Avf3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKA 1429E

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKA 1429E

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

