

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

HAMSTER CAR RENTAL PTE LTD
8 BURN ROAD #15-13 TRIVER
SINGAPORE 369977

Contact : 91750993

TP Chiam
Shirley

ESTIMATE

Repair Code : CLM16402

Date in : 31/08/2020

Vehicle Num. : SLF7505R

Model : HONDA VEZEL HYBRID 1.5X A

Chassis/Eng# : RU31210061/LEB5910071

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
AIRCON CONDENSER <i>dent</i>	1	568.10	✓ 568.10
AIRCON CONDENSER ALUMINIUM PIPE	1	195.00	+ 195.00
AIRCON CONDENSER DISCHARGE PIPE <i>Altera Bent</i>	1	210.00	+ 210.00
FRONT BONNET <i>dent</i>	1	892.30	✓ 892.30
FRONT BONNET HINGES L/R <i>Altera Bent</i>	2	48.50	✓ 97.00
FRONT BONNET INNER RUBBER GUIDE STOPPER L/R <i>new</i>	2	23.80	+ 47.60
FRONT BONNET INNER SIDE MOULDING L/R	2	37.50	+ 75.00
FRONT BONNET INNER TOP MOULDING L/R <i>new</i>	2	23.00	+ 46.00
FRONT BONNET INSULATOR	1	122.30	+ 122.30
FRONT BONNET MECHANISM LOCK <i>Dented</i>	1	95.00	✓ 95.00
FRONT BUMPER <i>dent</i>	1	801.70	✓ 801.70
FRONT BUMPER FOGLAMP BRACKET L/R	2	48.00	+ 96.00
FRONT BUMPER FOGLAMP GARNISH L/R <i>new</i>	2	45.00	+ 90.00
FRONT BUMPER FOGLAMP L/R <i>new</i>	2	327.70	+ 655.40
FRONT BUMPER LOWER GRILLE <i>crack</i>	1	77.50	✓ 77.50
FRONT BUMPER LOWER LID <i>torn</i>	1	381.00	✓ 381.00
FRONT BUMPER REINFORCEMENT <i>Bent</i>	1	321.00	✓ 321.00
FRONT BUMPER SIDE RETAINER L/R <i>new</i>	2	20.60	✓ 41.20

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

HAMSTER CAR RENTAL PTE LTD
 8 BURN ROAD #15-13 TRIVER
 SINGAPORE 369977

Contact : 91750993

ESTIMATE

Repair Code : CLM16402

Date in : 31/08/2020

Vehicle Num. : SLF7505R

Model : HONDA VEZEL HYBRID 1.5X A

Chassis/Eng# : RU31210061/LEB5910071

FRONT BUMPER TOW HOOK COVER <i>Rehd</i>	1	17.10	✓	17.10
FRONT GRILLE <i>cruld</i>	1	351.80	✓	351.80
FRONT GRILLE 'LOGO' EMBLEM <i>nu</i>	1	23.40	✓	23.40
FRONT GRILLE CENTER BRACKET <i>cruld</i>	1	76.00	✓	76.00
FRONT GRILLE OUTER CHROME MOULDING <i>cruld</i>	1	98.00	✓	98.00
FRONT GRILLE OUTER COVER <i>cruld</i>	1	421.00	✓	421.00
FRONT GRILLE TOP GARNISH <i>cruld</i>	1	85.00	✓	85.00
FRONT HEADLAMP L/R <i>cruld</i>	2	1784.50	✓	3,569.00
FRONT HEADLAMP LOWER BRACKET L/R <i>cruld</i>	2	35.00	✓	70.00
FRONT HEADLAMP SIDE BRACKET L/R <i>cruld</i>	2	35.00	✓	70.00
FRONT HORN <i>Rehd</i>	1	110.50	✓	110.50
FRONT SUPPORT PANEL <i>Brkd</i>	1	576.20	✓	576.20
RADIATOR (AUTO) <i>Dented</i>	1	1376.60	✓	1,376.60 1,250.60
RADIATOR SIDE GUIDE L/R <i>Rehd</i>	2	31.60	✓	63.20
RAER TAILGATE 'HYBRID' EMBLEM <i>nu</i>	1	75.80	✓	75.80
RAER TAILGATE 'LOGO' EMBLEM <i>nu</i>	1	25.00	✓	25.00
RAER TAILGATE 'VEZEL' EMBLEM <i>nu</i>	1	56.20	✓	56.20
RAER TAILGATE HINGES L/R <i>Not nu</i>	2	50.00	✗	100.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

HAMSTER CAR RENTAL PTE LTD
8 BURN ROAD #15-13 TRIVER
SINGAPORE 369977

Contact : 91750993

ESTIMATE

Repair Code : CLM16402

Date in : 31/08/2020

Vehicle Num. : SLF7505R

Model : HONDA VEZEL HYBRID 1.5X A

Chassis/Eng# : RU31210061/LEB5910071

RAER TAILGATE INNER PULL GARNISH	<i>new Del'd</i>	1	27.50	<i>+</i>	27.50
RAER TAILGATE INNER RUBBER GUIDE STOPPER L/R	<i>new</i>	2	18.50	<i>+</i>	37.00
RAER TAILGATE INNER TRIM BOARD	<i>ould</i>	1	153.40	<i>✓</i>	153.40
RAER TAILGATE LOCK STRIKER	<i>new</i>	1	27.50	<i>+</i>	27.50
RAER TAILGATE MECHANISM LOCK	<i>Del'd</i>	1	180.00	<i>✓</i>	180.00
RAER TAILGATE OUTER GARNISH	<i>ould</i>	1	220.00	<i>✓</i>	220.00
RAER TAILGATE REFLECTOR INNER BLACK GASKET L/R	<i>new RH</i>	2	38.50	<i>38.50</i>	77.00
RAER TAILGATE REFLECTOR L/R	<i>RH ut</i>	2	413.20	<i>413.20</i>	826.40
RAER TAILGATE WEATHER STRIP	<i>ut</i>	1	96.80	<i>✓</i>	96.80
RAER TAILGATE WINDSCREEN MOULDING L/R	<i>new</i>	2	50.00	<i>✓</i>	100.00
RAER TAILGATE WINDSCREEN MOULDING T/L	<i>new</i>	2	50.00	<i>✓</i>	100.00
REAR BUMPER	<i>Del'd</i>	1	762.70	<i>✓</i>	762.70
REAR BUMPER REFLECTOR L/R	<i>RH ould</i>	2	141.10	<i>141.10</i>	282.20
REAR BUMPER SIDE COVER L/R	<i>RH Del'd</i>	2	195.00	<i>195</i>	390.00
REAR BUMPER SIDE RETAINER L/R	<i>new</i>	2	23.00	<i>✓</i>	46.00
REAR BUMPER UNDER COVER	<i>Del'd</i>	1	250.00	<i>✓</i>	250.00
REAR END PANEL	<i>Del'd</i>	1	415.60	<i>✓</i>	415.60
REAR END PANEL BUZZLE SENSOR	<i>xbw new</i>	1	85.20	<i>+</i>	85.20

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

HAMSTER CAR RENTAL PTE LTD
8 BURN ROAD #15-13 TRIVER
SINGAPORE 369977

Contact : 91750993

ESTIMATE

Repair Code : CLM16402

Date in : 31/08/2020

Vehicle Num. : SLF7505R

Model : HONDA VEZEL HYBRID 1.5X A

Chassis/Eng# : RU31210061/LEB5910071

REAR END PANEL INNER TOP GARNISH <i>Del'd</i>	1	98.00	✓	98.00
REAR EXHAUST CHROME TAIL PIPE <i>Best</i>	1	135.00	✓	135.00
REAR EXHAUST GASKET <i>new</i>	1	48.30	+	48.30
REAR EXHAUST RUBBER MOUNTING <i>3 new</i>	2	16.50	+	33.00
REAR EXHAUST SILENCER BOX	1	517.70	+	517.70
REAR FLOOR PANEL COMPARTMENT TRAY GARNISH <i>Del'd</i>	1	485.30	327	485.30
REAR FLOOR PANEL TOP BOARD COVER <i>Del'd</i>	1	430.30	306	430.30
REAR LH FENDER ARCH GARNISH <i>could</i>	1	195.00	✓	195.00
REAR LH FENDER INNER TRIM BOARD <i>could</i>	1	295.00	✓	295.00
REAR RH TAILLAMP <i>lit</i>	1	474.60	✓	474.60
REAR RH TAILLAMP INNER BLACK GASKET <i>new</i>	1	38.00	✓	38.00
REAR TAILGATE <i>Detent</i>	1	953.30	✓	953.30
TEMPERATURE SENSOR <i>could</i>	1	80.00	✓	80.00

Subtotal before discount

19,837.70

Percentage discount 20%

3,967.54

Sub-total 1

15,870.16

FRONT BONNET INSULATOR CLIPS - SET <i>new</i>	1	40.00	+	40.00
FRONT BUMPER CLIPS - SET <i>new</i>	1	80.00	30	80.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

HAMSTER CAR RENTAL PTE LTD
 8 BURN ROAD #15-13 TRIVER
 SINGAPORE 369977

Contact : 91750993

ESTIMATE

Repair Code : CLM16402

Date in : 31/08/2020

Vehicle Num. : SLF7505R

Model : HONDA VEZEL HYBRID 1.5X A

Chassis/Eng# : RU31210061/LEB5910071

FRONT GRILLE CLIPS - SET <i>nu</i>	1	40.00	<i>20</i> 40.00
FRONT GRILLE NUMBER PLATE <i>cust</i>	1	25.00	<i>✓</i> 25.00
FRONT GRILLE NUMBER PLATE HOLDER <i>Rehd</i>	1	50.00	<i>30</i> 50.00
RADIATOR COOLANT <i>nu</i>	1	80.00	<i>40</i> 80.00
RAER TAILGATE INNER TRIM BOARD CLIPS - SET <i>nu</i>	1	50.00	<i>30</i> 50.00
RAER TAILGATE NUMBER PLATE <i>3 new</i>	1	25.00	<i>+</i> 25.00
RAER TAILGATE NUMBER PLATE HOLDER	1	50.00	<i>+</i> 50.00
RAER TAILGATE OUTER GARNISH CLIPS - SET <i>nu</i>	1	40.00	<i>10</i> 40.00
RAER TAILGATE WINDSCREEN SEALANT <i>nu</i>	1	80.00	<i>60</i> 80.00
REAR BUMPER CLIPS - SET <i>nu</i>	1	80.00	<i>30</i> 80.00
REAR BUMPER REVERSE SENSOR - SET <i>Dangd</i>	1	300.00	<i>20</i> 300.00
REAR LH FENDER ARCH GARNISH CLIPS - SET <i>nu</i>	1	40.00	<i>20</i> 40.00
REAR LH FENDER INNER TRIM BOARD CLIPS - SET <i>nu</i>	1	40.00	<i>30</i> 40.00
REAR RH TAILLAMP CLIPS - SET <i>nu</i>	1	25.00	<i>10</i> 25.00
Subtotal before discount			1,045.00
Percentage discount 0%			0.00
Sub-total 2			1,045.00
Parts-total			16,915.16

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

HAMSTER CAR RENTAL PTE LTD
8 BURN ROAD #15-13 TRIVER
SINGAPORE 369977

Contact : 91750993

ESTIMATE

Repair Code : CLM16402

Date in : 31/08/2020

Vehicle Num. : SLF7505R

Model : HONDA VEZEL HYBRID 1.5X A

Chassis/Eng# : RU31210061/LEB5910071

LABOUR

- To remove, change air con parts, vacuums, refill air con gas.
- To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)
- To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.
- To remove, reinstall tailgate windscreen
- To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)
- To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.
- To re-spray painting on the front bonnet, front support panel, front fender (L/R) and front bumper.
- To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.
- To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.
- To apply anti-rust chemical on repaired and replaced panel.
- To remove, reinstall tailgate mechanism and check for function

120 140.00
30 80.00
80 100.00
120 150.00
80 140.00
700 1,100.00
700 1,100.00
80 100.00
1600 2,000.00
60 120.00
80.00

3650

Labour Total

5,110.00

Parts & Labour Total

22,025.16

*** This is a computer-generated document which requires no signature.***

page 6

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
4/s 01/09/20

12 Pays.

total: 17357.24

4/s: 138K ✓