

SIN YU SIN WORKSHOP

Reg No: 53253863C

1 Kaki Bukit Ave 6 #01-52 (Auto Bay @Kaki Bukit) Singapore 417883

Mobile no: (65) 91993103 / 97825292 Fax: (65) 68163103

Email : Sinyusin@hotmail.com

TPMSIG.

Vonne

31 August 2020

QUOTATION FOR ACCIDENT REPAIR OF SMH3527G HYUNDAI AVANTE

THIRD PARTY INSURER: MSIG INSURANCE

S/No.	Parts	Qty	Amount (\$)
1.	Rear bootlid <i>Dented</i>	1	\$ 1360.20 ✓
2.	Rear bootlid "Avante" emblem <i>3pc</i>	1	\$ 88.40 ✓
3.	Rear bootlid "Logo" emblem	1	\$ 75.80 ✓
4.	Rear bootlid "logo base" <i>2pc</i>	1	\$ 158.00 ✓
5.	Rear bootlid reflector lamp L/R <i>RH at</i>	2	280 \$ 520.00 <i>280</i>
6.	Rear bootlid reverse camera <i>2nd</i>	1	\$ 280.00 ✓
7.	Rear bootlid reverse camera cover <i>1pc</i>	1	\$ 108.30 ✓
8.	Rear bootlid mechanism lock <i>2nd</i>	1	\$ 189.20 ✓
9.	Rear bootlid lock striker <i>1pc</i>	1	\$ 55.00 ✓
10.	Rear bootlid weather strip <i>1pc</i>	1	\$ 220.80 ✓
11.	Rear bootlid hinge L/R <i>1pc</i>	2	154 \$ 308.00 ✓
12.	Rear bootlid inner trim <i>1pc</i>	1	\$ 206.40 ✓
13.	Rear bootlid lock antenna <i>2pc</i>	1	\$ 158.00 ✓
14.	Rear taillamp L/R <i>2nd</i>	2	435 \$ 870.00 ✓
15.	Rear taillamp panel L/R <i>1pc</i>	2	135 \$ 270.00 ✓
16.	Rear taillamp Stay Clip L/R <i>1pc</i>	4	8.50 \$ 34.00 ✓
17.	Rear bumper <i>Delam</i>	1	\$ 782.30 ✓
18.	Rear bumper diffuser <i>Delam</i>	1	\$ 459.40 ✓
19.	Rear bumper side reflector L/R <i>2nd</i>	2	201.50 \$ 403.00 ✓
20.	Rear bumper no plate lamp L/R <i>1pc</i>	2	62.50 \$ 125.00 ✓
21.	Rear bumper side retainer L/R <i>1pc</i>	2	54.00 \$ 98.00 ✓
22.	Rear bumper reinforcement beam <i>2nd</i>	1	\$ 298.80 ✓
23.	Rear bumper reinforcement beam bracket L/R <i>2nd</i>	2	158 \$ 316.00 ✓
24.	Rear bumper reinforcement support garnish <i>1pc</i>	1	\$ 90.00 ✓
25.	Rear end panel <i>Dented</i>	1	\$ 544.80 ✓
26.	Rear end panel garnish <i>Delam</i>	1	\$ 145.00 ✓
27.	Rear spare tyre panel top cover <i>Delam</i>	1	\$ 286.00 ✓
28.	Rear fender inner trim L/R <i>RH torn</i>	2	346 \$ 692.00 <i>346</i>
Subtotal before discount			\$ 9122.40
Discount 20%			\$ 1824.48
Subtotal 1			\$ 7297.92

7167.70

5734.16

SIN YU SIN WORKSHOP

Reg No: 53253863C

1 Kaki Bukit Ave 6 #01-52 (Auto Bay @Kaki Bukit) Singapore 417883

Mobile no: (65) 91993103 / 97825292 Fax: (65) 68163103

Email : Sinyusin@hotmail.com

31 August 2020

QUOTATION FOR ACCIDENT REPAIR OF SMH3527G HYUNDAI AVANTE THIRD PARTY INSURER: MSIG INSURANCE

<u>S/Nett.</u>	<u>Parts</u>	<u>Qty</u>	<u>Amount (\$)</u>
1.	Rear bumper clip <i>new</i>	1	\$ 30 ✓
2.	Rear fender inner trim clip L/R <i>new</i>	2	\$ 60 30
3.	Rear bootlid inner trim clip <i>new</i>	1	\$ 30 +
4.	Rear no plate <i>Bent</i>	1	\$ 25 ✓
5.	Rear no plate garnish <i>2 behind</i>	1	\$ 50 30
6.	Rear end panel sealant <i>new</i>	1	\$ 50 ✓
<i>165</i> Subtotal 2			\$ 245

Labour

To check wirings.	\$ 80 30
To transfer boot component parts to new boot	\$ 100 60
To remove & install side compartment trims, side garnish to facilitate repair	\$ 150 60
To remove, replace and reinstall rear reverse camera	\$ 100 50
To remove, replace and reinstall rear reverse sensor	<i>1850</i> \$ 80 50
To straighten, repair, realign on affected area and replace damaged parts	\$ 1000 800
To spray painting on affected area	\$ 1000 800
Total Labour Cost	\$ 2510

Total Cost Of Repairs (Total cost of parts + Total labour cost)

\$ 10,052.92

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
h/s 01/09/20
068mp

total: 7749.16
L/S: 621K.