

哈 汽 車 貿 易 服 務


HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: 2999/08/20

Your Ref: _____

Date: 7th SEP 2020

 The Claim's Manager
Motor Claims Dept.
INDIA INTERNATIONAL INSURANCE PTE. LTD.
64, Cecil Street, #05-00, IOB Bldg.
Singapore 049711

Name Of Insured : Mr Ng Seng Hiong
Date Of Accident : 27/08/2020 (20:30hrs)
Policy Number : D20MPC0000347

Cost of repair to NISSAN NOTE 1.2 (A) CVT H/B - SMH 3909 M

1 pc front bumper		\$	394.30	Nett
16 pcs front bumper top & low clips	© \$ 4.50 N		72.00	"
1 pc front bumper n/s airscoop grille			71.50	"
1 pc front bumper n/s side retainer			25.70	"
1 pc front bumper reinforcement			381.60	"
1 pc front bumper sponge damper			218.60	"
1 pc front grille			276.70	"
1 pc n/s head lamp assy			1,614.60	"
1 pc front n/s fender inner shield			100.50	"
8 pcs front n/s fender inner shield clips	© \$ 4.50 N		36.00	"
1 pc front n/s fender bracket			35.00	"
1 pc front centre lower engine duct cover			387.40	"
10 pcs front lower engine duct cover clips	© \$ 4.50 N		45.00	"

\$ 3,658.90 Nett

Less 10% \$ 365.89

\$ 3,293.01

To wiring check up for affected wiring system. 20.00

To check & adjust front wheel alignment & balancing. 60.00

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out front support panel, front n/s fender & necessary parts, to weld, renew & align above parts. 550.00

To putty & respray painting on all affected accident parts. 900.00

\$ 4,823.01

Less Excess \$ 600.00

\$ 4,223.01
=====

HUP MOTOR TRADING & SERVICE

Dollars : Four Thousand Two Hundred Twenty Three And Cents One Only.

Encl : Discharge Voucher & Authorisation Letter signed by Insured.