

**MODERN AUTOMOTIVE PTE LTD**  
**BLK 3023A UBI ROAD 1 # 01-61**  
**SINGAPORE 408717**

Tel : 6748 4422 / 6745 4422 Fax : 6747- 6720 REG NO 200501702H

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

**Quotation**  
 Date: 01.08.2020  
 Acknowledged by Repairer: [Signature]  
 Signature: SJF936A  
 Date: Toyota Altis

**MSIG INSURANCE (S) PTE LTD**  
 4 Shenton Way # 21 - 01  
 SGX Centre 2  
 Singapore 068807  
 Hot line : 6827 - 7660  
 Fax : 6225- 7402 ( CLAIM )

XiaoChen

DATE : 01.08.2020  
 VEH NO : SJF936A  
 MODEL : Toyota Altis  
 D O A : 23.08.2020  
 YR REF : SJW24S

Attn : Motor Claim Dept (pls arrange vehicle survey & check liability)

**RE : ESTIMATE FOR ACCIDENT REPAIR SJF936A (TOYOTA ALTIS)**

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
<b>NO</b>	<b>LIST ITEMS</b>		
1	Rear Bumper <i>Distorted</i>	1	476.10 ✓
2	Rear Bumper Clips <i>new</i>	1 set	30.00 ✓
3	Rear Bumper Side Holder - LH & RH <i>RH painted</i>	2	76.00 38
4	Rear Bumper Reflector - LH & RH <i>RH cracked</i>	2	69.20 34.60
5	Rear Bumper Sponge <i>Missing</i>	1	129.00 ✓
6	Rear Bumper Impact Bracket - RH <i>Dented</i>	1	85.60 ✓
7	Rear End Panel <i>Distorted</i>	1	532.80 ✓
8	Rear End Panel Top Garnish <i>Deformed</i>	1	192.70 ✓
9	Tail Lamp - RH <i>cracked</i>	1	342.00 ✓
10	Tail Lamp Lower Bracket - RH <i>cracked</i>	1	55.00 ✓
11	Tail Lamp Panel - RH <i>Distorted</i>	1	195.40 ✓
12	Bootlid <i>Dented</i>	1	680.40 ✓
13	Bootlid Lock <i>new</i>	1	121.50 ✗
14	Bootlid Weatherstripe <i>cut</i>	1	195.50 ✓
15	Bootlid Lamp - RH <i>cracked</i>	1	223.00 ✓
16	Toyota Logo	1	52.00 ✓
17	1.6 emblem	1	46.00 ✓
18	Corolla Emblem <i>new</i>	1	48.00 ✓
19	Altis Emblem	1	49.00 ✓
20	Rear Fender - RH <i>Distorted</i>	1	927.50 ✓
21	Rear Fender Air Vent - RH <i>cracked</i>	1	115.40 ✓
22	Rear Fender Inner Panel - RH <i>Reps</i>	1	371.90 ✗
23	Rear Fender Inner Trim - RH <i>cracked</i>	1	334.20 ✓
24	Rear Fender Inner Trim Clip - RH <i>new</i>	1	30.00 ✓
25	Rear Fender Inner Shield - RH <i>new</i>	1	48.50 ✗
26	Rear Fender Inner Shield Clip - RH <i>new</i>	1	10.00 ✗
27	Rear Windscreen Moulding <i>new</i>	1	96.30 ✓
28	Rear Door - RH <i>Reps</i>	1	891.10 ✗
29	Rear Door Lock - RH <i>new</i>	1	473.90 ✗

**RE : ESTIMATE FOR ACCIDENT REPAIR SJF936A (TOYOTA ALTIS)**

30	Spare Tyre Panel Top Board <i>torn</i>	1	359.20 ✓
31	Rear Exhaust Pipe <i>Rep</i>	1	792.10 X
32	Rear Exhaust Mounting <i>NEW</i>	1	42.00 X
			<hr/>
			\$ 8,091.30
	<i>5267.70</i>	Less 25%	<i>(2,022.83)</i>
	<i>3950.77</i>		<hr/>
			\$ 6,068.48

**S/NET ITEMS**

1	Reverse Sensor <i>Dayd</i>	1	\$ <del>280.00</del> <i>200</i>
2	Rear End Panel Sealant <i>320</i>	1	\$ 60.00 ✓
3	Rear Windscreen Sealant <i>NEW</i>	1	\$ 60.00 ✓
			<hr/>
			\$ 400.00
	<b>Total parts</b>		<hr/>
			\$ <b>6,468.48</b>

**LABOUR CHARGE**

1	To knocking & pull out rear portion & renew above parts	\$ <del>1,800.00</del> <i>1300</i>
2	To putty and spray up paint works	\$ <del>1,600.00</del> <i>1100</i>
3	To check wiring system	\$ <del>50.00</del> <i>30</i>
4	To underseal	\$ <del>150.00</del> <i>80</i>
5	To remove reverse sensor	\$ <del>100.00</del> <i>50</i>
6	To remove upholstery	\$ <del>150.00</del> <i>60</i>
7	To remove fuel tank <i>2820</i>	\$ <del>150.00</del> <i>80</i>
8	To remove rear windscreen	\$ <del>180.00</del> <i>120</i>
9	To transfer door fittings	\$ 150.00 X
		<hr/>
		\$ 4,330.00

**GRAND TOTAL** \$ 10,798.48

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE

*total: 7090.77*  
*L/s: 5650*  
*09 Days.*