



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934

HP: 98888885

Estimation

Date:

28/8/2020

Vehicle:

SMF1796U

Make / Model:

TOYOTA PRIUS

Chassis No:

No.	Description	Unit	Unit Price	Amount
	Parts Replacement:			
1	FRONT BUMPER / <i>CHT</i>	1	\$ 570.00	\$ 570.00
2	FRONT BUMPER LOGO / <i>APC</i>	1	\$ 189.00	\$ 189.00
3	FRONT BUMPER FOGLAMP LH X	1	\$ 435.00	\$ 435.00
4	FRONT BUMPER SIDE LAMP LH / <i>CHT</i>	1	\$ 212.00	\$ 212.00
5	FRONT BUMPER TOP BEAM X	1	\$ 415.00	\$ 415.00
6	FRONT BUMPER LOWER ABSORBER X	1	\$ 235.00	\$ 235.00
7	FRONT BUMPER LOWER GRILLE X	1	\$ 186.00	\$ 186.00
8	FRONT BUMPER UNDER GARNISH X	1	\$ 298.00	\$ 298.00
9	FRONT BUMPER SIDE RETAINER / <i>DR</i>	2	\$ 58.00	\$ 118.00
10	FRONT BUMPER REINFORCEMENT X	1	\$ 459.00	\$ 459.00
11	FRONT BUMPER TOWING COVER X	1	\$ 68.00	\$ 68.00
12	FRONT BUMPER SPONGE X	1	\$ 119.00	\$ 119.00
13	FRONT BUMPER LOWER X		\$ 415.00	\$ 415.00
14	FRONT FENDER LH 2 <i>R</i> - <i>BT</i>	1	\$ 985.00	\$ 985.00
15	FRONT FENDER EMBLEM 'HYBRID' / <i>APC</i>	1	\$ 65.00	\$ 65.00
16	FRONT FENDER INNER COWLING LH X	1	\$ 135.00	\$ 135.00
17	FRONT FENDER GARNISH LH X	1	\$ 64.00	\$ 64.00
18	HEADLAMP LH / <i>CHT</i>	1	\$ 1,487.00	\$ 1,487.00
19	FRONT SUPPORT TOP GARNISH X	1	\$ 289.00	\$ 289.00
20	AIR GUARD LH X	1	\$ 71.00	\$ 71.00
21	FRONT KNUCKLE ARM LH X	1	\$ 821.00	\$ 821.00
22	FRONT KNUCKLE ARM BEARING LH X	1	\$ 165.00	\$ 165.00
23	FRONT SHOCK ABSORBER LH X	1	\$ 651.00	\$ 651.00
24	FRONT LOWER ARM LH X	1	\$ 628.00	\$ 628.00
25	STABILIZER LINK LH X	1	\$ 198.00	\$ 198.00
26	STEERING TIE ROD LH X	1	\$ 211.40	\$ 211.40
				\$ 9,489.40
			Less 25%	\$ 2,372.35
			Total	\$ 7,117.05
	S/Nett items:			
1	FRONT GRILLE CLIPS X	1 SET	\$ 50.00	\$ 50.00
2	<i>front</i> BEAR BUMPER CLIP /	1 SET	\$ 80.00	\$ 80.00
3	FRONT SPORTS RIM LH 2 (<i>cop only</i>) <i>cut</i>	1	\$ 800.00	\$ 800.00
4	FRONT TYRE LH X	1	\$ 250.00	\$ 250.00
5	FRONT FENDER SEALANT LH X	1	\$ 150.00	\$ 150.00
6	BRAKE FLUID X	1	\$ 30.00	\$ 30.00
				\$ 1,360.00
	Labour to:			

30

1	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 800.00	\$ 800.00	400
2	PANEL BEATING ON AFFECTED AREAS	1	\$ 800.00	\$ 800.00	250
3	TO CHECK ELECTRICAL WIRING	1	\$ 80.00	\$ 80.00	30
4	REMOVE AND REFIX FRONT UNDERCARRIAGE	1	\$ 450.00	\$ 450.00	X
5	REALIGN HEADLAMP	1	\$ 120.00	\$ 120.00	30
6	CHECK AND TEST FOR WATER LEAKAGE	1	\$ 50.00	\$ 50.00	X
7	CHECK AND RESET FAULT CODE LIGHT ON	1	\$ 250.00	\$ 250.00	X
8	CONDUCT WHEEL ALIGNMENT	1	\$ 120.00	\$ 120.00	60
9	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 120.00	\$ 120.00	30
				\$ 2,790.00	
			Parts Replacement Amount	\$ 8,477.05	
			Total Amount for Labour	\$ 2,790.00	
			Total Amount	\$ 11,267.05	

Steve (LKK) incl April
1/9/70, 1.00pm
3 days
L/S
Ry AL SM

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: