



HP: 98888885

Chassis No:

72 ✓
 X
 /
 X
 X
 X
 X
 /
 X
 X
 X
 X
 X
 731.35 ✓
 /
 X
 X
 /
 X
 X
 X
 X
 X
 X
 X
 X
 3255.35
 - 75%
 2441.51
 X
 30 ✓
 130 ✓
 X
 X
 X
 160

1	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 800.00	\$ 800.00
2	PANEL BEATING ON AFFECTED AREAS	1	\$ 800.00	\$ 800.00
3	TO CHECK ELECTRICAL WIRING	1	\$ 80.00	\$ 80.00
4	REMOVE AND REFIX FRONT UNDERCARRIAGE	1	\$ 450.00	\$ 450.00
5	REALIGN HEADLAMP	1	\$ 120.00	\$ 120.00
6	CHECK AND TEST FOR WATER LEAKAGE	1	\$ 50.00	\$ 50.00
7	CHECK AND RESET FAULT CODE LIGHT ON	1	\$ 250.00	\$ 250.00
8	CONDUCT WHEEL ALIGNMENT	1	\$ 120.00	\$ 120.00
9	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 120.00	\$ 120.00
				\$ 2,790.00
			Parts Replacement Amount	\$ 8,477.05
			Total Amount for Labour	\$ 2,790.00
			Total Amount	\$ 11,267.05

400
250
30
X
30
X
60
30

800

Steve (LKK) incl April
1/9/70, 1.00pm
3 days
L/S
Ry AL sky

P-2441-51
A/- 160
L- 800
3401-51
L/S - 2721-20
= 2700

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: