

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: [Nora.khai@premiumauto.com.sg](mailto:Nora.khai@premiumauto.com.sg) / [claims@premiumauto.com.sg](mailto:claims@premiumauto.com.sg)

**WIP : 47135**

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/TP/0609/2020/NS  
**Date** : 28-Aug-20

**Vehicle NOT IN workshop. Please arrange for survey.**

**Your insured veh no : GBJ 9739 S**

### **AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way  
#07-16 AIG Building  
Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Mr Teng jun Yong  
**Address** : Blk 818 Woodlands St 82  
#12-413  
Singapore 730818  
**Telephone** : (HP) +65 91064652  
**Type of Claim** : Third Party Claims  
**Policy No.** : 5117200026  
**Vehicle No** : **SLN 1578 C**  
**Model Code** : Volkswagen Scirocco  
**Model / Year** : 25/5/2017  
**Engine No** : CMS 044465  
**Chassis No** : WVVZZZ13ZHV004871  
**Mileage** : -  
**Date In** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 26-Aug-20  
**Place of Accident** : Yishun Ave 6

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

## Estimated Labour Charges for Accident Vehicle. SLN 1578 C

<u>S/n</u>	<u>Nature of Jobs</u>	<u>Estimated Charges</u>	<u>Surveyor's Recommendations</u>
1	To remove and transfer rhs front door's multi-lock system and power window devices. Inspect for damages.	S/N \$ 280.00	
2	To dismantle and renew rhs front door. Re-organise crash management components. Reinstall all parts removed.	\$ 1,050.00	
3	To respray rhs front door, door handle and rhs rear fender.	\$ 2,300.00	
4	To carry out diagnostic check.	S/N \$ 192.00	
<b>TOTAL LABOUR CHARGES</b>		<b>: <u>\$ 3,822.00</u></b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SLN 1578 C

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT DOOR - RH	\$ 2,674.00	
2	OUTER A-PILLAR DOOR SEAL - RH	\$ 114.00	
3	OUTER DOOR SEAL	\$ 62.00	
4	SOUND ABSORBER	\$ 31.00	
5	MOUNTING BAR - RH	\$ 239.00	
6	EXTERIOR DOOR HANDLE - RH	\$ 337.00	
7	DOOR HANDLE CAP - RH	\$ 35.00	
8	FRONT DOOR COVER - RH	\$ 163.00	
9	REAR PROTECTIVE STRIP - RH	\$ 149.00	
10	SUNDRIES	\$ 200.00	
	<b>TOTAL SPARE PARTS</b>	<b>: \$ 4,004.00</b>	
	<b>TOTAL LABOUR CHARGES</b>	<b>: \$ 3,822.00</b>	
	<b>GRAND TOTAL</b>	<b>: \$ 7,826.00</b>	

All charges are not inclusive of GST.  
Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

**Name** :  
**Surveyed Date** :  
**Authorised Date** :  
**Excess Cost** :  
**Liability** :  
**Remarks** :

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant