

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premlumauto.com.sg / claims@premlumauto.com.sg

WIP : 47135

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0609/2020/NS
Date : 28-Aug-20

Jaslin.

\$4680.32 .

Vehicle NOT IN workshop. Please arrange for survey.

Your insured veh no : GBJ 9739 S

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Teng jun Yong
Address : Blk 818 Woodlands St 82
#12-413
Singapore 730818
Telephone : (HP) +65 91064652
Type of Claim : Third Party Claims
Policy No. : 5117200026
Vehicle No : **SLN 1578 C**
Model Code : Volkswagen Scirocco
Model / Year : 25/5/2017
Engine No : CMS 044465
Chassis No : WVVZZZ13ZHV004871
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 26-Aug-20
Place of Accident : Yishun Ave 6

Premium Automobiles

55 (Bukit Merah), Singapore 400050
Tel: (65) 2373 1181 Fax: (65) 2373 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLN 1578 C

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rhs front door's multi-lock system and power window devices. Inspect for damages.	S/N \$ 280.00 ✓	
2	To dismantle and renew rhs front door. Re-organise crash management components. Reinstall all parts removed.	\$ 1,050.00 ✓ 500	
3	To respray rhs front door, door handle and rhs rear fender. ✓	\$ 2,300.00 ✓ 1000	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: <u>\$ 3,822.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 1578 C

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT DOOR - RH <i>Dented</i>	\$ 2,674.00	✓ 2139.20
2	OUTER A-PILLAR DOOR SEAL - RH <i>new</i>	\$ 114.00	* ✓
3	OUTER DOOR SEAL <i>new</i>	\$ 62.00	✓ 49.92
4	SOUND ABSORBER <i>Not new</i>	\$ 31.00	* ✓
5	MOUNTING BAR - RH <i>new</i>	\$ 239.00	* ✓
6	EXTERIOR DOOR HANDLE - RH <i>new</i>	\$ 337.00	✓ 269.60
7	DOOR HANDLE CAP - RH <i>new</i>	\$ 35.00	* ✓
8	FRONT DOOR COVER - RH <i>new</i>	\$ 163.00	✓ 130.40
9	REAR PROTECTIVE STRIP - RH <i>new</i>	\$ 149.00	✓ 119.20
10	SUNDRIES <i>Not new</i>	\$ 200.00	* ✓
TOTAL SPARE PARTS		: \$ 4,004.00	
TOTAL LABOUR CHARGES		: \$ 3,822.00	
GRAND TOTAL		: \$ 7,826.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Net.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Name : *Adgany Lj*
Surveyed Date : *28/08/10*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorised, OAPays*
sls

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at Tel.6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

KIV