

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
 3 Anson Road #16-00
 Springleaf Tower
 Singapore 079909
 Tel : 6389 - 6111
 Fax : 6224 - 7478 / 7175

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modifications is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Quotation

DATE: : 07.09.2020
 VEH NO : SKF2599P
 MODEL : BMW 335i
 D O A : 29.08.2020
 YR REF : XE4320P

Phanchuan

Attn : Motor Claim Dept

(Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SKF2599P (BMW 335i)

Item	Description	Qty	Amt
NO	LIST ITEMS		
1	Front Bumper Side Holder - LH & RH <i>new</i>	2	250.00 ✓
2	Front Bumper Towing Cover <i>cracked</i>	1	38.00 ✓
3	Front Bumper Fog Lamp - RH <i>3 new</i>	1	338.00 x
4	Front Bumper Fog Lamp Cover - RH	1	105.00 x
5	Front Bumper Reinforcement <i>new</i>	1	755.00 x
6	Front Bumper Sponge <i>cracked</i>	1	148.00 ✓
7	Front Bumper Logo <i>new</i>	1	85.00 ✓
8	Front Grille <i>RH cut</i>	2	220.00 110
9	Front Grille Inner Frame <i>cracked</i>	1	388.00 ✓
10	Air Con Condenser Side Guide - RH <i>del</i>	1	95.00 ✓
11	Inter Cooler Outer Cover <i>del</i>	1	185.00 ✓
12	Head Lamp - RH <i>cracked</i>	1	2,695.00 ✓
13	Rear Bumper Side Holder - LH & RH <i>RH cracked</i>	2	310.00 155
14	Rear Bumper Tower Cover <i>new</i>	1	35.00 x
15	Rear Bumper Reinforcement <i>Best</i>	1	715.00 ✓
16	Rear Bumper Centre Guide <i>cracked</i>	1	195.00 ✓
17	Rear Bumper Reinforcement Cover <i>new</i>	1	89.00 x
18	Tail Lamp - RH <i>cracked</i>	1	395.00 ✓
19	Tail Lamp Panel - RH <i>del</i>	1	215.00 ✓
20	Tail Lamp Side Cover - RH <i>cut</i>	1	49.00 ✓
21	Bootlid <i>del</i>	1	1,655.00 ✓
22	Bootlid Lock <i>new</i>	1	390.00 x
23	Bootlid Weatherstripe <i>cut</i>	1	195.00 ✓
24	Bootlid Lamp - RH <i>cracked</i>	1	285.00 ✓
25	BMW Logo <i>new</i>	1	75.00 ✓
26	335i Emblem	1	85.00 ✓
27	Rear Fender - RH <i>Rep</i>	1	1,695.00 x
28	Rear Windscreen C/w Moulding <i>new</i>	1	1,580.00 x

RE : **ESTIMATE FOR ACCIDENT REPAIR SKF2599P (BMW 335i)**

29	Rear Exhaust Pipe	2 new	1	1,358.00	X
30	Rear Exhaust Mounting	new	1	40.00	X
				\$	14,663.00
8013					173315
7612.35				\$	13929.85

S/NETT ITEMS

1	Front Number Plate	Dented	1	30.00	/
2	Front Number Plate Holder	Del-d	1	30.00	/
3	Front Bumper (M3 Version)	Crashd	1	2,400.00	1800.
4	Front Bumper Clips	new	1 set	50.00	30
5	Rear Bumper (M3 Version)	Del-d	1	2,300.00	1800
5	Rear Bumper Clips	new	1 set	50.00	30
6	Rear Bumper Side Reflector - RH	2 new	1	80.00	X
7	Rear Windscreen Sealant		1	60.00	X
				\$	5,000.00

Total parts

\$ 18,196.70

LABOUR CHARGE

1	To knocking out front & rear portion & renew above parts	\$	1,600.00	1000
2	To putty & spray up paint works	\$	1,400.00	1250
3	To check wiring system	\$	100.00	60
4	To underseal	\$	150.00	40
5	To remove upholstery	\$	150.00	50
6	To remove rear windscreen	\$	180.00	X
7	To remove exhaust pipe	\$	150.00	X
8	To transfer bootlid fittings	\$	150.00	80
9	To remove fuel tank	\$	150.00	X
10	To perform dianogstic test	\$	150.00	100
11	To remove rear camera	\$	100.00	50
Total Labour			\$	4,280.00

Grand Total

\$ 23209.85

GST Will be reflected in the final bills

total 13962.35
H/S: 11150
08 Days